Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN								
Primary Objective of Design	Compare a site mean to a fixed threshold							
Type of Sampling Design	Parametric							
Sample Placement (Location) in the Field	Simple random sampling							
Working (Null) Hypothesis	The mean value at the site exceeds the threshold							
Formula for calculating number of sampling locations	Student's t-test							
Calculated total number of samples	11							
Number of samples on map ^a	41							
Number of selected sample areas b	2							
Specified sampling area ^c	188054.34 m ²							
Total cost of sampling d	\$6,500.00							

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1										
X Coord	Y Coord	Label	Value	Туре	Historical					
679268.7700	3083200.3260	J-11S	1110	Manual	Т					
679301.1600	3083254.0340	J-12S	748	Manual	Т					
679171.2970	3083289.7960	J-04S	747	Manual	Т					
679155.0740	3083294.6960	J-03S	2250	Manual	Т					
679133.4290	3083306.3130	J-01S	1200	Manual	Т					
679104.2450	3083223.2620	J-02S	7690	Manual	Т					
679164.8060	3083214.7100	J-06S	6880	Manual	Т					
679181.2750	3083178.2880	J-08S	10900	Manual	Т					
679213.7730	3083224.9730	J-09S	858	Manual	Т					
679280.5440	3083305.6810	J-10S	1090	Manual	Т					
679242.7260	3083326.5280	J-07S	11400	Manual	Т					
679225.8560	3083359.9740	J-05S	959	Manual	Т					

Area: Area 3										
X Coord	Y Coord	Label	Value	Туре	Historical					
679261.0980	3083016.3510	J-15S	5880	Manual	Т					
679335.0020	3082941.1720	J-21S	648	Manual	Т					
679343.5810	3082969.5980	J-19S	1760	Manual	Т					
679394.8070	3082971.8300	J-24S	790	Manual	Т					
679382.8640	3083009.1130	J-20S	915	Manual	Т					
679293.5600	3082950.4980	J-17S	1130	Manual	Т					
679360.5700	3083026.4980	J-18S	3510	Manual	Т					

3082840.6970	J-23S	4180	Manual T
3082781.0290	J-22S	1960	Manual T
3082840.1720	J-16S	3640	Manual T
3083075.4290	J-14S	917	Manual T
3082933.0980	J-13S	5140	Manual T
3082652.6750	J-28S	9150	Manual T
3082683.1400	J-26S	2800	Manual T
3082549.7640	J-25S	13800	Manual T
3082537.3510	J-27S	4660	Manual T
3082605.3190	J-35S	2140	Manual T
3082548.6880	J-34S	1830	Manual T
3082667.5270	J-36S	7640	Manual T
3082711.0960	J-29S	3630	Manual T
3082791.3300	J-30S	1770	Manual T
3082914.1150	J-32S	2460	Manual T
3082845.8460	J-31S	1390	Manual T
3082897.2580	J-41S	2480	Manual T
3082940.9730	J-33S	1240	Manual T
3082886.8990	J-40S	1495	Manual T
3082840.3960	J-39S	1160	Manual T
3082776.7350	J-38S	3310	Manual T
3082731.6820	J-37S	8450	Manual T
	3082781.0290 3082840.1720 3083075.4290 3082933.0980 3082652.6750 3082652.6750 3082549.7640 3082537.3510 3082548.6880 3082548.6880 3082667.5270 3082711.0960 3082791.3300 3082914.1150 3082845.8460 3082897.2580 3082940.9730 3082846.8990 3082840.3960 3082776.7350	3082781.0290 J-22S 3082840.1720 J-16S 3083075.4290 J-14S 3082933.0980 J-13S 3082652.6750 J-28S 3082683.1400 J-26S 3082549.7640 J-25S 3082537.3510 J-27S 3082605.3190 J-35S 3082548.6880 J-34S 308267.5270 J-36S 3082711.0960 J-29S 3082791.3300 J-30S 3082914.1150 J-32S 3082845.8460 J-31S 3082845.8460 J-31S 3082840.9730 J-33S 3082840.9730 J-40S 3082886.8990 J-40S 30828776.7350 J-38S	3082781.0290 J-22S 1960 3082840.1720 J-16S 3640 3083075.4290 J-14S 917 3082933.0980 J-13S 5140 3082652.6750 J-28S 9150 3082683.1400 J-26S 2800 3082549.7640 J-25S 13800 3082537.3510 J-27S 4660 3082605.3190 J-35S 2140 3082548.6880 J-34S 1830 3082711.0960 J-29S 3630 3082791.3300 J-30S 1770 3082914.1150 J-32S 2460 3082845.8460 J-31S 1390 3082845.8460 J-31S 1390 3082840.9730 J-33S 1240 3082840.3960 J-39S 1160 3082776.7350 J-38S 3310

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyta	_	Parameter						
Analyte	"	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b	
Aluminium	11	3362 mg/kg	3261 mg/kg	0.05	0.1	1.64485	1.28155	


 $^{\text{a}}$ This value is automatically calculated by VSP based upon the user defined value of α

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples									
AL GE	n-1	α	=5	α=	10	α=15			
AL=652	2 I	s=6724	s=3362	s=6724	s=3362	s=6724	s=3362		
	β=5	1152	290	912	229	765	192		
LBGR=90	β=10	912	229	700	176	572	144		
	β=15	766	193	573	144	458	115		
	β=5	290	74	229	58	192	49		
LBGR=80	β=10	229	59	176	45	144	37		
	β=15	193	50	144	37	115	30		
LBGR=70	β=5	130	34	102	27	86	22		

β=10	103	27	79	21	65	17
β=15	87	23	65	17	52	14

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$6,500.00, which averages out to a per sample cost of \$590.91. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	11 Samples						
Field collection costs		\$100.00	\$1,100.00						
Analytical costs	\$400.00	\$400.00	\$4,400.00						
Sum of Field & Analytical costs		\$500.00	\$5,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$6,500.00						

Data Analysis for Aluminium

The following data points were entered by the user for analysis.

	Aluminium (mg/kg)									
Rank	k 1 2 3 4 5 6 7 8 9 10									10
0	648	747	748	790	858	915	917	959	1090	1110
10	1130	1160	1200	1240	1390	1495	1760	1770	1830	1960
20	2140	2250	2460	2480	2800	3310	3510	3630	3640	4180
30	4660	5140	5880	6880	7640	7690	8450	9150	1.09e+004	1.14e+004
40	1.38e+004									

SUMMARY STATISTICS for Aluminium							
n	41						
Min	648						
Max	13800						
Range	13152						
Mean	3553.8						
Median	2140						
Variance	1.1301e+007						
StdDev	3361.7						
Std Error	525						
Skewness	1.4858						

Inte	erquar	nge	3780					
Percentiles								
1%	5%	10%	25%	50% 75% 90% 95% 99%				
648	747.1	803.6	1120	2140	4900	9010	1.135e+004	1.38e+004

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Aluminium									
k	Test Statistic R _k 5% Critical Value C _k Significant?								
1	3.048	3.05	No						

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Shapiro-Wilk Test Statistic	0.8					
Shapiro-Wilk 5% Critical Value	0.94					

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Aluminium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the

distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/guality/ga-docs.html).

Tests for Aluminium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic 0.7943					
Shapiro-Wilk 5% Critical Value	0.941				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	4438
95% Non-Parametric (Chebyshev) UCL	5842

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (5842) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data, AL is the action level or threshold (6521),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
-5.6517	1.6839	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+) 95% Critical Value Null Hypothesis							
33	26	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

 * - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN						
Primary Objective of Design	Compare a site mean to a fixed threshold					
Type of Sampling Design	Parametric					
Sample Placement (Location) in the Field	Simple random sampling					
Working (Null) Hypothesis	The mean value at the site exceeds the threshold					
Formula for calculating number of sampling locations	Student's t-test					
Calculated total number of samples	13					
Number of samples on map ^a	41					
Number of selected sample areas b	2					
Specified sampling area ^c	188054.34 m ²					
Total cost of sampling d	\$7,500.00					

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical				
679268.7700	3083200.3260	J-11S	1110	Manual	Т				
679301.1600	3083254.0340	J-12S	748	Manual	Т				
679171.2970	3083289.7960	J-04S	747	Manual	Т				
679155.0740	3083294.6960	J-03S	2250	Manual	Т				
679133.4290	3083306.3130	J-01S	1200	Manual	Т				
679104.2450	3083223.2620	J-02S	7690	Manual	Т				
679164.8060	3083214.7100	J-06S	6880	Manual	Т				
679181.2750	3083178.2880	J-08S	10900	Manual	Т				
679213.7730	3083224.9730	J-09S	858	Manual	Т				
679280.5440	3083305.6810	J-10S	1090	Manual	Т				
679242.7260	3083326.5280	J-07S	11400	Manual	Т				
679225.8560	3083359.9740	J-05S	959	Manual	Т				

Area: Area 3										
X Coord Y Coord Label Value Type Histor										
679261.0980	3083016.3510	J-15S	5880	Manual	Т					
679335.0020	3082941.1720	J-21S	648	Manual	Т					
679343.5810	3082969.5980	J-19S	1760	Manual	Т					
679394.8070	3082971.8300	J-24S	790	Manual	Т					
679382.8640	3083009.1130	J-20S	915	Manual	Т					
679293.5600	3082950.4980	J-17S	1130	Manual	Т					
679360.5700	3083026.4980	J-18S	3510	Manual	Т					

3082840.6970	J-23S	4180	Manual T
3082781.0290	J-22S	1960	Manual T
3082840.1720	J-16S	3640	Manual T
3083075.4290	J-14S	917	Manual T
3082933.0980	J-13S	5140	Manual T
3082652.6750	J-28S	9150	Manual T
3082683.1400	J-26S	2800	Manual T
3082549.7640	J-25S	13800	Manual T
3082537.3510	J-27S	4660	Manual T
3082605.3190	J-35S	2140	Manual T
3082548.6880	J-34S	1830	Manual T
3082667.5270	J-36S	7640	Manual T
3082711.0960	J-29S	3630	Manual T
3082791.3300	J-30S	1770	Manual T
3082914.1150	J-32S	2460	Manual T
3082845.8460	J-31S	1390	Manual T
3082897.2580	J-41S	2480	Manual T
3082940.9730	J-33S	1240	Manual T
3082886.8990	J-40S	1495	Manual T
3082840.3960	J-39S	1160	Manual T
3082776.7350	J-38S	3310	Manual T
3082731.6820	J-37S	8450	Manual T
	3082781.0290 3082840.1720 3083075.4290 3082933.0980 3082652.6750 3082652.6750 3082549.7640 3082537.3510 3082548.6880 3082548.6880 3082667.5270 3082711.0960 3082791.3300 3082914.1150 3082845.8460 3082897.2580 3082940.9730 3082846.8990 3082840.3960 3082776.7350	3082781.0290 J-22S 3082840.1720 J-16S 3083075.4290 J-14S 3082933.0980 J-13S 3082652.6750 J-28S 3082683.1400 J-26S 3082549.7640 J-25S 3082537.3510 J-27S 3082605.3190 J-35S 3082548.6880 J-34S 308267.5270 J-36S 3082711.0960 J-29S 3082791.3300 J-30S 3082914.1150 J-32S 3082845.8460 J-31S 3082845.8460 J-31S 3082840.9730 J-33S 3082840.9730 J-40S 3082886.8990 J-40S 30828776.7350 J-38S	3082781.0290 J-22S 1960 3082840.1720 J-16S 3640 3083075.4290 J-14S 917 3082933.0980 J-13S 5140 3082652.6750 J-28S 9150 3082683.1400 J-26S 2800 3082549.7640 J-25S 13800 3082537.3510 J-27S 4660 3082605.3190 J-35S 2140 3082548.6880 J-34S 1830 3082711.0960 J-29S 3630 3082791.3300 J-30S 1770 3082914.1150 J-32S 2460 3082845.8460 J-31S 1390 3082845.8460 J-31S 1390 3082840.9730 J-33S 1240 3082840.3960 J-39S 1160 3082776.7350 J-38S 3310

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

S

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_		Para	amete	er		
Analyte	"	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
Aluminium	13	3362 mg/kg	2967 mg/kg	0.05	0.1	1.64485	1.28155


 $^{\rm a}$ This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples									
AL GE	n-1	α=5 α			10	α=15			
AL=652	4 I	s=6724	s=3362	s=6724 s=3362		s=6724	s=3362		
	β=5	1152	290	912	229	765	192		
LBGR=90	β=10	912	229	700	176	572	144		
	β=15	766	193	573	144	458	115		
	β=5	290	74	229	58	192	49		
LBGR=80	β=10	229	59	176	45	144	37		
	β=15	193	50	144	37	115	30		
LBGR=70	β=5	130	34	102	27	86	22		

β=10	103	27	79	21	65	17
β=15	87	23	65	17	52	14

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$7,500.00, which averages out to a per sample cost of \$576.92. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION							
Cost Details	Per Analysis	Per Sample	13 Samples				
Field collection costs		\$100.00	\$1,300.00				
Analytical costs	\$400.00	\$400.00	\$5,200.00				
Sum of Field & Analytical costs		\$500.00	\$6,500.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$7,500.00				

Data Analysis for Aluminium

The following data points were entered by the user for analysis.

	Aluminium (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	648	747	748	790	858	915	917	959	1090	1110
10	1130	1160	1200	1240	1390	1495	1760	1770	1830	1960
20	2140	2250	2460	2480	2800	3310	3510	3630	3640	4180
30	4660	5140	5880	6880	7640	7690	8450	9150	1.09e+004	1.14e+004
40	1.38e+004									

SUMMARY STAT	SUMMARY STATISTICS for Aluminium			
n	41			
Min	648			
Max	13800			
Range	13152			
Mean	3553.8			
Median	2140			
Variance	1.1301e+007			
StdDev	3361.7			
Std Error	525			
Skewness	1.4858			

Interquartile Range							3780	
	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
648	747.1	803.6	1120	2140	4900	9010	1.135e+004	1.38e+004

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Aluminium						
k	k Test Statistic R _k 5% Critical Value C _k Significant?					
1	3.048	3.05	No			

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Shapiro-Wilk Test Statistic	0.8					
Shapiro-Wilk 5% Critical Value	0.94					

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Aluminium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the

distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/guality/ga-docs.html).

Tests for Aluminium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.7943			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	4438
95% Non-Parametric (Chebyshev) UCL	5842

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (5842) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data, AL is the action level or threshold (6521),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic Critical Value $t_{0.95}$ Null Hypothesis						
-5.6517	1.6839	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothesis						
33	26	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

 * - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN				
Primary Objective of Design	Compare a site mean to a fixed threshold				
Type of Sampling Design	Parametric				
Sample Placement (Location) in the Field	Simple random sampling				
Working (Null) Hypothesis	The mean value at the site exceeds the threshold				
Formula for calculating number of sampling locations	Student's t-test				
Calculated total number of samples	79				
Number of samples on map ^a	79				
Number of selected sample areas b	2				
Specified sampling area ^c	188054.34 m ²				
Total cost of sampling d	\$40,500.00				

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1							
X Coord	Y Coord	Label	Value	Туре	Historical		
679242.7260	3083326.5280	J-07S	0.47	Manual	Т		
679104.2450	3083223.2620	J-02S	0.34	Manual	Т		
679181.2750	3083178.2880	J-08S	0.29	Manual	Т		
679133.4290	3083306.3130	J-01S	0.14	Manual	Т		
679268.7700	3083200.3260	J-11S	0.26	Manual	Т		
679171.2970	3083289.7960	J-04S	0.115	Manual	Т		
679164.8060	3083214.7100	J-06S	0.23	Manual	Т		
679213.7730	3083224.9730	J-09S	0.105	Manual	Т		
679280.5440	3083305.6810	J-10S	0.105	Manual	Т		
679155.0740	3083294.6960	J-03S	0.1	Manual	Т		
679301.1600	3083254.0340	J-12S	0.09	Manual	Т		
679225.8560	3083359.9740	J-05S	0.08	Manual	Т		
679344.9917	3083309.2278	J-38S	2.2	Adaptive-Fill			
679167.5023	3083363.3712	J-37S	2.1	Adaptive-Fill			
679247.5039	3083262.4916	J-19S	1.7	Adaptive-Fill			
679108.9961	3083271.3916	J-36S	1.7	Adaptive-Fill			
679224.6687	3083176.2417	J-41S	1.7	Adaptive-Fill			
679192.8634	3083333.4953	J-23S	1.4	Adaptive-Fill			
679208.9664	3083274.1678	J-28S	1.2	Adaptive-Fill			
679306.1204	3083334.0306	J-32S	1.1	Adaptive-Fill			

Area: Area 3

X Coord	Y Coord	Label	Value	Туре	Historical
679470.3570	3082776.7350	J-38S	2.2	Manual	Т
679433.9450	3082731.6820	J-37S	2.1	Manual	Т
679343.5810	3082969.5980	J-19S	1.7	Manual	Т
679382.8900	3082667.5270	J-36S	1.7	Manual	Т
679560.6070	3082897.2580	J-41S	1.7	Manual	Т
679297.0010	3082840.6970	J-23S	1.4	Manual	Т
679272.0040	3082652.6750	J-28S	1.2	Manual	Т
679453.4760	3082914.1150	J-32S	1.1	Manual	Т
679146.6460	3082549.7640	J-25S	1	Manual	Т
679169.0760	3082537.3510	J-27S	1	Manual	Т
679495.8840	3082940.9730	J-33S	0.81	Manual	Т
679304.6530	3082548.6880	J-34S	0.8	Manual	Т
679342.7410	3082605.3190	J-35S	0.78	Manual	Т
679252.7130	3082781.0290	J-22S	0.74	Manual	Т
679497.3310	3082840.3960	J-39S	0.7	Manual	Т
679524.3310	3082886.8990	J-40S	0.62	Manual	Т
679329.4380	3082711.0960	J-29S	0.58	Manual	Т
679149.4920	3082933.0980	J-13S	0.54	Manual	Т
679374.4420	3082791.3300	J-30S	0.54	Manual	Т
679360.5700	3083026.4980	J-18S	0.44	Manual	Т
679293.5600	3082950.4980	J-17S	0.41	Manual	Т
679261.0980	3083016.3510	J-15S	0.38	Manual	Т
679222.6340	3082840.1720	J-16S	0.33	Manual	Т
679394.8070	3082971.8300	J-24S	0.3	Manual	Т
679382.8640	3083009.1130	J-20S	0.12	Manual	Т
679279.6830	3083075.4290	J-14S	0.115	Manual	Т
679410.1490	3082845.8460	J-31S	0.23	Manual	Т
679224.5850	3082683.1400	J-26S	0.11	Manual	Т
679335.0020	3082941.1720	J-21S	0.1	Manual	Т
679187.7108	3082743.9049		0	Adaptive-Fill	
679201.3419	3082986.3558		0	Adaptive-Fill	
679228.1261	3082909.4864		0	Adaptive-Fill	
679354.1234	3082881.5703		0	Adaptive-Fill	
679165.3089	3082875.0841		0	Adaptive-Fill	
679214.7953	3083052.5423		0	Adaptive-Fill	
679270.7295	3082728.2056		0	Adaptive-Fill	
679253.6530	3082528.8006		0	Adaptive-Fill	
679296.7054	3082893.3847		0	Adaptive-Fill	
679329.1669	3082764.4865		0	Adaptive-Fill	
679322.5779	3082652.2311		0	Adaptive-Fill	

679377.2589	3082728.9013	0	Adaptive-Fill
679397.3161	3082610.7954	0	Adaptive-Fill
679392.4419	3082922.3762	0	Adaptive-Fill
679291.0689	3082602.5607	0	Adaptive-Fill
679191.3863	3082789.3978	0	Adaptive-Fill
679439.5764	3082956.5943	0	Adaptive-Fill
679441.5982	3082681.4673	0	Adaptive-Fill
679448.5842	3082821.4334	0	Adaptive-Fill
679299.4420	3082797.6478	0	Adaptive-Fill
679549.8870	3082842.9025	0	Adaptive-Fill
679312.1684	3083030.8840	0	Adaptive-Fill
679230.0779	3082953.9913	0	Adaptive-Fill
679338.6362	3082832.5643	0	Adaptive-Fill
679472.1177	3082720.7150	0	Adaptive-Fill
679258.2576	3083112.5898	0	Adaptive-Fill
679417.6739	3082886.3804	0	Adaptive-Fill
679187.6340	3082917.6887	0	Adaptive-Fill
679448.6706	3082857.7165	0	Adaptive-Fill
679228.4704	3083021.7000	0	Adaptive-Fill

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyta	_	Parameter					
Analyte	11	S	Δ	α	β	Ζ _{1-α} ^a	Z _{1-β} b
Arsenic	79	0.58368 mg/kg	0.1948 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples								
AL=0.39		α	=5	α=	10	α=15		
		s=1.16736	s=0.58368	s=1.16736	s=0.58368	s=1.16736	s=0.58368	
	β=5	9698	2426	7674	1920	6442	1611	
LBGR=90	β=10	7675	1920	5887	1473	4815	1205	
	β=15	6443	1612	4815	1205	3851	963	
	β=5	2426	608	1920	481	1611	404	
LBGR=80	β=10	1920	481	1473	369	1205	302	
	β=15	1612	404	1205	302	963	242	
LBGR=70	β=5	1079	271	854	214	717	180	

β=10	854	215	655	165	536	135
β=15	718	181	536	135	429	108

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$40,500.00, which averages out to a per sample cost of \$512.66. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	79 Samples					
Field collection costs		\$100.00	\$7,900.00					
Analytical costs	\$400.00	\$400.00	\$31,600.00					
Sum of Field & Analytical costs		\$500.00	\$39,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$40,500.00					

Data Analysis for Arsenic

The following data points were entered by the user for analysis.

	Arsenic (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0	0
10	0	0	0	0	0	0	0	0	0	0
20	0	0	0	0	0	0	0	0	0	0
30	0.08	0.09	0.1	0.1	0.105	0.105	0.11	0.115	0.115	0.12
40	0.14	0.23	0.23	0.26	0.29	0.3	0.33	0.34	0.38	0.41
50	0.44	0.47	0.54	0.54	0.58	0.62	0.7	0.74	0.78	8.0
60	0.81	1	1	1.1	1.1	1.2	1.2	1.4	1.4	1.7
70	1.7	1.7	1.7	1.7	1.7	2.1	2.1	2.2	2.2	

SUMMARY STA	SUMMARY STATISTICS for Arsenic					
n	79					
Min	0					
Max	2.2					
Range	2.2					
Mean	0.49582					
Median	0.12					
Variance	0.42709					

	0.65352							
		0.073527						
		-	1.2833	3				
Inte	rquar	0.8						
			Perc	entile	es			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0	0	0	0.12	0.8	1.7	2.1	2.2

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Arsenic						
k	Test Statistic R _k	5% Critical Value C _k	Significant?			
1	2.68	3.05	No			

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Lilliefors Test Statistic	0.8461					
Lilliefors 5% Critical Value	0.94					

The calculated Lilliefors test statistic is less than the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Arsenic


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Arsenic

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST						
Lilliefors Test Statistic	0.2259					
Lilliefors 5% Critical Value	0.09968					

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLS ON THE MEAN						
95% Parametric UCL	0.6182					
95% Non-Parametric (Chebyshev) UCL	0.8163					

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.8163) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=79 data,

AL is the action level or threshold (0.39),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=78 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic	Critical Value t _{0.95}	Null Hypothesis				
1.4392	1.6646	Cannot Reject				

The test did not reject the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean exceeds the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test S	Statistic (S+)	95% Critical Value	Null Hypothesis				
49		47	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN							
Primary Objective of Design	Compare a site mean to a fixed threshold							
Type of Sampling Design	Parametric							
Sample Placement (Location) in the Field	Simple random sampling							
Working (Null) Hypothesis	The mean value at the site exceeds the threshold							
Formula for calculating number of sampling locations	Student's t-test							
Calculated total number of samples	2							
Number of samples on map ^a	41							
Number of selected sample areas b	2							
Specified sampling area ^c	188054.34 m ²							
Total cost of sampling d	\$2,000.00							

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical				
679242.7260	3083326.5280	J-07S	0.47	Manual	Т				
679104.2450	3083223.2620	J-02S	0.34	Manual	Т				
679181.2750	3083178.2880	J-08S	0.29	Manual	Т				
679133.4290	3083306.3130	J-01S	0.14	Manual	Т				
679268.7700	3083200.3260	J-11S	0.26	Manual	Т				
679171.2970	3083289.7960	J-04S	0.115	Manual	Т				
679164.8060	3083214.7100	J-06S	0.23	Manual	Т				
679213.7730	3083224.9730	J-09S	0.105	Manual	Т				
679280.5440	3083305.6810	J-10S	0.105	Manual	Т				
679155.0740	3083294.6960	J-03S	0.1	Manual	Т				
679301.1600	3083254.0340	J-12S	0.09	Manual	Т				
679225.8560	3083359.9740	J-05S	0.08	Manual	Т				

Area: Area 3									
X Coord	Y Coord	Label	Value	Туре	Historical				
679470.3570	3082776.7350	J-38S	2.2	Manual	Т				
679433.9450	3082731.6820	J-37S	2.1	Manual	Т				
679343.5810	3082969.5980	J-19S	1.7	Manual	Т				
679382.8900	3082667.5270	J-36S	1.7	Manual	Т				
679560.6070	3082897.2580	J-41S	1.7	Manual	Т				
679297.0010	3082840.6970	J-23S	1.4	Manual	Т				
679272.0040	3082652.6750	J-28S	1.2	Manual	Т				

679453.4760 3082914.1150 J-32S 1.1 N	Manual T
679146.6460 3082549.7640 J-25S 1 N	Manual T
679169.0760 3082537.3510 J-27S 1 N	Manual T
679495.8840 3082940.9730 J-33S 0.81 N	Manual T
679304.6530 3082548.6880 J-34S 0.8 N	Manual T
679342.7410 3082605.3190 J-35S 0.78 N	Manual T
679252.7130 3082781.0290 J-22S 0.74 N	Manual T
679497.3310 3082840.3960 J-39S 0.7 N	Manual T
679524.3310 3082886.8990 J-40S 0.62 N	Manual T
679329.4380 3082711.0960 J-29S 0.58 N	Manual T
679149.4920 3082933.0980 J-13S 0.54 N	Manual T
679374.4420 3082791.3300 J-30S 0.54 N	Manual T
679360.5700 3083026.4980 J-18S 0.44 N	Manual T
679293.5600 3082950.4980 J-17S 0.41 N	Manual T
679261.0980 3083016.3510 J-15S 0.38 N	Manual T
679222.6340 3082840.1720 J-16S 0.33 N	Manual T
679394.8070 3082971.8300 J-24S 0.3 N	Manual T
679382.8640 3083009.1130 J-20S 0.12 N	Manual T
679279.6830 3083075.4290 J-14S 0.115 N	Manual T
679410.1490 3082845.8460 J-31S 0.23 N	Manual T
679224.5850 3082683.1400 J-26S 0.11 N	Manual T
679335.0020 3082941.1720 J-21S 0.1 N	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

S

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

1-p

The values of these inputs that result in the calculated number of sampling locations are:

Analyta	_		Par	amete	er		
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z_{1-β} b
Arsenic	2	0.58368 mg/kg	3 mg/kg	0.05	0.1	1.64485	1.28155


 $^{\rm a}$ This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples									
AL=6		α	=5	α=	:10	α=15			
		s=1.16736	s=0.58368	s=1.16736 s=0.58368		s=1.16736	s=0.58368		
	β=5	43	12	34	9	28	8		
LBGR=90	β=10	34	10	26	8	21	6		
	β=15	29	9	22	6	17	5		
	β=5	12	4	9	3	8	3		
LBGR=80	β=10	10	4	8	3	6	2		
	β=15	9	4	6	3	5	2		
LBGR=70	β=5	6	3	5	2	4	2		

β=10	5	3	4	2	3	2
ß=15	5	3	4	2	3	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	2 Samples						
Field collection costs		\$100.00	\$200.00						
Analytical costs	\$400.00	\$400.00	\$800.00						
Sum of Field & Analytical costs		\$500.00	\$1,000.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$2,000.00						

Data Analysis for Arsenic

The following data points were entered by the user for analysis.

	Arsenic (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0	0
10	0	0	0	0	0	0	0	0	0	0
20	0	0	0	0	0	0	0	0	0	0
30	0.08	0.09	0.1	0.1	0.105	0.105	0.11	0.115	0.115	0.12
40	0.14	0.23	0.23	0.26	0.29	0.3	0.33	0.34	0.38	0.41
50	0.44	0.47	0.54	0.54	0.58	0.62	0.7	0.74	0.78	8.0
60	0.81	1	1	1.1	1.1	1.2	1.2	1.4	1.4	1.7
70	1.7	1.7	1.7	1.7	1.7	2.1	2.1	2.2	2.2	

SUMMARY STATISTICS for Arsenic		
n	79	
Min	0	
Max	2.2	
Range	2.2	
Mean	0.49582	
Median	0.12	
Variance	0.42709	

StdDev		0.65352						
Std Error		0.073527						
Skewness		1.2833						
Inte	Interquartile Range		0.8					
Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0	0	0	0.12	0.8	1.7	2.1	2.2

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Arsenic			
k	Test Statistic R _k	5% Critical Value C _k	Significant?
1	2.608	3.305	No

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)			
Lilliefors Test Statistic	0.2282		
Lilliefors 5% Critical Value	0.1003		

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Arsenic


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Arsenic

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST		
Lilliefors Test Statistic	0.2259	
Lilliefors 5% Critical Value	0.09968	

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN							
95% Parametric UCL	0.6182						
95% Non-Parametric (Chebyshev) UCL	0.8163						

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.8163) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=79 data,

AL is the action level or threshold (6),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=78 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic	Critical Value t _{0.95}	Null Hypothesis					
-74.86	1.6646	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+)	95% Critical Value	Null Hypothesis					
79	47	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN								
Primary Objective of Design	Compare a site mean to a fixed threshold							
Type of Sampling Design	Parametric							
Sample Placement (Location) in the Field	Simple random sampling							
Working (Null) Hypothesis	The mean value at the site exceeds the threshold							
Formula for calculating number of sampling locations	Student's t-test							
Calculated total number of samples	2							
Number of samples on map ^a	41							
Number of selected sample areas b	2							
Specified sampling area ^c	188054.34 m ²							
Total cost of sampling d	\$2,000.00							

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical				
679268.7700	3083200.3260	J-11S	0.98	Manual	Т				
679301.1600	3083254.0340	J-12S	0.58	Manual	Т				
679171.2970	3083289.7960	J-04S	2.1	Manual	Т				
679155.0740	3083294.6960	J-03S	1.2	Manual	Т				
679133.4290	3083306.3130	J-01S	0.63	Manual	Т				
679104.2450	3083223.2620	J-02S	3.9	Manual	Т				
679164.8060	3083214.7100	J-06S	3.7	Manual	Т				
679181.2750	3083178.2880	J-08S	5.2	Manual	Т				
679213.7730	3083224.9730	J-09S	1.8	Manual	Т				
679280.5440	3083305.6810	J-10S	1	Manual	Т				
679242.7260	3083326.5280	J-07S	4.3	Manual	Т				
679225.8560	3083359.9740	J-05S	0.8	Manual	Т				

Area: Area 3										
X Coord	Y Coord	Label	Value	Туре	Historical					
679261.0980	3083016.3510	J-15S	3.4	Manual	Т					
679335.0020	3082941.1720	J-21S	0.59	Manual	Т					
679343.5810	3082969.5980	J-19S	15	Manual	Т					
679394.8070	3082971.8300	J-24S	1.2	Manual	Т					
679382.8640	3083009.1130	J-20S	2.5	Manual	Т					
679293.5600	3082950.4980	J-17S	2.4	Manual	Т					
679360.5700	3083026.4980	J-18S	3.2	Manual	Т					

679297.0010	3082840.6970	J-23S	3.5	Manual T
679252.7130	3082781.0290	J-22S	4.1	Manual T
679222.6340	3082840.1720	J-16S	3.2	Manual T
679279.6830	3083075.4290	J-14S	0.6	Manual T
679149.4920	3082933.0980	J-13S	4.9	Manual T
679272.0040	3082652.6750	J-28S	6.1	Manual T
679224.5850	3082683.1400	J-26S	1.7	Manual T
679146.6460	3082549.7640	J-25S	7.4	Manual T
679169.0760	3082537.3510	J-27S	3.7	Manual T
679342.7410	3082605.3190	J-35S	1.8	Manual T
679304.6530	3082548.6880	J-34S	1.5	Manual T
679382.8900	3082667.5270	J-36S	6	Manual T
679329.4380	3082711.0960	J-29S	2.7	Manual T
679374.4420	3082791.3300	J-30S	2.2	Manual T
679453.4760	3082914.1150	J-32S	2.9	Manual T
679410.1490	3082845.8460	J-31S	0.76	Manual T
679560.6070	3082897.2580	J-41S	2.2	Manual T
679495.8840	3082940.9730	J-33S	1.9	Manual T
679524.3310	3082886.8990	J-40S	2.3	Manual T
679497.3310	3082840.3960	J-39S	1.4	Manual T
679470.3570	3082776.7350	J-38S	2.5	Manual T
679433.9450	3082731.6820	J-37S	8.8	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyte	_		Parar	neter			
	11	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
Chromium	2	2.69 mg/kg	105.338 mg/kg	0.05	0.1	1.64485	1.28155


 $^{\rm a}$ This value is automatically calculated by VSP based upon the user defined value of α .

^b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples								
AL=210.675		α	=5	α=	10	α=15		
		s=5.38	s=2.69	s=5.38 s=2.69		s=5.38	s=2.69	
	β=5	3	2	2	1	2	1	
LBGR=90	β=10	2	2	2	1	1	1	
	β=15	2	2	2	1	1	1	
	β=5	2	2	1	1	1	1	
LBGR=80	β=10	2	2	1	1	1	1	
	β=15	2	2	1	1	1	1	
LBGR=70	β=5	2	2	1	1	1	1	

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	2 Samples						
Field collection costs		\$100.00	\$200.00						
Analytical costs	\$400.00	\$400.00	\$800.00						
Sum of Field & Analytical costs		\$500.00	\$1,000.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$2,000.00						

Data Analysis for Chromium

The following data points were entered by the user for analysis.

	Chromium (mg/kg)										
Rank	1	2	3	4	5	6	7	8	9	10	
0	0.58	0.59	0.6	0.63	0.76	0.8	0.98	1	1.2	1.2	
10	1.4	1.5	1.7	1.8	1.8	1.9	2.1	2.2	2.2	2.3	
20	2.4	2.5	2.5	2.7	2.9	3.2	3.2	3.4	3.5	3.7	
30	3.7	3.9	4.1	4.3	4.9	5.2	6	6.1	7.4	8.8	
40	15										

SUMMARY STA	SUMMARY STATISTICS for Chromium			
n	41			
Min	0.58			
Max	15			
Range	14.42			
Mean	3.0888			
Median	2.4			
Variance	7.2627			
StdDev	StdDev 2.6949			
Std Error	0.42088			
Skewness	2.5355			

Interquartile Range			2.5					
Pero			Perc	entile	s			
1%	1% 5% 10% 25% 50% 75% 90% 95% 99%						99%	
0.58	0.591	0.656	1.3	2.4	3.8	6.08	8.66	15

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST for Chromium					
k	k Test Statistic R _k 5% Critical Value C _k Significant?					
1	4.42	3.05	Yes			

The test statistic 4.42 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS for Chromium		
1	15	

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Shapiro-Wilk Test Statistic	0.8953			
Shapiro-Wilk 5% Critical Value	0.94			

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Chromium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Chromium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST			
Shapiro-Wilk Test Statistic 0.7725			
Shapiro-Wilk 5% Critical Value	0.941		

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	3.797
95% Non-Parametric (Chebyshev) UCL	4.923

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (4.923) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (210.675),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-493.22	1.6839	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
41	26	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold					
Type of Sampling Design	Parametric					
Sample Placement (Location) in the Field	Simple random sampling					
Working (Null) Hypothesis	The mean value at the site exceeds the threshold					
Formula for calculating number of sampling locations	Student's t-test					
Calculated total number of samples	2					
Number of samples on map ^a	41					
Number of selected sample areas b	2					
Specified sampling area ^c	188054.34 m ²					
Total cost of sampling d	\$2,000.00					

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679268.7700	3083200.3260	J-11S	0.98	Manual	Т	
679301.1600	3083254.0340	J-12S	0.58	Manual	Т	
679171.2970	3083289.7960	J-04S	2.1	Manual	Т	
679155.0740	3083294.6960	J-03S	1.2	Manual	Т	
679133.4290	3083306.3130	J-01S	0.63	Manual	Т	
679104.2450	3083223.2620	J-02S	3.9	Manual	Т	
679164.8060	3083214.7100	J-06S	3.7	Manual	Т	
679181.2750	3083178.2880	J-08S	5.2	Manual	Т	
679213.7730	3083224.9730	J-09S	1.8	Manual	Т	
679280.5440	3083305.6810	J-10S	1	Manual	Т	
679242.7260	3083326.5280	J-07S	4.3	Manual	Т	
679225.8560	3083359.9740	J-05S	0.8	Manual	Т	

Area: Area 3						
X Coord	Y Coord	Label	Value	Туре	Historical	
679261.0980	3083016.3510	J-15S	3.4	Manual	Т	
679335.0020	3082941.1720	J-21S	0.59	Manual	Т	
679343.5810	3082969.5980	J-19S	15	Manual	Т	
679394.8070	3082971.8300	J-24S	1.2	Manual	Т	
679382.8640	3083009.1130	J-20S	2.5	Manual	Т	
679293.5600	3082950.4980	J-17S	2.4	Manual	Т	
679360.5700	3083026.4980	J-18S	3.2	Manual	Т	

679297.0010	3082840.6970	J-23S	3.5	Manual T
679252.7130	3082781.0290	J-22S	4.1	Manual T
679222.6340	3082840.1720	J-16S	3.2	Manual T
679279.6830	3083075.4290	J-14S	0.6	Manual T
679149.4920	3082933.0980	J-13S	4.9	Manual T
679272.0040	3082652.6750	J-28S	6.1	Manual T
679224.5850	3082683.1400	J-26S	1.7	Manual T
679146.6460	3082549.7640	J-25S	7.4	Manual T
679169.0760	3082537.3510	J-27S	3.7	Manual T
679342.7410	3082605.3190	J-35S	1.8	Manual T
679304.6530	3082548.6880	J-34S	1.5	Manual T
679382.8900	3082667.5270	J-36S	6	Manual T
679329.4380	3082711.0960	J-29S	2.7	Manual T
679374.4420	3082791.3300	J-30S	2.2	Manual T
679453.4760	3082914.1150	J-32S	2.9	Manual T
679410.1490	3082845.8460	J-31S	0.76	Manual T
679560.6070	3082897.2580	J-41S	2.2	Manual T
679495.8840	3082940.9730	J-33S	1.9	Manual T
679524.3310	3082886.8990	J-40S	2.3	Manual T
679497.3310	3082840.3960	J-39S	1.4	Manual T
679470.3570	3082776.7350	J-38S	2.5	Manual T
679433.9450	3082731.6820	J-37S	8.8	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter					
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z_{1-β} b
Chromium	2	2.69 mg/kg	207.59 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples								
AL=210.675		α=5		α=	:10	α=15		
		s=5.38	s=2.69	s=5.38	s=2.69	s=5.38	s=2.69	
	β=5	3	2	2	1	2	1	
LBGR=90	β=10	2	2	2	1	1	1	
	β=15	2	2	2	1	1	1	
	β=5	2	2	1	1	1	1	
LBGR=80	β=10	2	2	1	1	1	1	
	β=15	2	2	1	1	1	1	
LBGR=70	β=5	2	2	1	1	1	1	

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	2 Samples			
Field collection costs		\$100.00	\$200.00			
Analytical costs	\$400.00	\$400.00	\$800.00			
Sum of Field & Analytical costs		\$500.00	\$1,000.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$2,000.00			

Data Analysis for Chromium

The following data points were entered by the user for analysis.

	Chromium (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	0.58	0.59	0.6	0.63	0.76	0.8	0.98	1	1.2	1.2
10	1.4	1.5	1.7	1.8	1.8	1.9	2.1	2.2	2.2	2.3
20	2.4	2.5	2.5	2.7	2.9	3.2	3.2	3.4	3.5	3.7
30	3.7	3.9	4.1	4.3	4.9	5.2	6	6.1	7.4	8.8
40	15									

SUMMARY STATISTICS for Chromium				
n	41			
Min	0.58			
Max	15			
Range	14.42			
Mean	3.0888			
Median	2.4			
Variance	7.2627			
StdDev	2.6949			
Std Error	0.42088			
Skewness	2.5355			

Inte	erquar	2.5						
		entile	s					
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.58	0.591	0.656	1.3	2.4	3.8	6.08	8.66	15

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Chromium					
k	Test Statistic R	5% Critical Value C _k	Significant?		
1	4.42	3.05	Yes		

The test statistic 4.42 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTL	IERS for Chromium
1	15

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Shapiro-Wilk Test Statistic	0.8953			
Shapiro-Wilk 5% Critical Value	0.94			

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Chromium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Chromium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.7725			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN						
95% Parametric UCL	3.797					
95% Non-Parametric (Chebyshev) UCL	4.923					

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (4.923) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (210.675),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic	Critical Value t _{0.95}	Null Hypothesis					
-493.22	1.6839	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+)	95% Critical Value	Null Hypothesis					
41	26	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary


This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.

SUMMARY OF SAMPLING DESIGN							
Primary Objective of Design	Compare a site mean to a fixed threshold						
Type of Sampling Design	Parametric						
Sample Placement (Location) in the Field	Simple random sampling						
Working (Null) Hypothesis	The mean value at the site exceeds the threshold						
Formula for calculating number of sampling locations	Student's t-test						
Calculated total number of samples	2						
Number of samples on map ^a	41						
Number of selected sample areas b	2						
Specified sampling area ^c	188054.34 m ²						
Total cost of sampling d	\$2,000.00						

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

X Coord	Y Coord	Label	Value	Туре	Historical
679268.7700	3083200.3260	J-11S	0.0017	Manual	Т
679301.1600	3083254.0340	J-12S	0.59	Manual	Т
679171.2970	3083289.7960	J-04S	0.00043	Manual	Т
679155.0740	3083294.6960	J-03S	0.0051	Manual	Т
679133.4290	3083306.3130	J-01S	0.055	Manual	Т
679104.2450	3083223.2620	J-02S	0.019	Manual	Т
679164.8060	3083214.7100	J-06S	0.033	Manual	Т
679181.2750	3083178.2880	J-08S	0.048	Manual	Т
679213.7730	3083224.9730	J-09S	0.00036	Manual	Т
679280.5440	3083305.6810	J-10S	0.00038	Manual	Т
679242.7260	3083326.5280	J-07S	0.012	Manual	Т
679225.8560	3083359.9740	J-05S	0.0021	Manual	Т

	Area: Area 3										
X Coord	Y Coord	Label	Value	Туре	Historical						
679261.0980	3083016.3510	J-15S	0.013	Manual	Т						
679335.0020	3082941.1720	J-21S	0.00038	Manual	Т						
679343.5810	3082969.5980	J-19S	0.0065	Manual	Т						
679394.8070	3082971.8300	J-24S	0.012	Manual	Т						
679382.8640	3083009.1130	J-20S	0.00044	Manual	Т						
679293.5600	3082950.4980	J-17S	0.055	Manual	Т						
679360.5700	3083026.4980	J-18S	0.0048	Manual	Т						
679297.0010	3082840.6970	J-23S	0.0077	Manual	Т						
679252.7130	3082781.0290	J-22S	0.0045	Manual	Т						
679222.6340	3082840.1720	J-16S	0.0025	Manual	Т						
679279.6830	3083075.4290	J-14S	0.00038	Manual	Т						
679149.4920	3082933.0980	J-13S	0.0073	Manual	Т						
679272.0040	3082652.6750	J-28S	0.054	Manual	Т						
679224.5850	3082683.1400	J-26S	0.011	Manual	Т						
679146.6460	3082549.7640	J-25S	0.01	Manual	Т						
679169.0760	3082537.3510	J-27S	0.0072	Manual	Т						
679342.7410	3082605.3190	J-35S	0.0038	Manual	Т						
679304.6530	3082548.6880	J-34S	0.000385	Manual	Т						
679382.8900	3082667.5270	J-36S	0.008	Manual	Т						
679329.4380	3082711.0960	J-29S	0.0024	Manual	Т						
679374.4420	3082791.3300	J-30S	0.0043	Manual	Т						
679453.4760	3082914.1150	J-32S	0.000365	Manual	Т						
679410.1490	3082845.8460	J-31S	0.0026	Manual	Т						
679560.6070	3082897.2580	J-41S	0.0053	Manual	Т						
679495.8840	3082940.9730	J-33S	0.0048	Manual	Т						

679524.3310	3082886.8990	J-40S	0.0046	Manual	Т
	3082840.3960			Manual	
679470.3570	3082776.7350	J-38S	0.0013	Manual	Т
679433.9450	3082731.6820	J-37S	0.00035	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-R) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region.

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analyta		n		Para	mete	r		
	Analyte n S		Δ	α	β	Z _{1-α} a	Z _{1-β} b	
	Mercury	2	0.09 mg/kg	1.0436 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at $1-\alpha$ on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at $1-\alpha$. If any of the inputs change, the number of samples that result in the correct curve changes.





Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed).
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples						
AL=2.0872	α=5	α=10	α=15			

	s=0.18	s=0.09	s=0.18	s=0.09	s=0.18	s=0.09	
	β=5	10	4	8	3	6	2
LBGR=90	β=10	8	3	6	3	5	2
	β=15	7	3	5	2	4	2
	β=5	4	2	3	2	2	1
LBGR=80	β=10	3	2	3	2	2	1
	β=15	3	2	2	2	2	1
	β=5	3	2	2	1	2	1
LBGR=70	β=10	3	2	2	1	1	1
	β=15	2	2	2	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	2 Samples						
Field collection costs		\$100.00	\$200.00						
Analytical costs	\$400.00	\$400.00	\$800.00						
Sum of Field & Analytical costs		\$500.00	\$1,000.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$2,000.00						

Data Analysis for Mercury

The following data points were entered by the user for analysis.

	Mercury (mg/kg)										
Rank	1	2	3	4	5	6	7	8	9	10	
0	0.00035	0.00036	0.000365	0.00038	0.00038	0.00038	0.000385	0.00043	0.00044	0.0013	
10	0.0017	0.0021	0.0024	0.0025	0.0026	0.0038	0.0043	0.0045	0.0046	0.0048	
20	0.0048	0.0051	0.0053	0.0065	0.0072	0.0073	0.0077	0.008	0.01	0.011	
30	0.012	0.012	0.013	0.014	0.019	0.033	0.048	0.054	0.055	0.055	
40	0.59										

SUMMARY STATISTICS for Mercury				
n 41				
Min 0.00035				

Max			0.59					
Range			0.58965					
	Mea	n		0.02478				
	Media	an			(0.0048		
	Variance 0.0084248			}				
	StdDev			0.091787				
Std Error 0.014335								
	Skewness			6.13				
	Interquartil	e Range		0.0105				
	Percen							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.00035	0.0003605	0.00038	0.0015	0.0048	0.012	0.0528	0.055	0.59

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Mercury						
k Test Statistic R _k 5% Critical Value C _k Significant?						
1	6.158	3.05	Yes			

The test statistic 6.158 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUT	LIERS for Mercury
1	0.59

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Shapiro-Wilk Test Statistic 0.6364				
Shapiro-Wilk 5% Critical Value	0.94			

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots for Mercury

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through

2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Mercury

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic 0.2612					
Shapiro-Wilk 5% Critical Value 0.941					

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	0.04892				
95% Non-Parametric (Chebyshev) UCL	0.08726				

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.08726) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data, AL is the action level or threshold (2.0872).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-143.88	1.6839	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
41	26	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1. Software and documentation available at http://dqo.pnl.gov/vsp
Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

 * - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary


This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.

SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold				
Type of Sampling Design	Parametric				
Sample Placement (Location) in the Field	Simple random sampling				
Working (Null) Hypothesis	The mean value at the site exceeds the threshold				
Formula for calculating number of sampling locations	Student's t-test				
Calculated total number of samples	2				
Number of samples on map ^a	41				
Number of selected sample areas b	2				
Specified sampling area ^c	188054.34 m ²				
Total cost of sampling d	\$2,000.00				

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

X Coord	Y Coord	Label	Value	Туре	Historical
679268.7700	3083200.3260	J-11S	0.0017	Manual	Т
679301.1600	3083254.0340	J-12S	0.59	Manual	Т
679171.2970	3083289.7960	J-04S	0.00043	Manual	Т
679155.0740	3083294.6960	J-03S	0.0051	Manual	Т
679133.4290	3083306.3130	J-01S	0.055	Manual	Т
679104.2450	3083223.2620	J-02S	0.019	Manual	Т
679164.8060	3083214.7100	J-06S	0.033	Manual	Т
679181.2750	3083178.2880	J-08S	0.048	Manual	Т
679213.7730	3083224.9730	J-09S	0.00036	Manual	Т
679280.5440	3083305.6810	J-10S	0.00038	Manual	Т
679242.7260	3083326.5280	J-07S	0.012	Manual	Т
679225.8560	3083359.9740	J-05S	0.0021	Manual	Т

Area: Area 3						
X Coord	Y Coord	Label	Value	Туре	Historical	
679261.0980	3083016.3510	J-15S	0.013	Manual	Т	
679335.0020	3082941.1720	J-21S	0.00038	Manual	Т	
679343.5810	3082969.5980	J-19S	0.0065	Manual	Т	
679394.8070	3082971.8300	J-24S	0.012	Manual	Т	
679382.8640	3083009.1130	J-20S	0.00044	Manual	Т	
679293.5600	3082950.4980	J-17S	0.055	Manual	Т	
679360.5700	3083026.4980	J-18S	0.0048	Manual	Т	
679297.0010	3082840.6970	J-23S	0.0077	Manual	Т	
679252.7130	3082781.0290	J-22S	0.0045	Manual	Т	
679222.6340	3082840.1720	J-16S	0.0025	Manual	Т	
679279.6830	3083075.4290	J-14S	0.00038	Manual	Т	
679149.4920	3082933.0980	J-13S	0.0073	Manual	Т	
679272.0040	3082652.6750	J-28S	0.054	Manual	Т	
679224.5850	3082683.1400	J-26S	0.011	Manual	Т	
679146.6460	3082549.7640	J-25S	0.01	Manual	Т	
679169.0760	3082537.3510	J-27S	0.0072	Manual	Т	
679342.7410	3082605.3190	J-35S	0.0038	Manual	Т	
679304.6530	3082548.6880	J-34S	0.000385	Manual	Т	
679382.8900	3082667.5270	J-36S	0.008	Manual	Т	
679329.4380	3082711.0960	J-29S	0.0024	Manual	Т	
679374.4420	3082791.3300	J-30S	0.0043	Manual	Т	
679453.4760	3082914.1150	J-32S	0.000365	Manual	Т	
679410.1490	3082845.8460	J-31S	0.0026	Manual	Т	
679560.6070	3082897.2580	J-41S	0.0053	Manual	Т	
679495.8840	3082940.9730	J-33S	0.0048	Manual	Т	

					_
679524.3310	3082886.8990	J-40S	0.0046	Manual	Т
679497.3310	3082840.3960	J-39S	0.014	Manual	Т
679470.3570	3082776.7350	J-38S	0.0013	Manual	Т
679433.9450	3082731.6820	J-37S	0.00035	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-R) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples, S

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region.

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analyta	_		Par	amet	er		
Analyte	11	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
Mercury	2	0.09 mg/kg	2.06 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at $1-\alpha$ on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at $1-\alpha$. If any of the inputs change, the number of samples that result in the correct curve changes.





Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed).
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples					
AL=2.0872	α=5	α=10	α=15		

	s=0.18	s=0.09	s=0.18	s=0.09	s=0.18	s=0.09	
	β=5	10	4	8	3	6	2
LBGR=90	β=10	8	3	6	3	5	2
	β=15	7	3	5	2	4	2
	β=5	4	2	3	2	2	1
LBGR=80	β=10	3	2	3	2	2	1
	β=15	3	2	2	2	2	1
	β=5	3	2	2	1	2	1
LBGR=70	β=10	3	2	2	1	1	1
	β=15	2	2	2	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	2 Samples			
Field collection costs		\$100.00	\$200.00			
Analytical costs	\$400.00	\$400.00	\$800.00			
Sum of Field & Analytical costs		\$500.00	\$1,000.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$2,000.00			

Data Analysis for Mercury

The following data points were entered by the user for analysis.

	Mercury (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	0.00035	0.00036	0.000365	0.00038	0.00038	0.00038	0.000385	0.00043	0.00044	0.0013
10	0.0017	0.0021	0.0024	0.0025	0.0026	0.0038	0.0043	0.0045	0.0046	0.0048
20	0.0048	0.0051	0.0053	0.0065	0.0072	0.0073	0.0077	0.008	0.01	0.011
30	0.012	0.012	0.013	0.014	0.019	0.033	0.048	0.054	0.055	0.055
40	0.59									

SUMMARY STATISTICS for Mercury			
n	41		
Min	0.00035		

	Max	(0.59						
	Rang	e	0.58965						
		0	.02478						
		(0.0048						
		0.0	0084248	}					
	0.091787								
	Std Er	ror		0.014335					
	Skewn	ess		6.13					
	Interquartil	e Range		0.0105					
	Percer					ntiles			
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0.00035	0.0003605	0.00038	0.0015	0.0048	0.012	0.0528	0.055	0.59	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Mercury					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	6.158	3.05	Yes		

The test statistic 6.158 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUT	LIERS for Mercury
1	0.59

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.6364				
Shapiro-Wilk 5% Critical Value	0.94				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots for Mercury

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through

2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Mercury

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.2612			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN		
95% Parametric UCL	0.04892	
95% Non-Parametric (Chebyshev) UCL	0.08726	

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.08726) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data, AL is the action level or threshold (2.0872).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST			
t-statistic	Critical Value t _{0.95}	Null Hypothesis	
-143.88	1.6839	Reject	

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test			
Test Statistic (S+)	95% Critical Value	Null Hypothesis	
41	26	Reject	

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1. Software and documentation available at http://dqo.pnl.gov/vsp
Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

 * - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN							
Primary Objective of Design	Compare a site mean to a fixed threshold						
Type of Sampling Design	Parametric						
Sample Placement (Location) in the Field	Simple random sampling						
Working (Null) Hypothesis	The mean value at the site exceeds the threshold						
Formula for calculating number of sampling locations	Student's t-test						
Calculated total number of samples	2						
Number of samples on map ^a	41						
Number of selected sample areas b	2						
Specified sampling area ^c	188054.34 m ²						
Total cost of sampling d	\$2,000.00						

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1										
X Coord	Y Coord	Label	Value	Туре	Historical					
679268.7700	3083200.3260	J-11S	2.3	Manual	Т					
679301.1600	3083254.0340	J-12S	1.3	Manual	Т					
679171.2970	3083289.7960	J-04S	2.3	Manual	Т					
679155.0740	3083294.6960	J-03S	2.4	Manual	Т					
679133.4290	3083306.3130	J-01S	1.9	Manual	Т					
679104.2450	3083223.2620	J-02S	3.8	Manual	Т					
679164.8060	3083214.7100	J-06S	3.2	Manual	Т					
679181.2750	3083178.2880	J-08S	4.1	Manual	Т					
679213.7730	3083224.9730	J-09S	1.5	Manual	Т					
679280.5440	3083305.6810	J-10S	1.7	Manual	Т					
679242.7260	3083326.5280	J-07S	4.3	Manual	Т					
679225.8560	3083359.9740	J-05S	2.7	Manual	Т					

Area: Area 3									
X Coord	Y Coord	Label	Value	Туре	Historical				
679261.0980	3083016.3510	J-15S	3.5	Manual	Т				
679335.0020	3082941.1720	J-21S	1.5	Manual	Т				
679343.5810	3082969.5980	J-19S	26	Manual	Т				
679394.8070	3082971.8300	J-24S	3.1	Manual	Т				
679382.8640	3083009.1130	J-20S	2.1	Manual	Т				
679293.5600	3082950.4980	J-17S	2.3	Manual	Т				
679360.5700	3083026.4980	J-18S	4.2	Manual	Т				

679297.0010	3082840.6970	J-23S	3.6	Manual T
679252.7130	3082781.0290	J-22S	2.5	Manual T
679222.6340	3082840.1720	J-16S	2.6	Manual T
679279.6830	3083075.4290	J-14S	1.8	Manual T
679149.4920	3082933.0980	J-13S	2.8	Manual T
679272.0040	3082652.6750	J-28S	9.3	Manual T
679224.5850	3082683.1400	J-26S	1.9	Manual T
679146.6460	3082549.7640	J-25S	4.2	Manual T
679169.0760	3082537.3510	J-27S	3.2	Manual T
679342.7410	3082605.3190	J-35S	2	Manual T
679304.6530	3082548.6880	J-34S	1.9	Manual T
679382.8900	3082667.5270	J-36S	6.8	Manual T
679329.4380	3082711.0960	J-29S	2.3	Manual T
679374.4420	3082791.3300	J-30S	2.7	Manual T
679453.4760	3082914.1150	J-32S	2.7	Manual T
679410.1490	3082845.8460	J-31S	1.7	Manual T
679560.6070	3082897.2580	J-41S	6.3	Manual T
679495.8840	3082940.9730	J-33S	5.9	Manual T
679524.3310	3082886.8990	J-40S	2.15	Manual T
679497.3310	3082840.3960	J-39S	1.6	Manual T
679470.3570	3082776.7350	J-38S	5.7	Manual T
679433.9450	3082731.6820	J-37S	6	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

S

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$,

 $Z_{1-\beta}^{\alpha}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}^{\alpha}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter							
Analyte	"	S Δ α β $Z_{1-\alpha}$ α $Z_{1-\beta}$							
Lead	2	3.96 mg/kg	200 mg/kg	0.05	0.1	1.64485	1.28155		


 $^{\rm a}$ This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples										
		α	=5	α=	10	α=15				
AL=40	U	s=7.92	s=3.96	s=7.92	s=3.96	s=7.92	s=3.96			
	β=5	2	2	2	1	1	1			
LBGR=90	β=10	2	2	2	1	1	1			
	β=15	2	2	2	1	1	1			
	β=5	2	2	1	1	1	1			
LBGR=80	β=10	2	2	1	1	1	1			
	β=15	2	2	1	1	1	1			
LBGR=70	β=5	2	2	1	1	1	1			

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	2 Samples						
Field collection costs		\$100.00	\$200.00						
Analytical costs	\$400.00	\$400.00	\$800.00						
Sum of Field & Analytical costs		\$500.00	\$1,000.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$2,000.00						

Data Analysis for Lead

The following data points were entered by the user for analysis.

	Lead (mg/kg)										
Rank	Rank 1 2 3 4 5 6 7 8 9 10										
0	1.3	1.5	1.5	1.6	1.7	1.7	1.8	1.9	1.9	1.9	
10	2	2.1	2.15	2.3	2.3	2.3	2.3	2.4	2.5	2.6	
20	2.7	2.7	2.7	2.8	3.1	3.2	3.2	3.5	3.6	3.8	
30	4.1	4.2	4.2	4.3	5.7	5.9	6	6.3	6.8	9.3	
40	26										

SUMMARY ST	SUMMARY STATISTICS for Lead							
n	41							
Min	1.3							
Max	26							
Range	24.7							
Mean	3.7524							
Median	2.7							
Variance	15.65							
StdDev	3.956							
Std Error	0.61782							
Skewness	4.7237							

Inte	erquar			2.2				
Pero				entile	es			
1%	5%	10%	25%	50%	75%	90%	95%	99%
1.3	1.5	1.62	1.95	2.7	4.15	6.24	9.05	26

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Lead									
k	Test Statistic R _k 5% Critical Value C _k Significant?								
1	5.624	3.05	Yes						

The test statistic 5.624 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OU	TLIERS for Lead
1	26

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Shapiro-Wilk Test Statistic	0.835			
Shapiro-Wilk 5% Critical Value	0.94			

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Lead


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Lead

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.5047			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	4.793
95% Non-Parametric (Chebyshev) UCL	6.445

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (6.445) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (400),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
-641.36	1.6839	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
41	26	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	2
Number of samples on map ^a	41
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$2,000.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical				
679268.7700	3083200.3260	J-11S	2.3	Manual	Т				
679301.1600	3083254.0340	J-12S	1.3	Manual	Т				
679171.2970	3083289.7960	J-04S	2.3	Manual	Т				
679155.0740	3083294.6960	J-03S	2.4	Manual	Т				
679133.4290	3083306.3130	J-01S	1.9	Manual	Т				
679104.2450	3083223.2620	J-02S	3.8	Manual	Т				
679164.8060	3083214.7100	J-06S	3.2	Manual	Т				
679181.2750	3083178.2880	J-08S	4.1	Manual	Т				
679213.7730	3083224.9730	J-09S	1.5	Manual	Т				
679280.5440	3083305.6810	J-10S	1.7	Manual	Т				
679242.7260	3083326.5280	J-07S	4.3	Manual	Т				
679225.8560	3083359.9740	J-05S	2.7	Manual	Т				

Area: Area 3									
X Coord	Y Coord	Label	Value	Туре	Historical				
679261.0980	3083016.3510	J-15S	3.5	Manual	Т				
679335.0020	3082941.1720	J-21S	1.5	Manual	Т				
679343.5810	3082969.5980	J-19S	26	Manual	Т				
679394.8070	3082971.8300	J-24S	3.1	Manual	Т				
679382.8640	3083009.1130	J-20S	2.1	Manual	Т				
679293.5600	3082950.4980	J-17S	2.3	Manual	Т				
679360.5700	3083026.4980	J-18S	4.2	Manual	Т				

679297.0010	3082840.6970	J-23S	3.6	Manual T
679252.7130	3082781.0290	J-22S	2.5	Manual T
679222.6340	3082840.1720	J-16S	2.6	Manual T
679279.6830	3083075.4290	J-14S	1.8	Manual T
679149.4920	3082933.0980	J-13S	2.8	Manual T
679272.0040	3082652.6750	J-28S	9.3	Manual T
679224.5850	3082683.1400	J-26S	1.9	Manual T
679146.6460	3082549.7640	J-25S	4.2	Manual T
679169.0760	3082537.3510	J-27S	3.2	Manual T
679342.7410	3082605.3190	J-35S	2	Manual T
679304.6530	3082548.6880	J-34S	1.9	Manual T
679382.8900	3082667.5270	J-36S	6.8	Manual T
679329.4380	3082711.0960	J-29S	2.3	Manual T
679374.4420	3082791.3300	J-30S	2.7	Manual T
679453.4760	3082914.1150	J-32S	2.7	Manual T
679410.1490	3082845.8460	J-31S	1.7	Manual T
679560.6070	3082897.2580	J-41S	6.3	Manual T
679495.8840	3082940.9730	J-33S	5.9	Manual T
679524.3310	3082886.8990	J-40S	2.15	Manual T
679497.3310	3082840.3960	J-39S	1.6	Manual T
679470.3570	3082776.7350	J-38S	5.7	Manual T
679433.9450	3082731.6820	J-37S	6	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

S

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	n Parameter S Δ α β $Z_{1-\alpha}$ α $Z_{1-\beta}$					
Analyte	n						Ζ_{1-β} b
Lead	2	3.96 mg/kg	396.25 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples								
A1 400		α=5		α=	α=10		α=15	
AL=40	U	s=7.92	s=3.96	s=7.92	s=3.96	s=7.92	s=3.96	
	β=5	2	2	2	1	1	1	
LBGR=90	β=10	2	2	2	1	1	1	
	β=15	2	2	2	1	1	1	
	β=5	2	2	1	1	1	1	
LBGR=80	β=10	2	2	1	1	1	1	
	β=15	2	2	1	1	1	1	
LBGR=70	β=5	2	2	1	1	1	1	

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	2 Samples			
Field collection costs		\$100.00	\$200.00			
Analytical costs	\$400.00	\$400.00	\$800.00			
Sum of Field & Analytical costs		\$500.00	\$1,000.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$2,000.00			

Data Analysis for Lead

The following data points were entered by the user for analysis.

	Lead (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	1.3	1.5	1.5	1.6	1.7	1.7	1.8	1.9	1.9	1.9
10	2	2.1	2.15	2.3	2.3	2.3	2.3	2.4	2.5	2.6
20	2.7	2.7	2.7	2.8	3.1	3.2	3.2	3.5	3.6	3.8
30	4.1	4.2	4.2	4.3	5.7	5.9	6	6.3	6.8	9.3
40	26									

SUMMARY STATISTICS for Lead				
n	41			
Min	1.3			
Max	26			
Range	24.7			
Mean	3.7524			
Median	2.7			
Variance	15.65			
StdDev	3.956			
Std Error	0.61782			
Skewness	4.7237			

Inte	Interquartile Range			2.2				
Pero				entile	es			
1%	5%	10%	25%	50%	75%	90%	95%	99%
1.3	1.5	1.62	1.95	2.7	4.15	6.24	9.05	26

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST for Lead					
k Test Statistic R _k 5% Critical Value C _k Significant?						
1		5.624	3.05	Yes		

The test statistic 5.624 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OU	TLIERS for Lead
1	26

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Shapiro-Wilk Test Statistic	0.835					
Shapiro-Wilk 5% Critical Value	0.94					

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Lead


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Lead

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic 0.5047				
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	4.793			
95% Non-Parametric (Chebyshev) UCL	6.445			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (6.445) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (400),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
-641.36	1.6839	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
41	26	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	2
Number of samples on map ^a	41
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$2,000.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical				
679268.7700	3083200.3260	J-11S	0.89	Manual	Т				
679301.1600	3083254.0340	J-12S	0.65	Manual	Т				
679171.2970	3083289.7960	J-04S	1	Manual	Т				
679155.0740	3083294.6960	J-03S	1.7	Manual	Т				
679133.4290	3083306.3130	J-01S	0.97	Manual	Т				
679104.2450	3083223.2620	J-02S	5	Manual	Т				
679164.8060	3083214.7100	J-06S	5.3	Manual	Т				
679181.2750	3083178.2880	J-08S	5.7	Manual	Т				
679213.7730	3083224.9730	J-09S	0.95	Manual	Т				
679280.5440	3083305.6810	J-10S	0.83	Manual	Т				
679242.7260	3083326.5280	J-07S	7.1	Manual	Т				
679225.8560	3083359.9740	J-05S	0.77	Manual	Т				

Area: Area 3										
X Coord	Y Coord	Label	Value	Туре	Historical					
679261.0980	3083016.3510	J-15S	4.4	Manual	Т					
679335.0020	3082941.1720	J-21S	1.1	Manual	Т					
679343.5810	3082969.5980	J-19S	3.2	Manual	Т					
679394.8070	3082971.8300	J-24S	1.2	Manual	Т					
679382.8640	3083009.1130	J-20S	1.8	Manual	Т					
679293.5600	3082950.4980	J-17S	2.1	Manual	Т					
679360.5700	3083026.4980	J-18S	3.6	Manual	Т					

3082840.6970	J-23S	6.7	Manual T
3082781.0290	J-22S	2.3	Manual T
3082840.1720	J-16S	4.5	Manual T
3083075.4290	J-14S	1.3	Manual T
3082933.0980	J-13S	6.9	Manual T
3082652.6750	J-28S	13	Manual T
3082683.1400	J-26S	2.9	Manual T
3082549.7640	J-25S	13.7	Manual T
3082537.3510	J-27S	6	Manual T
3082605.3190	J-35S	3.1	Manual T
3082548.6880	J-34S	2.4	Manual T
3082667.5270	J-36S	11	Manual T
3082711.0960	J-29S	3.8	Manual T
3082791.3300	J-30S	2.4	Manual T
3082914.1150	J-32S	3.7	Manual T
3082845.8460	J-31S	1.7	Manual T
3082897.2580	J-41S	4.3	Manual T
3082940.9730	J-33S	2	Manual T
3082886.8990	J-40S	1.95	Manual T
3082840.3960	J-39S	2.4	Manual T
3082776.7350	J-38S	5.8	Manual T
3082731.6820	J-37S	12.1	Manual T
	3082781.0290 3082840.1720 3083075.4290 3082933.0980 3082652.6750 3082683.1400 3082549.7640 3082537.3510 3082605.3190 3082548.6880 3082667.5270 3082711.0960 3082791.3300 3082940.9730 3082845.8460 3082897.2580 3082940.9730 3082840.3960 3082776.7350	3082781.0290 J-22S 3082840.1720 J-16S 3083075.4290 J-14S 3082933.0980 J-13S 3082652.6750 J-28S 3082683.1400 J-26S 3082549.7640 J-25S 3082537.3510 J-27S 3082605.3190 J-35S 3082548.6880 J-34S 3082667.5270 J-36S 3082711.0960 J-29S 3082791.3300 J-30S 3082914.1150 J-32S 3082845.8460 J-31S 3082845.8460 J-31S 3082840.9730 J-33S 3082840.9730 J-33S 3082840.3960 J-39S 3082776.7350 J-38S	3082781.0290 J-22S 2.3 3082840.1720 J-16S 4.5 3083075.4290 J-14S 1.3 3082933.0980 J-13S 6.9 3082652.6750 J-28S 13 3082683.1400 J-26S 2.9 3082549.7640 J-25S 13.7 3082537.3510 J-27S 6 3082605.3190 J-35S 3.1 3082548.6880 J-34S 2.4 308267.5270 J-36S 11 3082711.0960 J-29S 3.8 3082791.3300 J-30S 2.4 3082914.1150 J-32S 3.7 3082845.8460 J-31S 1.7 3082897.2580 J-41S 4.3 3082940.9730 J-33S 2 3082886.8990 J-40S 1.95 3082840.3960 J-39S 2.4 3082776.7350 J-38S 5.8

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyta	_	Parameter						
Analyte	n	S Δ α β $Z_{1-\alpha}$ α					Z _{1-β} b	
Vanadium	1 2	3.4 mg/kg	145.507 mg/kg	0.05	0.1	1.64485	1.28155	


 $^{\rm a}$ This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples										
AL 201	014	α=	=5	α=	:10	α=	α=15			
AL=291	.014	s=6.8	s=3.4	s=6.8	s=3.4	s=6.8	s=3.4			
	β=5	2	2	2	1	1	1			
LBGR=90	β=10	2	2	2	1	1	1			
	β=15	2	2	2	1	1	1			
	β=5	2	2	1	1	1	1			
LBGR=80	β=10	2	2	1	1	1	1			
	β=15	2	2	1	1	1	1			
LBGR=70	β=5	2	2	1	1	1	1			

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	2 Samples						
Field collection costs		\$100.00	\$200.00						
Analytical costs	\$400.00	\$400.00	\$800.00						
Sum of Field & Analytical costs		\$500.00	\$1,000.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$2,000.00						

Data Analysis for Vanadium

The following data points were entered by the user for analysis.

	Vanadium (mg/kg)										
Rank	nk 1 2 3 4 5 6 7 8 9 10										
0	0.65	0.77	0.83	0.89	0.95	0.97	1	1.1	1.2	1.3	
10	1.7	1.7	1.8	1.95	2	2.1	2.3	2.4	2.4	2.4	
20	2.9	3.1	3.2	3.6	3.7	3.8	4.3	4.4	4.5	5	
30	5.3	5.7	5.8	6	6.7	6.9	7.1	11	12.1	13	
40	13.7										

SUMMARY STA	SUMMARY STATISTICS for Vanadium							
n	41							
Min	0.65							
Max	13.7							
Range	13.05							
Mean	3.9563							
Median	2.9							
Variance	11.535							
StdDev	3.3963							
Std Error	0.53042							
Skewness	1.5509							

Inte	erquar			4				
Per				centil	es			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.65	0.776	0.902	1.5	2.9	5.5	12.91	13.7	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Vanadium								
k	Test Statistic R _k 5% Critical Value C _k Significant?							
1	2.869	3.05	No					

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Shapiro-Wilk Test Statistic	0.8286					
Shapiro-Wilk 5% Critical Value	0.94					

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Vanadium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the

distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Vanadium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic	0.8131				
Shapiro-Wilk 5% Critical Value	0.941				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	4.849
95% Non-Parametric (Chebyshev) UCL	6.268

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (6.268) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (291.014),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
-541.19	1.6839	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothesis						
41	26	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN						
Primary Objective of Design	Compare a site mean to a fixed threshold						
Type of Sampling Design	Parametric						
Sample Placement (Location) in the Field	Simple random sampling						
Working (Null) Hypothesis	The mean value at the site exceeds the threshold						
Formula for calculating number of sampling locations	Student's t-test						
Calculated total number of samples	2						
Number of samples on map ^a	41						
Number of selected sample areas b	2						
Specified sampling area ^c	188054.34 m ²						
Total cost of sampling d	\$2,000.00						

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Туре	Historical							
679268.7700	3083200.3260	J-11S	0.89	Manual	Т				
679301.1600	3083254.0340	J-12S	0.65	Manual	Т				
679171.2970	3083289.7960	J-04S	1	Manual	Т				
679155.0740	3083294.6960	J-03S	1.7	Manual	Т				
679133.4290	3083306.3130	J-01S	0.97	Manual	Т				
679104.2450	3083223.2620	J-02S	5	Manual	Т				
679164.8060	3083214.7100	J-06S	5.3	Manual	Т				
679181.2750	3083178.2880	J-08S	5.7	Manual	Т				
679213.7730	3083224.9730	J-09S	0.95	Manual	Т				
679280.5440	3083305.6810	J-10S	0.83	Manual	Т				
679242.7260	3083326.5280	J-07S	7.1	Manual	Т				
679225.8560	3083359.9740	J-05S	0.77	Manual	Т				

Area: Area 3										
X Coord Y Coord Label Value Type Histori										
679261.0980	3083016.3510	J-15S	4.4	Manual	Т					
679335.0020	3082941.1720	J-21S	1.1	Manual	Т					
679343.5810	3082969.5980	J-19S	3.2	Manual	Т					
679394.8070	3082971.8300	J-24S	1.2	Manual	Т					
679382.8640	3083009.1130	J-20S	1.8	Manual	Т					
679293.5600	3082950.4980	J-17S	2.1	Manual	Т					
679360.5700	3083026.4980	J-18S	3.6	Manual	Т					

3082840.6970	J-23S	6.7	Manual T
3082781.0290	J-22S	2.3	Manual T
3082840.1720	J-16S	4.5	Manual T
3083075.4290	J-14S	1.3	Manual T
3082933.0980	J-13S	6.9	Manual T
3082652.6750	J-28S	13	Manual T
3082683.1400	J-26S	2.9	Manual T
3082549.7640	J-25S	13.7	Manual T
3082537.3510	J-27S	6	Manual T
3082605.3190	J-35S	3.1	Manual T
3082548.6880	J-34S	2.4	Manual T
3082667.5270	J-36S	11	Manual T
3082711.0960	J-29S	3.8	Manual T
3082791.3300	J-30S	2.4	Manual T
3082914.1150	J-32S	3.7	Manual T
3082845.8460	J-31S	1.7	Manual T
3082897.2580	J-41S	4.3	Manual T
3082940.9730	J-33S	2	Manual T
3082886.8990	J-40S	1.95	Manual T
3082840.3960	J-39S	2.4	Manual T
3082776.7350	J-38S	5.8	Manual T
3082731.6820	J-37S	12.1	Manual T
	3082781.0290 3082840.1720 3083075.4290 3082933.0980 3082652.6750 3082683.1400 3082549.7640 3082537.3510 3082605.3190 3082548.6880 3082667.5270 3082711.0960 3082791.3300 3082940.9730 3082845.8460 3082897.2580 3082940.9730 3082840.3960 3082776.7350	3082781.0290 J-22S 3082840.1720 J-16S 3083075.4290 J-14S 3082933.0980 J-13S 3082652.6750 J-28S 3082683.1400 J-26S 3082549.7640 J-25S 3082537.3510 J-27S 3082605.3190 J-35S 3082548.6880 J-34S 3082667.5270 J-36S 3082711.0960 J-29S 3082791.3300 J-30S 3082914.1150 J-32S 3082845.8460 J-31S 3082845.8460 J-31S 3082840.9730 J-33S 3082840.9730 J-33S 3082840.3960 J-39S 3082776.7350 J-38S	3082781.0290 J-22S 2.3 3082840.1720 J-16S 4.5 3083075.4290 J-14S 1.3 3082933.0980 J-13S 6.9 3082652.6750 J-28S 13 3082683.1400 J-26S 2.9 3082549.7640 J-25S 13.7 3082537.3510 J-27S 6 3082605.3190 J-35S 3.1 3082548.6880 J-34S 2.4 308267.5270 J-36S 11 3082711.0960 J-29S 3.8 3082791.3300 J-30S 2.4 3082914.1150 J-32S 3.7 3082845.8460 J-31S 1.7 3082897.2580 J-41S 4.3 3082940.9730 J-33S 2 3082886.8990 J-40S 1.95 3082840.3960 J-39S 2.4 3082776.7350 J-38S 5.8

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta			Para	amete	r		
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
Vanadium	2	3.4 mg/kg	287.06 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples								
AL 004 044		α=5		α=	α=10		α=15	
AL=291	AL=291.014		s=3.4	s=6.8	s=3.4	s=6.8	s=3.4	
	β=5	2	2	2	1	1	1	
LBGR=90	β=10	2	2	2	1	1	1	
	β=15	2	2	2	1	1	1	
	β=5	2	2	1	1	1	1	
LBGR=80	β=10	2	2	1	1	1	1	
	β=15	2	2	1	1	1	1	
LBGR=70	β=5	2	2	1	1	1	1	

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	2 Samples			
Field collection costs		\$100.00	\$200.00			
Analytical costs	\$400.00	\$400.00	\$800.00			
Sum of Field & Analytical costs		\$500.00	\$1,000.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$2,000.00			

Data Analysis for Vanadium

The following data points were entered by the user for analysis.

Vanadium (mg/kg)										
Rank	1	2	3	4	5	6	7	8	9	10
0	0.65	0.77	0.83	0.89	0.95	0.97	1	1.1	1.2	1.3
10	1.7	1.7	1.8	1.95	2	2.1	2.3	2.4	2.4	2.4
20	2.9	3.1	3.2	3.6	3.7	3.8	4.3	4.4	4.5	5
30	5.3	5.7	5.8	6	6.7	6.9	7.1	11	12.1	13
40	13.7									

SUMMARY STATISTICS for Vanadium				
n	41			
Min	0.65			
Max	13.7			
Range	13.05			
Mean	3.9563			
Median	2.9			
Variance	11.535			
StdDev	3.3963			
Std Error	0.53042			
Skewness	1.5509			

Interquartile Range				4				
Per				centil	es			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.65	0.776	0.902	1.5	2.9	5.5	10.22	12.91	13.7

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Vanadium				
k	Test Statistic R _k	5% Critical Value C _k	Significant?	
1	2.869	3.05	No	

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.8286				
Shapiro-Wilk 5% Critical Value	0.94				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Vanadium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the

distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Vanadium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic 0.8131				
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	4.849
95% Non-Parametric (Chebyshev) UCL	6.268

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (6.268) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (291.014),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic	Critical Value t _{0.95}	Null Hypothesis				
-541.19	1.6839	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+)	95% Critical Value	Null Hypothesis				
41	26	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN								
Primary Objective of Design	Compare a site mean to a fixed threshold							
Type of Sampling Design	Parametric							
Sample Placement (Location) in the Field	Simple random sampling							
Working (Null) Hypothesis	The mean value at the site exceeds the threshold							
Formula for calculating number of sampling locations	Student's t-test							
Calculated total number of samples	23							
Number of samples on map ^a	41							
Number of selected sample areas b	2							
Specified sampling area ^c	188054.34 m ²							
Total cost of sampling d	\$12,500.00							

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1										
X Coord	Y Coord	Label	Value	Туре	Historical					
679133.4290	3083306.3130	J-01S	3010	Manual	Т					
679104.2450	3083223.2620	J-02S	820	Manual	Т					
679155.0740	3083294.6960	J-03S	659.5	Manual	Т					
679171.2970	3083289.7960	J-04S	786	Manual	Т					
679225.8560	3083359.9740	J-05S	1250	Manual	Т					
679164.8060	3083214.7100	J-06S	609	Manual	Т					
679242.7260	3083326.5280	J-07S	2900	Manual	Т					
679181.2750	3083178.2880	J-08S	5020	Manual	Т					
679213.7730	3083224.9730	J-09S	5460	Manual	Т					
679280.5440	3083305.6810	J-10S	1670	Manual	Т					
679268.7700	3083200.3260	J-11S	14300	Manual	Т					
679301.1600	3083254.0340	J-12S	3550	Manual	Т					

Area: Area 3									
X Coord	Y Coord	Label	Value	Туре	Historical				
679149.4920	3082933.0980	J-13S	2590	Manual	Т				
679279.6830	3083075.4290	J-14S	2710	Manual	Т				
679261.0980	3083016.3510	J-15S	1440	Manual	Т				
679222.6340	3082840.1720	J-16S	3680	Manual	Т				
679293.5600	3082950.4980	J-17S	7070	Manual	Т				
679360.5700	3083026.4980	J-18S	3030	Manual	Т				
679343.5810	3082969.5980	J-19S	4375	Manual	Т				

679382.8640 3083009.1130 J-20S 4570 Manual T 679335.0020 3082941.1720 J-21S 4470 Manual T 679252.7130 3082781.0290 J-22S 5620 Manual T 679297.0010 3082840.6970 J-23S 8090 Manual T 679394.8070 3082971.8300 J-24S 2110 Manual T 679146.6460 3082549.7640 J-26S 2540.05 Manual T 679169.0760 3082537.3510 J-27S 2550 Manual T 679169.0760 3082537.3510 J-27S 2550 Manual T 679169.0760 3082537.3510 J-27S 2550 Manual T 679272.0040 3082652.6750 J-28S 5510 Manual T 679374.4420 3082791.3300 J-30S 14400 Manual T 679453.4760 3082941.1150 J-32S 14200 Manual T 679495.8840 <						
679252.71303082781.0290J-22S5620ManualT679297.00103082840.6970J-23S8090ManualT679394.80703082971.8300J-24S2110ManualT679146.64603082549.7640J-25S1105ManualT679224.58503082683.1400J-26S2540.05ManualT679169.07603082537.3510J-27S2550ManualT679272.00403082652.6750J-28S5510ManualT679329.43803082711.0960J-29S12200ManualT679374.44203082791.3300J-30S14400ManualT679453.47603082914.1150J-31S15650ManualT679495.88403082940.9730J-33S2600ManualT679304.65303082548.6880J-34S25400ManualT679382.89003082667.5270J-36S7830ManualT679470.35703082776.7350J-38S9900ManualT679497.33103082840.3960J-39S5110ManualT679524.33103082886.8990J-40S9850ManualT	679382.8640	3083009.1130	J-20S	4570	Manual	Т
679297.0010 3082840.6970 J-23S 8090 Manual T 679394.8070 3082971.8300 J-24S 2110 Manual T 679146.6460 3082549.7640 J-25S 1105 Manual T 679224.5850 3082683.1400 J-26S 2540.05 Manual T 679169.0760 3082537.3510 J-27S 2550 Manual T 679272.0040 3082652.6750 J-28S 5510 Manual T 679329.4380 3082711.0960 J-29S 12200 Manual T 679374.4420 3082791.3300 J-30S 14400 Manual T 679453.4760 3082941.1150 J-31S 15650 Manual T 679495.8840 3082940.9730 J-32S 14200 Manual T 679304.6530 3082548.6880 J-34S 25400 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679470.3570 3082731.6820 J-37S 6190 Manual T 67949	679335.0020	3082941.1720	J-21S	4470	Manual	Т
679394.8070 3082971.8300 J-24S 2110 Manual T 679146.6460 3082549.7640 J-25S 1105 Manual T 679224.5850 3082683.1400 J-26S 2540.05 Manual T 679272.0040 3082537.3510 J-27S 2550 Manual T 679374.4420 3082791.3300 J-28S 5510 Manual T 679374.4420 3082791.3300 J-30S 14400 Manual T 679453.4760 3082914.1150 J-32S 14200 Manual T 679495.8840 3082940.9730 J-33S 2600 Manual T 679304.6530 3082548.6880 J-34S 25400 Manual T 679342.7410 3082605.3190 J-35S 5130 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679470.3570 3082776.7350 J-38S 9900 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679252.7130	3082781.0290	J-22S	5620	Manual	Т
679146.6460 3082549.7640 J-25S 1105 Manual T 679224.5850 3082683.1400 J-26S 2540.05 Manual T 679169.0760 3082537.3510 J-27S 2550 Manual T 679272.0040 3082652.6750 J-28S 5510 Manual T 679329.4380 3082711.0960 J-29S 12200 Manual T 679374.4420 3082791.3300 J-30S 14400 Manual T 679410.1490 3082845.8460 J-31S 15650 Manual T 679453.4760 3082914.1150 J-32S 14200 Manual T 679495.8840 3082940.9730 J-33S 2600 Manual T 679304.6530 3082548.6880 J-34S 25400 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679470.3570 3082776.7350 J-38S 9900 Manual T 679524.3310	679297.0010	3082840.6970	J-23S	8090	Manual	Т
679224.5850 3082683.1400 J-26S 2540.05 Manual T 679169.0760 3082537.3510 J-27S 2550 Manual T 679272.0040 3082652.6750 J-28S 5510 Manual T 679329.4380 3082711.0960 J-29S 12200 Manual T 679374.4420 3082791.3300 J-30S 14400 Manual T 679410.1490 3082845.8460 J-31S 15650 Manual T 679453.4760 3082914.1150 J-32S 14200 Manual T 679495.8840 3082940.9730 J-33S 2600 Manual T 679304.6530 3082548.6880 J-34S 25400 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679433.9450 3082731.6820 J-37S 6190 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310	679394.8070	3082971.8300	J-24S	2110	Manual	Т
679169.0760 3082537.3510 J-27S 2550 Manual T 679272.0040 3082652.6750 J-28S 5510 Manual T 679329.4380 3082711.0960 J-29S 12200 Manual T 679374.4420 3082791.3300 J-30S 14400 Manual T 679410.1490 3082845.8460 J-31S 15650 Manual T 679495.8840 3082914.1150 J-32S 14200 Manual T 679495.8840 3082940.9730 J-33S 2600 Manual T 679304.6530 3082548.6880 J-34S 25400 Manual T 679342.7410 3082605.3190 J-35S 5130 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679470.3570 3082776.7350 J-38S 9900 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679146.6460	3082549.7640	J-25S	1105	Manual	Т
679272.0040 3082652.6750 J-28S 5510 Manual T 679329.4380 3082711.0960 J-29S 12200 Manual T 679374.4420 3082791.3300 J-30S 14400 Manual T 679410.1490 3082845.8460 J-31S 15650 Manual T 679453.4760 3082914.1150 J-32S 14200 Manual T 679495.8840 3082940.9730 J-33S 2600 Manual T 679304.6530 3082548.6880 J-34S 25400 Manual T 679342.7410 3082605.3190 J-35S 5130 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679433.9450 3082731.6820 J-37S 6190 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679224.5850	3082683.1400	J-26S	2540.05	Manual	Т
679329.4380 3082711.0960 J-29S 12200 Manual T 679374.4420 3082791.3300 J-30S 14400 Manual T 679410.1490 3082845.8460 J-31S 15650 Manual T 679495.8840 3082940.9730 J-32S 14200 Manual T 679495.8840 3082940.9730 J-33S 2600 Manual T 679304.6530 3082548.6880 J-34S 25400 Manual T 679342.7410 3082605.3190 J-35S 5130 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679470.3570 3082731.6820 J-37S 6190 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679169.0760	3082537.3510	J-27S	2550	Manual	Т
679374.4420 3082791.3300 J-30S 14400 Manual T 679410.1490 3082845.8460 J-31S 15650 Manual T 679453.4760 3082914.1150 J-32S 14200 Manual T 679495.8840 3082940.9730 J-33S 2600 Manual T 679304.6530 3082548.6880 J-34S 25400 Manual T 679342.7410 3082605.3190 J-35S 5130 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679433.9450 3082731.6820 J-37S 6190 Manual T 679470.3570 3082776.7350 J-38S 9900 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679272.0040	3082652.6750	J-28S	5510	Manual	Т
679410.1490 3082845.8460 J-31S 15650 Manual T 679453.4760 3082914.1150 J-32S 14200 Manual T 679495.8840 3082940.9730 J-33S 2600 Manual T 679304.6530 3082548.6880 J-34S 25400 Manual T 679342.7410 3082605.3190 J-35S 5130 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679433.9450 3082731.6820 J-37S 6190 Manual T 679470.3570 3082776.7350 J-38S 9900 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679329.4380	3082711.0960	J-29S	12200	Manual	Т
679453.4760 3082914.1150 J-32S 14200 Manual T 679495.8840 3082940.9730 J-33S 2600 Manual T 679304.6530 3082548.6880 J-34S 25400 Manual T 679342.7410 3082605.3190 J-35S 5130 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679433.9450 3082731.6820 J-37S 6190 Manual T 679470.3570 3082776.7350 J-38S 9900 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679374.4420	3082791.3300	J-30S	14400	Manual	Т
679495.8840 3082940.9730 J-33S 2600 Manual T 679304.6530 3082548.6880 J-34S 25400 Manual T 679342.7410 3082605.3190 J-35S 5130 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679433.9450 3082731.6820 J-37S 6190 Manual T 679470.3570 3082776.7350 J-38S 9900 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679410.1490	3082845.8460	J-31S	15650	Manual	Т
679304.6530 3082548.6880 J-34S 25400 Manual T 679342.7410 3082605.3190 J-35S 5130 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679433.9450 3082731.6820 J-37S 6190 Manual T 679470.3570 3082776.7350 J-38S 9900 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679453.4760	3082914.1150	J-32S	14200	Manual	Т
679342.7410 3082605.3190 J-35S 5130 Manual T 679382.8900 3082667.5270 J-36S 7830 Manual T 679433.9450 3082731.6820 J-37S 6190 Manual T 679470.3570 3082776.7350 J-38S 9900 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679495.8840	3082940.9730	J-33S	2600	Manual	Т
679382.8900 3082667.5270 J-36S 7830 Manual T 679433.9450 3082731.6820 J-37S 6190 Manual T 679470.3570 3082776.7350 J-38S 9900 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679304.6530	3082548.6880	J-34S	25400	Manual	Т
679433.9450 3082731.6820 J-37S 6190 Manual T 679470.3570 3082776.7350 J-38S 9900 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679342.7410	3082605.3190	J-35S	5130	Manual	Т
679470.3570 3082776.7350 J-38S 9900 Manual T 679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679382.8900	3082667.5270	J-36S	7830	Manual	Т
679497.3310 3082840.3960 J-39S 5110 Manual T 679524.3310 3082886.8990 J-40S 9850 Manual T	679433.9450	3082731.6820	J-37S	6190	Manual	Т
679524.3310 3082886.8990 J-40S 9850 Manual T	679470.3570	3082776.7350	J-38S	9900	Manual	Т
	679497.3310	3082840.3960	J-39S	5110	Manual	Т
679560.6070 3082897.2580 J-41S 4830 Manual T	679524.3310	3082886.8990	J-40S	9850	Manual	Т
	679560.6070	3082897.2580	J-41S	4830	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

S

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter						
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b	
Aluminium	23	5176 mg/kg	3261 mg/kg	0.05	0.1	1.64485	1.28155	


 $^{\rm a}$ This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples									
AL=6521		α=	:5	α=	10	α=	α=15		
		s=10352	s=5176	s=10352	s=5176	s=10352	s=5176		
	β=5	2729	684	2160	541	1813	454		
LBGR=90	β=10	2160	541	1657	415	1355	340		
	β=15	1814	455	1355	340	1084	272		
	β=5	684	172	541	136	454	114		
LBGR=80	β=10	541	137	415	105	340	86		
	β=15	455	115	340	86	272	69		
LBGR=70	β=5	305	78	241	61	202	51		

β=10	242	62	185	47	151	39
β=15	203	52	152	39	121	31

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$12,500.00, which averages out to a per sample cost of \$543.48. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	23 Samples						
Field collection costs		\$100.00	\$2,300.00						
Analytical costs	\$400.00	\$400.00	\$9,200.00						
Sum of Field & Analytical costs		\$500.00	\$11,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$12,500.00						

Data Analysis for Aluminium

The following data points were entered by the user for analysis.

	Aluminium (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	609	659.5	786	820	1105	1250	1440	1670	2110	2540
10	2550	2590	2600	2710	2900	3010	3030	3550	3680	4375
20	4470	4570	4830	5020	5110	5130	5460	5510	5620	6190
30	7070	7830	8090	9850	9900	1.22e+004	1.42e+004	1.43e+004	1.44e+004	1.565e+004
40	2.54e+004									

SUMMARY STATISTICS for Aluminium					
n	41				
Min	609				
Max	25400				
Range	24791 5726.5 4470				
Mean					
Median					
Variance	2.6787e+007				
StdDev	5175.7				
Std Error	808.3				
Skewness	1.857				

Interquartile Range				4905				
					Perce	ntiles		
1%	5%	10%	25%	50%	75%	90%	95%	99%
609	672.1	877	2545	4470	7450	1.428e+004	1.552e+004	2.54e+004

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Aluminium						
k	Test Statistic R _k	5% Critical Value C _k	Significant?			
1	3.801	3.05	Yes			

The test statistic 3.801 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS for Aluminium				
1	25400			

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Shapiro-Wilk Test Statistic	0.8538					
Shapiro-Wilk 5% Critical Value	0.94					

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Aluminium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Aluminium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST						
Shapiro-Wilk Test Statistic	0.8145					
Shapiro-Wilk 5% Critical Value	0.941					

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	7088			
95% Non-Parametric (Chebyshev) UCL	9250			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (9250) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{\Im E}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (6521),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic	Critical Value t _{0.95}	Null Hypothesis				
-0.98298	1.6839	Cannot Reject				

The test did not reject the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean exceeds the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+)	95% Critical Value	Null Hypothesis				
30	26	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	365
Number of samples on map ^a	365
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$183,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1- β) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:


Analysta	_	Parameter					
Analyte	11	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
Aluminium	365	5176 mg/kg	795 mg/kg	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



b This value is automatically calculated by VSP based upon the user defined value of β.

Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples							
AL=6521		α=5		α=10		α=15	
		s=10352	s=5176	s=10352	s=5176	s=10352	s=5176
	β=5	2729	684	2160	541	1813	454
LBGR=90	β=10	2160	541	1657	415	1355	340
	β=15	1814	455	1355	340	1084	272
	β=5	684	172	541	136	454	114
LBGR=80	β=10	541	137	415	105	340	86
	β=15	455	115	340	86	272	69
	β=5	305	78	241	61	202	51
LBGR=70	β=10	242	62	185	47	151	39
	β=15	203	52	152	39	121	31

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$183,500.00, which averages out to a per sample cost of \$502.74. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION							
Cost Details Per Analysis Per Sample 365 Sample							
Field collection costs		\$100.00	\$36,500.00				
Analytical costs	\$400.00	\$400.00	\$146,000.00				
Sum of Field & Analytical costs		\$500.00	\$182,500.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$183,500.00				

	SUMMARY STATISTICS for Aluminium							
n						3	65	
	М	in			0			
	M	ах			25400			
	Rai	nge				25	400	
	Me	an				11	76.8	
	Мес	dian					0	
Variance				1.107	3e+00	7		
	Std	Dev				33	27.6	
	Std I	Error				17	4.17	
	Skew	ness				4.0	233	
Inte	erquar	tile Ra	nge				0	
Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0	0	0	0	0	4570	7830	1.565e+004

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Aluminium					
k Test Statistic R _k 5% Critical Value C _k Significant?					
1	3.801	3.05	Yes		

The test statistic 3.801 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS for Aluminium				
1	25400			

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Lilliefors Test Statistic	0.8538				
Lilliefors 5% Critical Value	0.94				

The calculated Lilliefors test statistic is less than the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed

data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots for Aluminium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Aluminium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Lilliefors Test Statistic	0.4464			
Lilliefors 5% Critical Value	0.04638			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	1464			
95% Non-Parametric (Chebyshev) UCL	1936			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (1936) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{\Im F}$$

where

x is the sample mean of the n=365 data, AL is the action level or threshold (6521),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=364 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST			
t-statistic Critical Value t _{0.95} Null Hypothesis			
-30.683	1.6491	Reject	

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.


Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:


MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
344	199	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1. Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.





Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN				
Primary Objective of Design	Compare a site mean to a fixed threshold				
Type of Sampling Design	Parametric				
Sample Placement (Location) in the Field	Simple random sampling				
Working (Null) Hypothesis	The mean value at the site exceeds the threshold				
Formula for calculating number of sampling locations	Student's t-test				
Calculated total number of samples	11				
Number of samples on map ^a	41				
Number of selected sample areas b	2				
Specified sampling area ^c	188054.34 m ²				
Total cost of sampling d	\$6,500.00				

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1							
X Coord	Y Coord	Label	Value	Туре	Historical		
679268.7700	3083200.3260	J-11S	2.6	Manual	Т		
679301.1600	3083254.0340	J-12S	0.57	Manual	Т		
679171.2970	3083289.7960	J-04S	0.23	Manual	Т		
679155.0740	3083294.6960	J-03S	0.115	Manual	Т		
679133.4290	3083306.3130	J-01S	0.51	Manual	Т		
679104.2450	3083223.2620	J-02S	0.09	Manual	Т		
679164.8060	3083214.7100	J-06S	0.12	Manual	Т		
679181.2750	3083178.2880	J-08S	0.83	Manual	Т		
679213.7730	3083224.9730	J-09S	1.2	Manual	Т		
679280.5440	3083305.6810	J-10S	0.31	Manual	Т		
679242.7260	3083326.5280	J-07S	2	Manual	Т		
679225.8560	3083359.9740	J-05S	0.29	Manual	Т		

Area: Area 3						
X Coord	Y Coord	Label	Value	Туре	Historical	
679261.0980	3083016.3510	J-15S	2.6	Manual	Т	
679335.0020	3082941.1720	J-21S	0.93	Manual	Т	
679343.5810	3082969.5980	J-19S	1.8	Manual	Т	
679394.8070	3082971.8300	J-24S	0.35	Manual	Т	
679382.8640	3083009.1130	J-20S	0.86	Manual	Т	
679293.5600	3082950.4980	J-17S	2	Manual	Т	
679360.5700	3083026.4980	J-18S	0.58	Manual	Т	

679297.0010 3082840.6970 J-23S 1.7 Manual T 679252.7130 3082781.0290 J-22S 1.035 Manual T 679222.6340 3082840.1720 J-16S 0.72 Manual T 679279.6830 3083075.4290 J-14S 0.66 Manual T 679149.4920 3082933.0980 J-13S 0.22 Manual T 679272.0040 3082652.6750 J-28S 1.1 Manual T 679224.5850 3082683.1400 J-26S 0.27805 Manual T 679146.6460 3082549.7640 J-25S 0.305 Manual T 679169.0760 3082537.3510 J-27S 0.53 Manual T 679342.7410 3082605.3190 J-35S 2 Manual T 679382.8900 3082548.6880 J-34S 3 Manual T 679329.4380 3082711.0960 J-29S 1.3 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679450.6070					
679222.6340 3082840.1720 J-16S 0.72 Manual T 679279.6830 3083075.4290 J-14S 0.66 Manual T 679149.4920 3082933.0980 J-13S 0.22 Manual T 679272.0040 3082652.6750 J-28S 1.1 Manual T 679224.5850 3082683.1400 J-26S 0.27805 Manual T 679146.6460 3082549.7640 J-25S 0.305 Manual T 679169.0760 3082537.3510 J-27S 0.53 Manual T 679342.7410 3082605.3190 J-35S 2 Manual T 679382.8900 3082548.6880 J-34S 3 Manual T 679329.4380 3082711.0960 J-29S 1.3 Manual T 679453.4760 3082914.1150 J-30S 3.1 Manual T 679460.6070 3082845.8460 J-31S 1.6 Manual T 679495.8840 3082940.	679297.0010	3082840.6970	J-23S	1.7	Manual T
679279.6830 3083075.4290 J-14S 0.66 Manual T 679149.4920 3082933.0980 J-13S 0.22 Manual T 679272.0040 3082652.6750 J-28S 1.1 Manual T 679224.5850 3082683.1400 J-26S 0.27805 Manual T 679146.6460 3082549.7640 J-25S 0.305 Manual T 679169.0760 3082537.3510 J-27S 0.53 Manual T 679342.7410 3082605.3190 J-35S 2 Manual T 679304.6530 3082548.6880 J-34S 3 Manual T 679382.8900 3082667.5270 J-36S 1.45 Manual T 679374.4420 3082791.3300 J-29S 1.3 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679560.6070 3082845.8460 J-31S 1.6 Manual T 679524.3310 3082886.	679252.7130	3082781.0290	J-22S	1.035	Manual T
679149.4920 3082933.0980 J-13S 0.22 Manual T 679272.0040 3082652.6750 J-28S 1.1 Manual T 679224.5850 3082683.1400 J-26S 0.27805 Manual T 679146.6460 3082549.7640 J-25S 0.305 Manual T 679169.0760 3082537.3510 J-27S 0.53 Manual T 679342.7410 3082605.3190 J-35S 2 Manual T 679304.6530 3082548.6880 J-34S 3 Manual T 679382.8900 3082667.5270 J-36S 1.45 Manual T 679374.4420 3082711.0960 J-29S 1.3 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679470.1490 3082845.8460 J-31S 1.6 Manual T 679495.8840 3082940.9730 J-33S 1.4 Manual T 679497.3310 3082886.8	679222.6340	3082840.1720	J-16S	0.72	Manual T
679272.0040 3082652.6750 J-28S 1.1 Manual T 679224.5850 3082683.1400 J-26S 0.27805 Manual T 679146.6460 3082549.7640 J-25S 0.305 Manual T 679169.0760 3082537.3510 J-27S 0.53 Manual T 679342.7410 3082605.3190 J-35S 2 Manual T 679304.6530 3082548.6880 J-34S 3 Manual T 679382.8900 3082667.5270 J-36S 1.45 Manual T 679329.4380 3082711.0960 J-29S 1.3 Manual T 679374.4420 3082791.3300 J-30S 3.1 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679460.6070 3082845.8460 J-31S 1.6 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570	679279.6830	3083075.4290	J-14S	0.66	Manual T
679224.5850 3082683.1400 J-26S 0.27805 Manual T 679146.6460 3082549.7640 J-25S 0.305 Manual T 679169.0760 3082537.3510 J-27S 0.53 Manual T 679342.7410 3082605.3190 J-35S 2 Manual T 679304.6530 3082548.6880 J-34S 3 Manual T 679382.8900 3082667.5270 J-36S 1.45 Manual T 679329.4380 3082711.0960 J-29S 1.3 Manual T 679374.4420 3082791.3300 J-30S 3.1 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679410.1490 3082845.8460 J-31S 1.6 Manual T 679495.8840 3082940.9730 J-31S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679470.3570 3082776.73	679149.4920	3082933.0980	J-13S	0.22	Manual T
679146.6460 3082549.7640 J-25S 0.305 Manual T 679169.0760 3082537.3510 J-27S 0.53 Manual T 679342.7410 3082605.3190 J-35S 2 Manual T 679304.6530 3082548.6880 J-34S 3 Manual T 679382.8900 3082667.5270 J-36S 1.45 Manual T 679329.4380 3082711.0960 J-29S 1.3 Manual T 679374.4420 3082791.3300 J-30S 3.1 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679410.1490 3082845.8460 J-31S 1.6 Manual T 679560.6070 3082897.2580 J-41S 1.3 Manual T 679495.8840 3082940.9730 J-33S 1.4 Manual T 679497.3310 3082886.8990 J-40S 2.8 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679272.0040	3082652.6750	J-28S	1.1	Manual T
679169.0760 3082537.3510 J-27S 0.53 Manual T 679342.7410 3082605.3190 J-35S 2 Manual T 679304.6530 3082548.6880 J-34S 3 Manual T 679382.8900 3082667.5270 J-36S 1.45 Manual T 679329.4380 3082711.0960 J-29S 1.3 Manual T 679374.4420 3082791.3300 J-30S 3.1 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679410.1490 3082845.8460 J-31S 1.6 Manual T 679560.6070 3082897.2580 J-41S 1.3 Manual T 679495.8840 3082940.9730 J-33S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679224.5850	3082683.1400	J-26S	0.27805	Manual T
679342.7410 3082605.3190 J-35S 2 Manual T 679304.6530 3082548.6880 J-34S 3 Manual T 679382.8900 3082667.5270 J-36S 1.45 Manual T 679329.4380 3082711.0960 J-29S 1.3 Manual T 679374.4420 3082791.3300 J-30S 3.1 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679410.1490 3082845.8460 J-31S 1.6 Manual T 679560.6070 3082897.2580 J-41S 1.3 Manual T 679495.8840 3082940.9730 J-33S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679146.6460	3082549.7640	J-25S	0.305	Manual T
679304.6530 3082548.6880 J-34S 3 Manual T 679382.8900 3082667.5270 J-36S 1.45 Manual T 679329.4380 3082711.0960 J-29S 1.3 Manual T 679374.4420 3082791.3300 J-30S 3.1 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679410.1490 3082845.8460 J-31S 1.6 Manual T 679560.6070 3082897.2580 J-41S 1.3 Manual T 679495.8840 3082940.9730 J-33S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679169.0760	3082537.3510	J-27S	0.53	Manual T
679382.8900 3082667.5270 J-36S 1.45 Manual T 679329.4380 3082711.0960 J-29S 1.3 Manual T 679374.4420 3082791.3300 J-30S 3.1 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679410.1490 3082845.8460 J-31S 1.6 Manual T 679560.6070 3082897.2580 J-41S 1.3 Manual T 679495.8840 3082940.9730 J-33S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679342.7410	3082605.3190	J-35S	2	Manual T
679329.4380 3082711.0960 J-29S 1.3 Manual T 679374.4420 3082791.3300 J-30S 3.1 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679410.1490 3082845.8460 J-31S 1.6 Manual T 679560.6070 3082897.2580 J-41S 1.3 Manual T 679495.8840 3082940.9730 J-33S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679304.6530	3082548.6880	J-34S	3	Manual T
679374.4420 3082791.3300 J-30S 3.1 Manual T 679453.4760 3082914.1150 J-32S 2.5 Manual T 679410.1490 3082845.8460 J-31S 1.6 Manual T 679560.6070 3082897.2580 J-41S 1.3 Manual T 679495.8840 3082940.9730 J-33S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679382.8900	3082667.5270	J-36S	1.45	Manual T
679453.4760 3082914.1150 J-32S 2.5 Manual T 679410.1490 3082845.8460 J-31S 1.6 Manual T 679560.6070 3082897.2580 J-41S 1.3 Manual T 679495.8840 3082940.9730 J-33S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679329.4380	3082711.0960	J-29S	1.3	Manual T
679410.1490 3082845.8460 J-31S 1.6 Manual T 679560.6070 3082897.2580 J-41S 1.3 Manual T 679495.8840 3082940.9730 J-33S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679374.4420	3082791.3300	J-30S	3.1	Manual T
679560.6070 3082897.2580 J-41S 1.3 Manual T 679495.8840 3082940.9730 J-33S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679453.4760	3082914.1150	J-32S	2.5	Manual T
679495.8840 3082940.9730 J-33S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679410.1490	3082845.8460	J-31S	1.6	Manual T
679524.3310 3082886.8990 J-40S 2.8 Manual T 679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679560.6070	3082897.2580	J-41S	1.3	Manual T
679497.3310 3082840.3960 J-39S 1.5 Manual T 679470.3570 3082776.7350 J-38S 2.4 Manual T	679495.8840	3082940.9730	J-33S	1.4	Manual T
679470.3570 3082776.7350 J-38S 2.4 Manual T	679524.3310	3082886.8990	J-40S	2.8	Manual T
	679497.3310	3082840.3960	J-39S	1.5	Manual T
670433 0450 3082731 6820 L37S 2.2 Manual T	679470.3570	3082776.7350	J-38S	2.4	Manual T
07 9433.9430 3002731.0020 3-373 2.2 Wallual 1	679433.9450	3082731.6820	J-37S	2.2	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

S

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

 λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyta	_		Pa	ramet	ter		
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z_{1-β} b
Arsenic	11	0.9 mg/kg	0.86 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples								
AL 0.0	20	α=	: 5	α=	10	α=15		
AL=0.3	9	s=1.8	s=0.9	s=1.8	s=0.9	s=1.8	s=0.9	
	β=5	23055	5765	18244	4562	15316	3830	
LBGR=90	β=10	18244	4562	13996	3500	11447	2862	
	β=15	15316	3830	11447	2863	9154	2289	
	β=5	5765	1443	4562	1141	3830	958	
LBGR=80	β=10	4562	1142	3500	876	2862	716	
	β=15	3830	959	2863	717	2289	573	
LBGR=70	β=5	2563	642	2028	508	1703	426	

β=10	2029	509	1556	390	1273	319
β=15	1703	427	1273	319	1018	255

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$6,500.00, which averages out to a per sample cost of \$590.91. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	11 Samples			
Field collection costs		\$100.00	\$1,100.00			
Analytical costs	\$400.00	\$400.00	\$4,400.00			
Sum of Field & Analytical costs		\$500.00	\$5,500.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$6,500.00			

Data Analysis for Arsenic

The following data points were entered by the user for analysis.

	Arsenic (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	0.09	0.115	0.12	0.22	0.23	0.2781	0.29	0.305	0.31	0.35
10	0.51	0.53	0.57	0.58	0.66	0.72	0.83	0.86	0.93	1.035
20	1.1	1.2	1.3	1.3	1.4	1.45	1.5	1.6	1.7	1.8
30	2	2	2	2.2	2.4	2.5	2.6	2.6	2.8	3
40	3.1									

SUMMARY STATISTICS for Arsenic				
n	41			
Min	0.09			
Max	3.1			
Range	3.01			
Mean	1.2459			
Median	1.1			
Variance	0.80844			
StdDev	0.89913			
Std Error	0.14042			
Skewness	0.50263			

Interquartile Range				1.57				
		Perce	entile	S				
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.09	0.1155	0.222	0.43	1.1	2	2.6	2.98	3.1

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Arsenic					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	2.062	3.05	No		

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION T	EST (excluding outliers)
Shapiro-Wilk Test Statistic	0.9198
Shapiro-Wilk 5% Critical Value	0.94

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Arsenic


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the

distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Arsenic

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.9178			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	1.482
95% Non-Parametric (Chebyshev) UCL	1.858

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (1.858) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (0.39),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic	Critical Value t _{0.95}	Null Hypothesis			
6.0954	1.6839	Cannot Reject			

The test did not reject the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean exceeds the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothe					
10	26	Cannot Reject			

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced * by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field is also provided below.

SUMMARY OF SAMPLING DESIGN				
Primary Objective of Design	Compare a site mean to a fixed threshold			
Type of Sampling Design	Parametric			
Sample Placement (Location) in the Field	Simple random sampling			
Working (Null) Hypothesis	The mean value at the site exceeds the threshold			
Formula for calculating number of sampling locations	Student's t-test			
Calculated total number of samples	741			
Number of samples on map ^a	741			
Number of selected sample areas b	2			
Specified sampling area ^c	188054.34 m ²			
Total cost of sampling d	\$371,500.00			

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:


Analysta	_		Paran	neter			
Analyte	n	S	Δ	α	β	Ζ _{1-α} ^a	Z _{1-β} b
Benzo(a)Anthracene	741	0.6855 mg/kg	0.0738 mg/kg	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



b This value is automatically calculated by VSP based upon the user defined value of β.

Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

	Number of Samples						
AL=0.1476		α=5		α=	=10	α=15	
		s=1.371	s=1.371 s=0.6855 s=1.371 s=0.6855		s=1.371	s=0.6855	
	β=5	93374	23345	73889	18473	62029	15508
LBGR=90	β=10	73889	18474	56682	14171	46359	11591
	β=15	62030	15509	46359	11591	37073	9269
	β=5	23345	5838	18473	4619	15508	3878
LBGR=80	β=10	18474	4620	14171	3544	11591	2898
	β=15	15509	3879	11591	2899	9269	2318
	β=5	10377	2596	8211	2054	6893	1724
LBGR=70	β=10	8212	2054	6299	1576	5152	1289
	β=15	6894	1725	5152	1289	4120	1031

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$371,500.00, which averages out to a per sample cost of \$501.35. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION							
Cost Details	Per Analysis	Per Sample	741 Samples				
Field collection costs		\$100.00	\$74,100.00				
Analytical costs	\$400.00	\$400.00	\$296,400.00				
Sum of Field & Analytical costs		\$500.00	\$370,500.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$371,500.00				

	SUMMARY STATISTICS for Benzo(a)Anthracene							пе
		n				741		
	N	lin				0		
	M	lax				3.97		
	Ra	nge				3.97		
	M	ean				0.0170	23	
Median					0			
Variance			0.029269					
StdDev				0.17108				
	Std	Error		0.0062848				
	Skev	vness		19.238				
Int	terquar	tile Ra	nge			0		
			Р	ercent	iles			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0	0	0	0	0	0	0.039	0.3816

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Benzo(a)Anthracene					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	23.11	3.943	Yes		

The test statistic 23.11 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS for Benzo(a)Anthracer				
1	3.97			

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Lilliefors Test Statistic	0.4583				
Lilliefors 5% Critical Value	0.03257				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not

justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots for Benzo(a)Anthracene


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Benzo(a)Anthracene

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBU	TION TEST
Lilliefors Test Statistic	0.4604
Lilliefors 5% Critical Value	0.03255

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.02737
95% Non-Parametric (Chebyshev) UCL	0.04442

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.04442) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=741 data, AL is the action level or threshold (0.1476),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=740 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic	Critical Value t _{0.95}	Null Hypothesis			
-20.777	1.6469	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothes						
729	393	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1. Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold				
Type of Sampling Design	Parametric				
Sample Placement (Location) in the Field	Simple random sampling				
Working (Null) Hypothesis	The mean value at the site exceeds the threshold				
Formula for calculating number of sampling locations	Student's t-test				
Calculated total number of samples	430				
Number of samples on map ^a	430				
Number of selected sample areas b	2				
Specified sampling area ^c	188054.34 m ²				
Total cost of sampling d	\$216,000.00				

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:


Analyto		Parameter					
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
Benzo(a)Anthracene	430	0.6855 mg/kg	0.097 mg/kg	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



b This value is automatically calculated by VSP based upon the user defined value of β.

Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples							
AL=0.1476		α=5		α=	=10	α=15	
		s=1.371	s=0.6855	s=1.371	s=0.6855	s=1.371	s=0.6855
	β=5	93374	23345	73889	18473	62029	15508
LBGR=90	β=10	73889	18474	56682	14171	46359	11591
	β=15	62030	15509	46359	11591	37073	9269
	β=5	23345	5838	18473	4619	15508	3878
LBGR=80	β=10	18474	4620	14171	3544	11591	2898
	β=15	15509	3879	11591	2899	9269	2318
	β=5	10377	2596	8211	2054	6893	1724
LBGR=70	β=10	8212	2054	6299	1576	5152	1289
	β=15	6894	1725	5152	1289	4120	1031

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$216,000.00, which averages out to a per sample cost of \$502.33. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	430 Samples					
Field collection costs		\$100.00	\$43,000.00					
Analytical costs	\$400.00	\$400.00	\$172,000.00					
Sum of Field & Analytical costs		\$500.00	\$215,000.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$216,000.00					

	SUMMARY STATISTICS for Benzo(a)Anthracene							
	ļ	n		430				
	M	lin				0		
	М	ах				3.97		
	Ra	nge				3.97		
	Ме	ean			(0.02933	35	
Median				0				
Variance			0.050125					
	StdDev				0.22389			
	Std	Error		0.010797				
	Skev	ness		14.67				
In	Interquartile Range					0		
			Р	ercenti	iles			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0	0	0	0	0	0.038	0.042	0.3975

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Benzo(a)Anthracene						
k	Test Statistic R _k	5% Critical Value C _k	Significant?			
1	5.434	3.05	Yes			

The test statistic 5.434 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS	for Benzo(a)Anthracene
1	3.97

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Lilliefors Test Statistic	0.3865				
Lilliefors 5% Critical Value	0.94				

The calculated Lilliefors test statistic is less than the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed

data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots for Benzo(a)Anthracene


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Benzo(a)Anthracene

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Lilliefors Test Statistic	0.4479			
Lilliefors 5% Critical Value	0.04273			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.04713
95% Non-Parametric (Chebyshev) UCL	0.0764

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.0764) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{\Im F}$$

where

is the sample mean of the n=430 data,

AL is the action level or threshold (0.1476),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=429 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-10.954	1.6484	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
418	233	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF SAMPLING DESIGN				
Primary Objective of Design	Compare a site mean to a fixed threshold			
Type of Sampling Design	Parametric			
Sample Placement (Location) in the Field	Simple random sampling			
Working (Null) Hypothesis	The mean value at the site exceeds the threshold			
Formula for calculating number of sampling locations	Student's t-test			
Calculated total number of samples	5055			
Number of samples on map ^a	5055			
Number of selected sample areas b	2			
Specified sampling area ^c	188054.34 m ²			
Total cost of sampling d	\$2,528,500.00			

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:


Analysta	_		Param	eter			
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
Benzo(a)Pyrene	5055	0.17975 mg/kg	0.0074 mg/kg	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



b This value is automatically calculated by VSP based upon the user defined value of β.

Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

	Number of Samples						
AL=0.0148		α=5		α=10		α=15	
		s=0.3595	s=0.17975	s=0.3595 s=0.17975		s=0.3595	s=0.17975
	β=5	638543	159637	505294	126325	424192	106049
LBGR=90	β=10	505295	126325	387622	96906	317028	79258
	β=15	424192	106049	317028	79258	253524	63382
	β=5	159637	39911	126325	31582	106049	26513
LBGR=80	β=10	126325	31583	96906	24228	79258	19815
	β=15	106049	26514	79258	19815	63382	15846
	β=5	70951	17739	56145	14037	47133	11784
LBGR=70	β=10	56146	14038	43070	10769	35226	8807
	β=15	47134	11785	35226	8808	28170	7043

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,528,500.00, which averages out to a per sample cost of \$500.20. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	5055 Samples		
Field collection costs		\$100.00	\$505,500.00		
Analytical costs	\$400.00	\$400.00	\$2,022,000.00		
Sum of Field & Analytical costs		\$500.00	\$2,527,500.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$2,528,500.00		

SUMMARY STATISTICS for Benzo(a)Pyrene								
	ı	n				5055		
	М	in		0				
	М	ах				0.775		
	Rai	nge				0.775		
	Мє	ean		0.0013544				
	Median				0			
	Variance				0.00044949			
	Std	Dev		0.021201				
	Std	0.00029819						
	Skew	ness				25.653	3	
Inte	Interquartile Range					0		
	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0	0	0	0	0	0	0	0.033

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Benzo(a)Pyrene					
k Test Statistic R _k 5% Critical Value C _k Significant?					
1	3.686	3.05	Yes		

The test statistic 3.686 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS for Benzo(a)Pyrene				
1	0.775			

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Lilliefors Test Statistic	0.5104			
Lilliefors 5% Critical Value	0.94			

The calculated Lilliefors test statistic is less than the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed

data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots for Benzo(a)Pyrene


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Benzo(a)Pyrene

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST			
Lilliefors Test Statistic	0.5116		
Lilliefors 5% Critical Value	0.01246		

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN			
95% Parametric UCL	0.001845		
95% Non-Parametric (Chebyshev) UCL	0.002654		

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.002654) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=5055 data, AL is the action level or threshold (0.0148).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=5054 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic	Critical Value t _{0.95}	Null Hypothesis					
-45.09	1.6452	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+)	95% Critical Value	Null Hypothesis				
4985	2586	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1. Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN							
Primary Objective of Design	Compare a site mean to a fixed threshold						
Type of Sampling Design	Parametric						
Sample Placement (Location) in the Field	Simple random sampling						
Working (Null) Hypothesis	The mean value at the site exceeds the threshold						
Formula for calculating number of sampling locations	Student's t-test						
Calculated total number of samples	31						
Number of samples on map ^a	41						
Number of selected sample areas b	2						
Specified sampling area ^c	188054.34 m ²						
Total cost of sampling d	\$16,500.00						

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1								
X Coord	Y Coord	Label	Value	Туре	Historical			
679268.7700	3083200.3260	J-11S	0.036	Manual	Т			
679301.1600	3083254.0340	J-12S	0.172	Manual	Т			
679171.2970	3083289.7960	J-04S	0.766	Manual	Т			
679155.0740	3083294.6960	J-03S	0.1025	Manual	Т			
679133.4290	3083306.3130	J-01S	0.037	Manual	Т			
679104.2450	3083223.2620	J-02S	0.031	Manual	Т			
679164.8060	3083214.7100	J-06S	0.03275	Manual	Т			
679181.2750	3083178.2880	J-08S	0.032	Manual	Т			
679213.7730	3083224.9730	J-09S	0.775	Manual	Т			
679280.5440	3083305.6810	J-10S	0.0325	Manual	Т			
679242.7260	3083326.5280	J-07S	0.325	Manual	Т			
679225.8560	3083359.9740	J-05S	0.035	Manual	Т			

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			
679261.0980	3083016.3510	J-15S	0.033	Manual	Т			
679335.0020	3082941.1720	J-21S	0.34	Manual	Т			
679343.5810	3082969.5980	J-19S	0.3475	Manual	Т			
679394.8070	3082971.8300	J-24S	0.315	Manual	Т			
679382.8640	3083009.1130	J-20S	0.31	Manual	Т			
679293.5600	3082950.4980	J-17S	0.0355	Manual	Т			
679360.5700	3083026.4980	J-18S	0.034	Manual	Т			

679297.00103082840.6970J-23S0.0315ManualT679252.71303082781.0290J-22S0.03275ManualT679222.63403082840.1720J-16S0.0335ManualT679279.68303083075.4290J-14S0.0985ManualT679149.49203082933.0980J-13S0.0325ManualT679272.00403082652.6750J-28S0.035ManualT679146.64603082549.7640J-26S0.03325ManualT679169.07603082537.3510J-27S0.0345ManualT679342.74103082605.3190J-35S0.0335ManualT679304.65303082548.6880J-34S0.0485ManualT679329.43803082711.0960J-29S0.035ManualT679374.44203082791.3300J-30S0.0375ManualT679453.47603082914.1150J-32S0.037ManualT679410.14903082845.8460J-31S0.03375ManualT679495.88403082940.9730J-33S0.0325ManualT679497.33103082886.8990J-40S0.0335ManualT679470.35703082776.7350J-38S0.0315ManualT679433.94503082731.6820J-37S0.0315ManualT						
679222.6340 3082840.1720 J-16S 0.0335 Manual T 679279.6830 3083075.4290 J-14S 0.0985 Manual T 679149.4920 3082933.0980 J-13S 0.0325 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679224.5850 3082683.1400 J-26S 0.03325 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679382.8900 3082548.6880 J-34S 0.0485 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679473.4760 3082914.1150 J-30S 0.0375 Manual T 679470.1490 3082845.8460 J-31S 0.03375 Manual T 679495.8	679297.0010	3082840.6970	J-23S	0.0315	Manual	Т
679279.6830 3083075.4290 J-14S 0.0985 Manual T 679149.4920 3082933.0980 J-13S 0.0325 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679224.5850 3082683.1400 J-26S 0.03325 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679374.4420 3082791.3300 J-29S 0.033 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679560.6070 3082845.8460 J-31S 0.03375 Manual T 679524.331	679252.7130	3082781.0290	J-22S	0.03275	Manual	Т
679149.4920 3082933.0980 J-13S 0.0325 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679224.5850 3082683.1400 J-26S 0.03325 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679374.4420 3082711.0960 J-29S 0.033 Manual T 679453.4760 3082914.1150 J-30S 0.0375 Manual T 679460.6070 3082845.8460 J-31S 0.0375 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679497.331	679222.6340	3082840.1720	J-16S	0.0335	Manual	Т
679272.0040 3082652.6750 J-28S 0.035 Manual T 679224.5850 3082683.1400 J-26S 0.03325 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679490.6070 3082845.8460 J-31S 0.0375 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679497.3310	679279.6830	3083075.4290	J-14S	0.0985	Manual	Т
679224.5850 3082683.1400 J-26S 0.03325 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679410.1490 3082845.8460 J-31S 0.0375 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679470.357	679149.4920	3082933.0980	J-13S	0.0325	Manual	Т
679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679495.8840 3082940.9730 J-31S 0.0325 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570	679272.0040	3082652.6750	J-28S	0.035	Manual	Т
679169.0760 3082537.3510 J-27S 0.0345 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570<	679224.5850	3082683.1400	J-26S	0.03325	Manual	Т
679342.7410 3082605.3190 J-35S 0.0335 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T	679146.6460	3082549.7640	J-25S	0.035	Manual	Т
679304.6530 3082548.6880 J-34S 0.0485 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T	679169.0760	3082537.3510	J-27S	0.0345	Manual	Т
679382.8900 3082667.5270 J-36S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T	679342.7410	3082605.3190	J-35S	0.0335	Manual	Т
679329.4380 3082711.0960 J-29S 0.033 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T	679304.6530	3082548.6880	J-34S	0.0485	Manual	Т
679374.4420 3082791.3300 J-30S 0.0375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T	679382.8900	3082667.5270	J-36S	0.035	Manual	Т
679453.4760 3082914.1150 J-32S 0.037 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T	679329.4380	3082711.0960	J-29S	0.033	Manual	Т
679410.1490 3082845.8460 J-31S 0.03375 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T	679374.4420	3082791.3300	J-30S	0.0375	Manual	Т
679560.6070 3082897.2580 J-41S 0.03 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T	679453.4760	3082914.1150	J-32S	0.037	Manual	Т
679495.8840 3082940.9730 J-33S 0.0325 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T	679410.1490	3082845.8460	J-31S	0.03375	Manual	Т
679524.3310 3082886.8990 J-40S 0.0335 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T	679560.6070	3082897.2580	J-41S	0.03	Manual	Т
679497.3310 3082840.3960 J-39S 0.036 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T	679495.8840	3082940.9730	J-33S	0.0325	Manual	Т
679470.3570 3082776.7350 J-38S 0.0315 Manual T	679524.3310	3082886.8990	J-40S	0.0335	Manual	Т
	679497.3310	3082840.3960	J-39S	0.036	Manual	Т
679433.9450 3082731.6820 J-37S 0.0315 Manual T	679470.3570	3082776.7350	J-38S	0.0315	Manual	Т
	679433.9450	3082731.6820	J-37S	0.0315	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability (1-β) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error, S

is the width of the gray region.

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}^{\alpha}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:


Analysta	_		Parameter				
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
Benzo(a)Pyrene	31	0.18 mg/kg	0.0976756 mg/kg	0.05	0.1	1.64485	1.28155

 a This value is automatically calculated by VSP based upon the user defined value of α . This value is automatically calculated by VSP based upon the user defined value of β .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples							
A1 0.0	1.40	α=5		α=	10	α=15	
AL=0.0	140	s=0.36	s=0.18	s=0.36	s=0.18	s=0.36	s=0.18
	β=5	640320	160081	506701	126676	425372	106344
LBGR=90	β=10	506701	126677	388701	97176	317910	79478
	β=15	425373	106345	317910	79479	254230	63558
	β=5	160081	40022	126676	31670	106344	26587
LBGR=80	β=10	126677	31671	97176	24295	79478	19870
	β=15	106345	26588	79479	19871	63558	15890
LBGR=70	β=5	71148	17788	56301	14076	47265	11817

β=10	56302	14077	43190	10799	35324	8832
β=15	47265	11818	35325	8832	28249	7063

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$16,500.00, which averages out to a per sample cost of \$532.26. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	31 Samples					
Field collection costs		\$100.00	\$3,100.00					
Analytical costs	\$400.00	\$400.00	\$12,400.00					
Sum of Field & Analytical costs		\$500.00	\$15,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$16,500.00					

Data Analysis for Benzo(a)Pyrene

The following data points were entered by the user for analysis.

	Benzo(a)Pyrene (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	0.03	0.031	0.0315	0.0315	0.0315	0.032	0.0325	0.0325	0.0325	0.03275
10	0.03275	0.033	0.033	0.03325	0.0335	0.0335	0.0335	0.03375	0.034	0.0345
20	0.035	0.035	0.035	0.035	0.0355	0.036	0.036	0.037	0.037	0.0375
30	0.0485	0.0985	0.1025	0.172	0.31	0.315	0.325	0.34	0.3475	0.766
40	0.775									

SUMMARY STATIS	SUMMARY STATISTICS for Benzo(a)Pyrene						
n	41						
Min	0.03						
Max	0.775						
Range	0.745						
Mean	0.11248						
Median	0.035						
Variance	0.032309						
StdDev	0.17975						
Std Error	0.028072						
Skewness	2.7405						

Interquartile Range				0.04075				
Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.03	0.03105	0.0315	0.03275	0.035	0.0735	0.337	0.7241	0.775

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Benzo(a)Pyrene					
k	Significant?				
1	3.686	3.05	Yes		

The test statistic 3.686 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS for Benzo(a)Pyrene			
1	0.775		

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Shapiro-Wilk Test Statistic	0.5104			
Shapiro-Wilk 5% Critical Value	0.94			

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Benzo(a)Pyrene


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Benzo(a)Pyrene

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.5155			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	0.1597				
95% Non-Parametric (Chebyshev) UCL	0.2348				

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.2348) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (0.0148),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic	Critical Value t _{0.95}	Null Hypothesis		
3.4795	1.6839	Cannot Reject		

The test did not reject the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean exceeds the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+)	95% Critical Value	Null Hypothesis			
0	26	Cannot Reject			

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	65
Number of samples on map ^a	65
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$33,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679268.7700	3083200.3260	J-11S	0.0465	Manual	Т	
679301.1600	3083254.0340	J-12S	0.218	Manual	Т	
679171.2970	3083289.7960	J-04S	0.465	Manual	Т	
679155.0740	3083294.6960	J-03S	0.135	Manual	Т	
679133.4290	3083306.3130	J-01S	0.048	Manual	Т	
679104.2450	3083223.2620	J-02S	0.04	Manual	Т	
679164.8060	3083214.7100	J-06S	0.04225	Manual	Т	
679181.2750	3083178.2880	J-08S	0.0415	Manual	Т	
679213.7730	3083224.9730	J-09S	1.03	Manual	Т	
679280.5440	3083305.6810	J-10S	0.042	Manual	Т	
679242.7260	3083326.5280	J-07S	0.42	Manual	Т	
679225.8560	3083359.9740	J-05S	0.045	Manual	Т	
679339.9414	3083309.8490	J-15S	0.043	Adaptive-Fill		
679229.3268	3083274.1226	J-21S	0.44	Adaptive-Fill		
679166.5144	3083360.6002	J-19S	0.45	Adaptive-Fill		
679199.0125	3083325.9512	J-24S	0.41	Adaptive-Fill		
679290.1895	3083343.7836	J-20S	0.405	Adaptive-Fill		

Area: Area 3							
X Coord	Historical						
679261.0980	3083016.3510	J-15S	0.043	Manual	Т		
679335.0020	3082941.1720	J-21S	0.44	Manual	Т		

	1				_
679343.5810	3082969.5980	J-19S	0.45	Manual	Т
679394.8070	3082971.8300	J-24S	0.41	Manual	Т
679382.8640	3083009.1130	J-20S	0.405	Manual	Т
679293.5600	3082950.4980	J-17S	0.046	Manual	Т
679360.5700	3083026.4980	J-18S	0.044	Manual	Т
679297.0010	3082840.6970	J-23S	0.041	Manual	Т
679252.7130	3082781.0290	J-22S	0.0425	Manual	Т
679222.6340	3082840.1720	J-16S	0.0435	Manual	Т
679279.6830	3083075.4290	J-14S	0.181	Manual	Т
679149.4920	3082933.0980	J-13S	0.042	Manual	Т
679272.0040	3082652.6750	J-28S	0.045	Manual	Т
679224.5850	3082683.1400	J-26S	0.04275	Manual	Т
679146.6460	3082549.7640	J-25S	0.04525	Manual	Т
679169.0760	3082537.3510	J-27S	0.0445	Manual	Т
679342.7410	3082605.3190	J-35S	0.0435	Manual	Т
679304.6530	3082548.6880	J-34S	0.065	Manual	Т
679382.8900	3082667.5270	J-36S	0.0455	Manual	Т
679329.4380	3082711.0960	J-29S	0.0425	Manual	Т
679374.4420	3082791.3300	J-30S	0.0485	Manual	Т
679453.4760	3082914.1150	J-32S	0.048	Manual	Т
679410.1490	3082845.8460	J-31S	0.04375	Manual	Т
679560.6070	3082897.2580	J-41S	0.0385	Manual	Т
679495.8840	3082940.9730	J-33S	0.042	Manual	Т
679524.3310	3082886.8990	J-40S	0.043	Manual	Т
679497.3310	3082840.3960	J-39S	0.0465	Manual	Т
679470.3570	3082776.7350	J-38S	0.041	Manual	Т
679433.9450	3082731.6820	J-37S	0.041	Manual	Т
679184.4446	3082996.9264		0	Adaptive-Fill	
679177.1426	3082742.3877		0	Adaptive-Fill	
679228.5215	3082904.9556		0	Adaptive-Fill	
679381.8163	3082901.9806		0	Adaptive-Fill	
679441.0893	3082675.5360		0	Adaptive-Fill	
679358.0925	3082553.5465		0	Adaptive-Fill	
679330.4159	3082886.8562		0	Adaptive-Fill	
679221.7466	3083051.9971		0	Adaptive-Fill	
679198.5354	3082789.3512		0	Adaptive-Fill	
679249.1891	3082543.7262		0	Adaptive-Fill	
679244.2914	3082956.2636		0	Adaptive-Fill	
679406.6415	3082623.4861		0	Adaptive-Fill	
679119.5052	3082897.8954		0	Adaptive-Fill	
679271.0195	3082888.8959		0	Adaptive-Fill	

679458.5374	3082967.5965	0	Adaptive-Fill	
679285.1118	3082715.7475	0	Adaptive-Fill	
679320.7859	3083010.0230	0	Adaptive-Fill	
679323.6573	3082776.1377	0	Adaptive-Fill	
679415.7477	3082785.3452	0	Adaptive-Fill	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta		Parameter					
Analyte	n	s	Δ	α	β	Ζ _{1-α} ^a	Z _{1-β} b
Benzo(b)fluoranthene	65	0.1998 mg/kg	0.0738 mg/kg	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),

-1 -0.9 -0.8 -0.7 -0.6 -0.5 -0.4 -0.3 -0.2 -0.1 0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 0.8 0.9 True Benzo(b)fluoranthene Mean (mg/kg)

- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples

AI _0 1/	AL=0.1476		α=5		:10	α=15		
AL=0.14	+70	s=0.3996	s=0.1998	s=0.3996	s=0.1998	s=0.3996	s=0.1998	
	β=5	7934	1985	6278	1571	5270	1318	
LBGR=90	β=10	6279	1571	4816	1205	3939	986	
	β=15	5271	1319	3940	986	3150	788	
	β=5	1985	498	1571	394	1318	330	
LBGR=80	β=10	1571	394	1205	302	986	247	
	β=15	1319	331	986	247	788	198	
	β=5	883	222	699	176	587	147	
LBGR=70	β=10	699	176	536	135	439	110	
	β=15	587	148	439	111	351	89	

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$33,500.00, which averages out to a per sample cost of \$515.38. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION							
Cost Details	Per Analysis	Per Sample	65 Samples				
Field collection costs		\$100.00	\$6,500.00				
Analytical costs	\$400.00	\$400.00	\$26,000.00				
Sum of Field & Analytical costs		\$500.00	\$32,500.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$33,500.00				

Data Analysis for Benzo(b)fluoranthene

SUMMARY STATISTIC	SUMMARY STATISTICS for Benzo(b)fluoranthene				
n	2094				
Min	0				
Max	1.03				
Range	1.03				
Mean	0.0040505				
Median	0				
Variance	0.001489				
StdDev	0.038588				
Std Error	0.00084325				
Skewness	15.668				

Inte	Interquartile Range			0				
	Per				es			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0	0	0	0	0	0	0	0.048

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Benzo(b)fluoranthene							
k	Test Statistic R	5% Critical Value C _k	Significant?				
1	26.59	4.207	Yes				

The test statistic 26.59 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS for Benzo(b)fluoranthene				
1	1.03			

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers						
Lilliefors Test Statistic	0.5122					
Lilliefors 5% Critical Value	0.01937					

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Benzo(b)fluoranthene


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Benzo(b)fluoranthene

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic	0.5084				
Lilliefors 5% Critical Value	0.01936				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	0.005438				
95% Non-Parametric (Chebyshev) UCL	0.007726				

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.007726) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=2094 data,

AL is the action level or threshold (0.1476),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=2093 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
-170.23	1.6456	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test			
Test Statistic (S+)	95% Critical Value	Null Hypothesis	
2080	1085	Reject	

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF SAMPLING DESIGN		
Primary Objective of Design	Compare a site mean to a fixed threshold	
Type of Sampling Design	Parametric	
Sample Placement (Location) in the Field	Simple random sampling	
Working (Null) Hypothesis	The mean value at the site exceeds the threshold	
Formula for calculating number of sampling locations	Student's t-test	
Calculated total number of samples	2094	
Number of samples on map ^a	2094	
Number of selected sample areas b	2	
Specified sampling area ^c	188054.34 m ²	
Total cost of sampling ^d	\$1,048,000.00	

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 χ is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:


Analyta	n		Parameter					
Analyte n		S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b	
Benzo(b)fluoranthene	2094	0.1998 mg/kg	0.0127829 mg/kg	0.05	0.1	1.64485	1.28155	

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



b This value is automatically calculated by VSP based upon the user defined value of β.

Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples							
AL=0.14	176	α=	=5	α=	10	α=15 s=0.3996 s=0.199	
AL=0.14	+/0	s=0.3996	s=0.1998	s=0.3996	s=0.1998		
	β=5	7934	1985	6278	1571	5270	1318
LBGR=90	β=10	6279	1571	4816	1205	3939	986
	β=15	5271	1319	3940	986	3150	788
	β=5	1985	498	1571	394	1318	330
LBGR=80	β=10	1571	394	1205	302	986	247
	β=15	1319	331	986	247	788	198
	β=5	883	222	699	176	587	147
LBGR=70	β=10	699	176	536	135	439	110
	β=15	587	148	439	111	351	89

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$1,048,000.00, which averages out to a per sample cost of \$500.48. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	2094 Samples		
Field collection costs		\$100.00	\$209,400.00		
Analytical costs	\$400.00	\$400.00	\$837,600.00		
Sum of Field & Analytical costs		\$500.00	\$1,047,000.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$1,048,000.00		

SUMMARY STATISTICS for Benzo(b)fluoranthene							ne	
	ı	n		2094				
	М	lin				0		
	M	ах				1.03		
	Ra	nge				1.03		
	Мє	ean			0	.00405	05	
	Ме	dian		0				
Variance				0.001489				
	Std	Dev		0.038588				
	Std	Error		0.00084325				
	Skev	ness		15.668				
Inte	erquar	tile Rar	nge	0				
			Pe	ercenti	les			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0	0	0	0	0	0	0	0.048

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNE	ROSNER'S OUTLIER TEST for Benzo(b)fluoranthene					
k	Test Statistic R _k	5% Critical Value C _k	Significant?			
1	26.59	4.207	Yes			

The test statistic 26.59 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS for Benzo(b)fluoranther			
1	1.03		

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Lilliefors Test Statistic	0.5122			
Lilliefors 5% Critical Value	0.01937			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not

justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots for Benzo(b)fluoranthene


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Benzo(b)fluoranthene

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Lilliefors Test Statistic	0.5084			
Lilliefors 5% Critical Value	0.01936			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN			
95% Parametric UCL	0.005438		
95% Non-Parametric (Chebyshev) UCL	0.007726		

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.007726) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=2094 data,

AL is the action level or threshold (0.1476),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=2093 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic	Critical Value t _{0.95}	Null Hypothesis			
-170.23	1.6456	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+)	95% Critical Value	Null Hypothesis			
2080	1085	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1. Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN				
Primary Objective of Design	Compare a site mean to a fixed threshold				
Type of Sampling Design	Parametric				
Sample Placement (Location) in the Field	Simple random sampling				
Working (Null) Hypothesis	The mean value at the site exceeds the threshold				
Formula for calculating number of sampling locations	Student's t-test				
Calculated total number of samples	2				
Number of samples on map ^a	41				
Number of selected sample areas b	2				
Specified sampling area ^c	188054.34 m ²				
Total cost of sampling d	\$2,000.00				

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical		
679268.7700	3083200.3260	J-11S	11.3	Manual	Т		
679301.1600	3083254.0340	J-12S	2.3	Manual	Т		
679171.2970	3083289.7960	J-04S	0.92	Manual	Т		
679155.0740	3083294.6960	J-03S	1.25	Manual	Т		
679133.4290	3083306.3130	J-01S	2.8	Manual	Т		
679104.2450	3083223.2620	J-02S	0.9	Manual	Т		
679164.8060	3083214.7100	J-06S	0.505	Manual	Т		
679181.2750	3083178.2880	J-08S	3.6	Manual	Т		
679213.7730	3083224.9730	J-09S	4.5	Manual	Т		
679280.5440	3083305.6810	J-10S	2.9	Manual	Т		
679242.7260	3083326.5280	J-07S	13.3	Manual	Т		
679225.8560	3083359.9740	J-05S	0.77	Manual	Т		

Area: Area 3							
X Coord	Y Coord	Label	Value	Туре	Historical		
679261.0980	3083016.3510	J-15S	7.4	Manual	Т		
679335.0020	3082941.1720	J-21S	8.3	Manual	Т		
679343.5810	3082969.5980	J-19S	3.8	Manual	Т		
679394.8070	3082971.8300	J-24S	1.6	Manual	Т		
679382.8640	3083009.1130	J-20S	4	Manual	Т		
679293.5600	3082950.4980	J-17S	9	Manual	Т		
679360.5700	3083026.4980	J-18S	2.8	Manual	Т		

679297.0010	3082840.6970	J-23S	6.9	Manual T
679252.7130	3082781.0290	J-22S	5.15	Manual T
679222.6340	3082840.1720	J-16S	4	Manual T
679279.6830	3083075.4290	J-14S	5.1	Manual T
679149.4920	3082933.0980	J-13S	1.4	Manual T
679272.0040	3082652.6750	J-28S	3.9	Manual T
679224.5850	3082683.1400	J-26S	1.714	Manual T
679146.6460	3082549.7640	J-25S	1.45	Manual T
679169.0760	3082537.3510	J-27S	4.2	Manual T
679342.7410	3082605.3190	J-35S	3.6	Manual T
679304.6530	3082548.6880	J-34S	14.9	Manual T
679382.8900	3082667.5270	J-36S	5.05	Manual T
679329.4380	3082711.0960	J-29S	6.7	Manual T
679374.4420	3082791.3300	J-30S	10.4	Manual T
679453.4760	3082914.1150	J-32S	8.9	Manual T
679410.1490	3082845.8460	J-31S	9.6	Manual T
679560.6070	3082897.2580	J-41S	3.7	Manual T
679495.8840	3082940.9730	J-33S	2	Manual T
679524.3310	3082886.8990	J-40S	7.8	Manual T
679497.3310	3082840.3960	J-39S	4.5	Manual T
679470.3570	3082776.7350	J-38S	6.4	Manual T
679433.9450	3082731.6820	J-37S	4.9	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

S

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	n		Parar	neter			
Analyte	n	S	Δ	α	β	Ζ _{1-α} ^a	Ζ_{1-β} b
Chromium	2	3.52 mg/kg	105.338 mg/kg	0.05	0.1	1.64485	1.28155


 $^{\rm a}$ This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

	Number of Samples							
AL 010	675	α	=5	α=	10	α=15		
AL=210	.075	s=7.04	s=3.52	s=7.04	s=3.52	s=7.04	s=3.52	
	β=5	3	2	2	2	2	1	
LBGR=90	β=10	3	2	2	2	2	1	
	β=15	3	2	2	1	2	1	
	β=5	2	2	2	1	1	1	
LBGR=80	β=10	2	2	2	1	1	1	
	β=15	2	2	1	1	1	1	
LBGR=70	β=5	2	2	1	1	1	1	

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	2 Samples			
Field collection costs		\$100.00	\$200.00			
Analytical costs	\$400.00	\$400.00	\$800.00			
Sum of Field & Analytical costs		\$500.00	\$1,000.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$2,000.00			

Data Analysis for Chromium

The following data points were entered by the user for analysis.

	Chromium (mg/kg)									
Rank	Rank 1 2 3 4 5 6 7 8 9 10									
0	0.505	0.77	0.9	0.92	1.25	1.4	1.45	1.6	1.714	2
10	2.3	2.8	2.8	2.9	3.6	3.6	3.7	3.8	3.9	4
20	4	4.2	4.5	4.5	4.9	5.05	5.1	5.15	6.4	6.7
30	6.9	7.4	7.8	8.3	8.9	9	9.6	10.4	11.3	13.3
40	14.9									

SUMMARY STATISTICS for Chromium					
n	41				
Min	0.505				
Max	14.9				
Range	14.395				
Mean	4.9807				
Median	4				
Variance	12.41				
StdDev	3.5228				
Std Error	0.55018				
Skewness	1.0052				

Inte	Interquartile Range					5		
	entile	s						
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.505	0.783	0.986	2.15	4	7.15	10.24	13.1	14.9

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Chromium					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	2.816	3.05	No		

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outlier					
	Shapiro-Wilk Test Statistic	0.9268			
	Shapiro-Wilk 5% Critical Value	0.94			

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Chromium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the

distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Chromium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic 0.9119					
Shapiro-Wilk 5% Critical Value	0.941				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN						
95% Parametric UCL	5.907					
95% Non-Parametric (Chebyshev) UCL	7.379					

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (7.379) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (210.675),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic Critical Value t _{0.95} Null Hypothesis						
-373.87	1.6839	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothesis						
41	26	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

 * - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	2
Number of samples on map ^a	41
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$2,000.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	X Coord Y Coord Label Value Type								
679268.7700	3083200.3260	J-11S	11.3	Manual	Т				
679301.1600	3083254.0340	J-12S	2.3	Manual	Т				
679171.2970	3083289.7960	J-04S	0.92	Manual	Т				
679155.0740	3083294.6960	J-03S	1.25	Manual	Т				
679133.4290	3083306.3130	J-01S	2.8	Manual	Т				
679104.2450	3083223.2620	J-02S	0.9	Manual	Т				
679164.8060	3083214.7100	J-06S	0.505	Manual	Т				
679181.2750	3083178.2880	J-08S	3.6	Manual	Т				
679213.7730	3083224.9730	J-09S	4.5	Manual	Т				
679280.5440	3083305.6810	J-10S	2.9	Manual	Т				
679242.7260	3083326.5280	J-07S	13.3	Manual	Т				
679225.8560	3083359.9740	J-05S	0.77	Manual	Т				

Area: Area 3								
X Coord	Label	Value	Туре	Historical				
679261.0980	3083016.3510	J-15S	7.4	Manual	Т			
679335.0020	3082941.1720	J-21S	8.3	Manual	Т			
679343.5810	3082969.5980	J-19S	3.8	Manual	Т			
679394.8070	3082971.8300	J-24S	1.6	Manual	Т			
679382.8640	3083009.1130	J-20S	4	Manual	Т			
679293.5600	3082950.4980	J-17S	9	Manual	Т			
679360.5700	3083026.4980	J-18S	2.8	Manual	Т			

3082840.6970	J-23S	6.9	Manual T
3082781.0290	J-22S	5.15	Manual T
3082840.1720	J-16S	4	Manual T
3083075.4290	J-14S	5.1	Manual T
3082933.0980	J-13S	1.4	Manual T
3082652.6750	J-28S	3.9	Manual T
3082683.1400	J-26S	1.714	Manual T
3082549.7640	J-25S	1.45	Manual T
3082537.3510	J-27S	4.2	Manual T
3082605.3190	J-35S	3.6	Manual T
3082548.6880	J-34S	14.9	Manual T
3082667.5270	J-36S	5.05	Manual T
3082711.0960	J-29S	6.7	Manual T
3082791.3300	J-30S	10.4	Manual T
3082914.1150	J-32S	8.9	Manual T
3082845.8460	J-31S	9.6	Manual T
3082897.2580	J-41S	3.7	Manual T
3082940.9730	J-33S	2	Manual T
3082886.8990	J-40S	7.8	Manual T
3082840.3960	J-39S	4.5	Manual T
3082776.7350	J-38S	6.4	Manual T
3082731.6820	J-37S	4.9	Manual T
	3082781.0290 3082840.1720 3083075.4290 3082933.0980 3082652.6750 3082683.1400 3082549.7640 3082537.3510 3082605.3190 3082548.6880 3082667.5270 3082711.0960 3082791.3300 3082940.9730 3082845.8460 3082897.2580 3082940.9730 3082840.3960 3082776.7350	3082781.0290 J-22S 3082840.1720 J-16S 3083075.4290 J-14S 3082933.0980 J-13S 3082652.6750 J-28S 3082683.1400 J-26S 3082549.7640 J-25S 3082537.3510 J-27S 3082605.3190 J-35S 3082548.6880 J-34S 3082667.5270 J-36S 3082711.0960 J-29S 3082791.3300 J-30S 3082914.1150 J-32S 3082845.8460 J-31S 3082845.8460 J-31S 3082840.9730 J-33S 3082840.9730 J-33S 3082840.3960 J-39S 3082776.7350 J-38S	3082781.0290 J-22S 5.15 3082840.1720 J-16S 4 3083075.4290 J-14S 5.1 3082933.0980 J-13S 1.4 3082652.6750 J-28S 3.9 3082683.1400 J-26S 1.714 3082549.7640 J-25S 1.45 3082537.3510 J-27S 4.2 3082605.3190 J-35S 3.6 3082548.6880 J-34S 14.9 3082667.5270 J-36S 5.05 3082711.0960 J-29S 6.7 3082791.3300 J-30S 10.4 3082914.1150 J-32S 8.9 3082845.8460 J-31S 9.6 3082897.2580 J-41S 3.7 3082840.9730 J-33S 2 3082840.3960 J-39S 4.5 3082776.7350 J-38S 6.4

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

	Analyta	_	Parameter					
	Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
(Chromium	2	3.52 mg/kg	205.69 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples							
AL=210.675		α=5		α=10		α=15	
		s=7.04	s=3.52	s=7.04	s=3.52	s=7.04	s=3.52
	β=5	3	2	2	2	2	1
LBGR=90	β=10	3	2	2	2	2	1
	β=15	3	2	2	1	2	1
	β=5	2	2	2	1	1	1
LBGR=80	β=10	2	2	2	1	1	1
	β=15	2	2	1	1	1	1
LBGR=70	β=5	2	2	1	1	1	1

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details Per Analysis Per Sample 2 Sample								
Field collection costs		\$100.00	\$200.00					
Analytical costs	\$400.00	\$400.00	\$800.00					
Sum of Field & Analytical costs		\$500.00	\$1,000.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$2,000.00					

Data Analysis for Chromium

The following data points were entered by the user for analysis.

	Chromium (mg/kg)									
Rank 1 2 3 4 5 6 7 8 9										10
0	0.505	0.77	0.9	0.92	1.25	1.4	1.45	1.6	1.714	2
10	2.3	2.8	2.8	2.9	3.6	3.6	3.7	3.8	3.9	4
20	4	4.2	4.5	4.5	4.9	5.05	5.1	5.15	6.4	6.7
30	6.9	7.4	7.8	8.3	8.9	9	9.6	10.4	11.3	13.3
40	14.9									

SUMMARY STATISTICS for Chromium					
n	41				
Min	0.505				
Max	14.9				
Range	14.395				
Mean	4.9807				
Median	4				
Variance	12.41				
StdDev	3.5228				
Std Error	0.55018				
Skewness	1.0052				

Interquartile Range				5				
Pero				entile	s			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.505	0.783	0.986	2.15	4	7.15	10.24	13.1	14.9

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Chromium							
k Test Statistic R _k 5% Critical Value C _k Significant?							
1	2.816	3.05	No				

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Shapiro-Wilk Test Statistic	0.9268					
Shapiro-Wilk 5% Critical Value	0.94					

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Chromium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the

distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Chromium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST						
Shapiro-Wilk Test Statistic 0.9119						
Shapiro-Wilk 5% Critical Value 0.941						

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN						
95% Parametric UCL	5.907					
95% Non-Parametric (Chebyshev) UCL	7.379					

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (7.379) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (210.675),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic Critical Value $t_{0.95}$ Null Hypothesis							
-373.87	1.6839	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+) 95% Critical Value Null Hypothesis							
41	26	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

 * - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary


This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.

SUMMARY OF SAMPLING DESIGN						
Primary Objective of Design	Compare a site mean to a fixed threshold					
Type of Sampling Design	Parametric					
Sample Placement (Location) in the Field	Simple random sampling					
Working (Null) Hypothesis	The mean value at the site exceeds the threshold					
Formula for calculating number of sampling locations	Student's t-test					
Calculated total number of samples	2					
Number of samples on map ^a	41					
Number of selected sample areas b	2					
Specified sampling area ^c	188054.34 m ²					
Total cost of sampling d	\$2,000.00					

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

X Coord	Y Coord	Label	Value	Туре	Historical
679268.7700	3083200.3260	J-11S	0.0037	Manual	Т
679301.1600	3083254.0340	J-12S	0.0065	Manual	Т
679171.2970	3083289.7960	J-04S	0.007	Manual	Т
679155.0740	3083294.6960	J-03S	0.0096	Manual	Т
679133.4290	3083306.3130	J-01S	0.0083	Manual	Т
679104.2450	3083223.2620	J-02S	0.0069	Manual	Т
679164.8060	3083214.7100	J-06S	0.00535	Manual	Т
679181.2750	3083178.2880	J-08S	0.0014	Manual	Т
679213.7730	3083224.9730	J-09S	0.013	Manual	Т
679280.5440	3083305.6810	J-10S	0.0047	Manual	Т
679242.7260	3083326.5280	J-07S	0.74	Manual	Т
679225.8560	3083359.9740	J-05S	0.0014	Manual	Т

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			
679261.0980	3083016.3510	J-15S	0.011	Manual	Т			
679335.0020	3082941.1720	J-21S	0.016	Manual	Т			
679343.5810	3082969.5980	J-19S	0.049	Manual	Т			
679394.8070	3082971.8300	J-24S	0.026	Manual	Т			
679382.8640	3083009.1130	J-20S	0.013	Manual	Т			
679293.5600	3082950.4980	J-17S	0.024	Manual	Т			
679360.5700	3083026.4980	J-18S	0.0088	Manual	Т			
679297.0010	3082840.6970	J-23S	0.012	Manual	Т			
679252.7130	3082781.0290	J-22S	0.034	Manual	Т			
679222.6340	3082840.1720	J-16S	0.034	Manual	Т			
679279.6830	3083075.4290	J-14S	0.0054	Manual	Т			
679149.4920	3082933.0980	J-13S	0.000385	Manual	Т			
679272.0040	3082652.6750	J-28S	0.0093	Manual	Т			
679224.5850	3082683.1400	J-26S	0.0073	Manual	Т			
679146.6460	3082549.7640	J-25S	0.0095	Manual	Т			
679169.0760	3082537.3510	J-27S	0.016	Manual	Т			
679342.7410	3082605.3190	J-35S	0.0072	Manual	Т			
679304.6530	3082548.6880	J-34S	0.079	Manual	Т			
679382.8900	3082667.5270	J-36S	0.0031	Manual	Т			
679329.4380	3082711.0960	J-29S	0.014	Manual	Т			
679374.4420	3082791.3300	J-30S	0.024	Manual	Т			
679453.4760	3082914.1150	J-32S	0.007	Manual	Т			
679410.1490	3082845.8460	J-31S	0.0215	Manual	Т			
679560.6070	3082897.2580	J-41S	0.013	Manual	Т			
679495.8840	3082940.9730	J-33S	0.0076	Manual	Т			

679524.3310	3082886.8990	J-40S	0.0079	Manual	Т
679497.3310	3082840.3960	J-39S	0.019	Manual	Т
679470.3570	3082776.7350	J-38S	0.0054	Manual	Т
679433.9450	3082731.6820	J-37S	0.0013	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-R) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region.

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analyte n		Parameter						
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b	
Mercury	2	0.11 mg/kg	1.0436 mg/kg	0.05	0.1	1.64485	1.28155	


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.





Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed).
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples				
AL=2.0872	α=5	α=10	α=15	

	s=0.22	s=0.11	s=0.22	s=0.11	s=0.22	s=0.11	
	β=5	14	5	11	4	9	3
LBGR=90	β=10	11	4	9	3	7	3
	β=15	10	4	7	3	6	2
	β=5	5	3	4	2	3	2
LBGR=80	β=10	4	2	3	2	3	1
	β=15	4	2	3	2	2	1
	β=5	3	2	2	2	2	1
LBGR=70	β=10	3	2	2	2	2	1
	β=15	3	2	2	1	2	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	2 Samples			
Field collection costs		\$100.00	\$200.00			
Analytical costs	\$400.00	\$400.00	\$800.00			
Sum of Field & Analytical costs		\$500.00	\$1,000.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$2,000.00			

Data Analysis for Mercury

The following data points were entered by the user for analysis.

	Mercury (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	0.000385	0.0013	0.0014	0.0014	0.0031	0.0037	0.0047	0.00535	0.0054	0.0054
10	0.0065	0.0069	0.007	0.007	0.0072	0.0073	0.0076	0.0079	0.0083	0.0088
20	0.0093	0.0095	0.0096	0.011	0.012	0.013	0.013	0.013	0.014	0.016
30	0.016	0.019	0.0215	0.024	0.024	0.026	0.034	0.034	0.049	0.079
40	0.74									

SUMMARY STATISTICS for Mercury			
n	41		
Min	0.000385		

	0.74								
	Range					73962			
	Ме	an			0.0	03155			
		0.	0093						
		0.0	13071						
	StdDev					0.11433			
	Std E	rror		0.017855					
	Skew	ness		6.2475					
Ir	nterquarti	ile Range	•	0.01155					
	Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0.000385	0.00131	0.00174	0.00595	0.0093	0.0175	0.034	0.076	0.74	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Mercury					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	6.197	3.05	Yes		

The test statistic 6.197 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUT	LIERS for Mercury
1	0.74

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.7183				
Shapiro-Wilk 5% Critical Value	0.94				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots for Mercury

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through

2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Mercury

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.2381			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	0.06162			
95% Non-Parametric (Chebyshev) UCL	0.1094			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.1094) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data, AL is the action level or threshold (2.0872).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST			
t-statistic	Critical Value t _{0.95}	Null Hypothesis	
-115.13	1.6839	Reject	

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+)	95% Critical Value	Null Hypothesis		
41	26	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1. Software and documentation available at http://dqo.pnl.gov/vsp
Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

 * - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary


This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.

SUMMARY OF SAMPLING DESIGN			
Primary Objective of Design	Compare a site mean to a fixed threshold		
Type of Sampling Design	Parametric		
Sample Placement (Location) in the Field	Simple random sampling		
Working (Null) Hypothesis	The mean value at the site exceeds the threshold		
Formula for calculating number of sampling locations	Student's t-test		
Calculated total number of samples	2		
Number of samples on map ^a	41		
Number of selected sample areas b	2		
Specified sampling area ^c	188054.34 m ²		
Total cost of sampling d	\$2,000.00		

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

X Coord	Y Coord	Label	Value	Туре	Historical
679268.7700	3083200.3260	J-11S	0.0037	Manual	Т
679301.1600	3083254.0340	J-12S	0.0065	Manual	Т
679171.2970	3083289.7960	J-04S	0.007	Manual	Т
679155.0740	3083294.6960	J-03S	0.0096	Manual	Т
679133.4290	3083306.3130	J-01S	0.0083	Manual	Т
679104.2450	3083223.2620	J-02S	0.0069	Manual	Т
679164.8060	3083214.7100	J-06S	0.00535	Manual	Т
679181.2750	3083178.2880	J-08S	0.0014	Manual	Т
679213.7730	3083224.9730	J-09S	0.013	Manual	Т
679280.5440	3083305.6810	J-10S	0.0047	Manual	Т
679242.7260	3083326.5280	J-07S	0.74	Manual	Т
679225.8560	3083359.9740	J-05S	0.0014	Manual	Т

Area: Area 3					
X Coord	Y Coord	Label	Value	Туре	Historical
679261.0980	3083016.3510	J-15S	0.011	Manual	Т
679335.0020	3082941.1720	J-21S	0.016	Manual	Т
679343.5810	3082969.5980	J-19S	0.049	Manual	Т
679394.8070	3082971.8300	J-24S	0.026	Manual	Т
679382.8640	3083009.1130	J-20S	0.013	Manual	Т
679293.5600	3082950.4980	J-17S	0.024	Manual	Т
679360.5700	3083026.4980	J-18S	0.0088	Manual	Т
679297.0010	3082840.6970	J-23S	0.012	Manual	Т
679252.7130	3082781.0290	J-22S	0.034	Manual	Т
679222.6340	3082840.1720	J-16S	0.034	Manual	Т
679279.6830	3083075.4290	J-14S	0.0054	Manual	Т
679149.4920	3082933.0980	J-13S	0.000385	Manual	Т
679272.0040	3082652.6750	J-28S	0.0093	Manual	Т
679224.5850	3082683.1400	J-26S	0.0073	Manual	Т
679146.6460	3082549.7640	J-25S	0.0095	Manual	Т
679169.0760	3082537.3510	J-27S	0.016	Manual	Т
679342.7410	3082605.3190	J-35S	0.0072	Manual	Т
679304.6530	3082548.6880	J-34S	0.079	Manual	Т
679382.8900	3082667.5270	J-36S	0.0031	Manual	Т
679329.4380	3082711.0960	J-29S	0.014	Manual	Т
679374.4420	3082791.3300	J-30S	0.024	Manual	Т
679453.4760	3082914.1150	J-32S	0.007	Manual	Т
679410.1490	3082845.8460	J-31S	0.0215	Manual	Т
679560.6070	3082897.2580	J-41S	0.013	Manual	Т
679495.8840	3082940.9730	J-33S	0.0076	Manual	Т

679524.3310	3082886.8990	J-40S	0.0079	Manual	Т
679497.3310	3082840.3960	J-39S	0.019	Manual	Т
679470.3570	3082776.7350	J-38S	0.0054	Manual	Т
679433.9450	3082731.6820	J-37S	0.0013	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-R) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples, S

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region.

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analyta	_		Par	amet	er		
Analyte	"	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
Mercury	2	0.11 mg/kg	2.06 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at $1-\alpha$ on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at $1-\alpha$. If any of the inputs change, the number of samples that result in the correct curve changes.





Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed).
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples				
AL=2.0872	α=5	α=10	α=15	

	s=0.22	s=0.11	s=0.22	s=0.11	s=0.22	s=0.11	
	β=5	14	5	11	4	9	3
LBGR=90	β=10	11	4	9	3	7	3
	β=15	10	4	7	3	6	2
	β=5	5	3	4	2	3	2
LBGR=80	β=10	4	2	3	2	3	1
	β=15	4	2	3	2	2	1
	β=5	3	2	2	2	2	1
LBGR=70	β=10	3	2	2	2	2	1
	β=15	3	2	2	1	2	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	2 Samples			
Field collection costs		\$100.00	\$200.00			
Analytical costs	\$400.00	\$400.00	\$800.00			
Sum of Field & Analytical costs		\$500.00	\$1,000.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$2,000.00			

Data Analysis for Mercury

The following data points were entered by the user for analysis.

	Mercury (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	0.000385	0.0013	0.0014	0.0014	0.0031	0.0037	0.0047	0.00535	0.0054	0.0054
10	0.0065	0.0069	0.007	0.007	0.0072	0.0073	0.0076	0.0079	0.0083	0.0088
20	0.0093	0.0095	0.0096	0.011	0.012	0.013	0.013	0.013	0.014	0.016
30	0.016	0.019	0.0215	0.024	0.024	0.026	0.034	0.034	0.049	0.079
40	0.74									

SUMMARY STATISTICS for Mercury			
n	41		
Min	0.000385		

	0.74								
	Range					73962			
	Mea	an			0.0	03155			
		0.	0093						
		0.0	13071						
	StdDev					0.11433			
	Std E	rror		0.017855					
	Skew	ness		6.2475					
Ir	nterquarti	ile Range	•	0.01155					
	Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0.000385	0.00131	0.00174	0.00595	0.0093	0.0175	0.034	0.076	0.74	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Mercury					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	6.197	3.05	Yes		

The test statistic 6.197 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUT	LIERS for Mercury
1	0.74

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.7183				
Shapiro-Wilk 5% Critical Value	0.94				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots for Mercury

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through

2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Mercury

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.2381			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN						
95% Parametric UCL	0.06162					
95% Non-Parametric (Chebyshev) UCL	0.1094					

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.1094) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{\Im F}$$

where

x is the sample mean of the n=41 data, AL is the action level or threshold (2.0872).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic	Critical Value t _{0.95}	Null Hypothesis					
-115.13	1.6839	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+)	95% Critical Value	Null Hypothesis					
41	26	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1. Software and documentation available at http://dqo.pnl.gov/vsp
Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

 * - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN								
Primary Objective of Design	Compare a site mean to a fixed threshold							
Type of Sampling Design	Parametric							
Sample Placement (Location) in the Field	Simple random sampling							
Working (Null) Hypothesis	The mean value at the site exceeds the threshold							
Formula for calculating number of sampling locations	Student's t-test							
Calculated total number of samples	2							
Number of samples on map ^a	41							
Number of selected sample areas b	2							
Specified sampling area ^c	188054.34 m ²							
Total cost of sampling d	\$2,000.00							

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1										
X Coord	Y Coord	Label Value		Туре	Historical					
679268.7700	3083200.3260	J-11S	6	Manual	Т					
679301.1600	3083254.0340	J-12S	3.4	Manual	Т					
679171.2970	3083289.7960	J-04S	3.6	Manual	Т					
679155.0740	3083294.6960	J-03S	4.4	Manual	Т					
679133.4290	3083306.3130	J-01S	7	Manual	Т					
679104.2450	3083223.2620	J-02S	4.6	Manual	Т					
679164.8060	3083214.7100	J-06S	2.15	Manual	Т					
679181.2750	3083178.2880	J-08S	8.3	Manual	Т					
679213.7730	3083224.9730	J-09S	8.9	Manual	Т					
679280.5440	3083305.6810	J-10S	6.9	Manual	Т					
679242.7260	3083326.5280	J-07S	80.6	Manual	Т					
679225.8560	3083359.9740	J-05S	4.8	Manual	Т					

Area: Area 3									
X Coord	Y Coord	Label	Value	Туре	Historical				
679261.0980	3083016.3510	J-15S	18.9	Manual	Т				
679335.0020	3082941.1720	J-21S	17.7	Manual	Т				
679343.5810	3082969.5980	J-19S	19.75	Manual	Т				
679394.8070	3082971.8300	J-24S	7.2	Manual	Т				
679382.8640	3083009.1130	J-20S	17.1	Manual	Т				
679293.5600	3082950.4980	J-17S	16.1	Manual	Т				
679360.5700	3083026.4980	J-18S	80.7	Manual	Т				

679297.0010	3082840.6970	J-23S	9.9	Manual T
679252.7130	3082781.0290	J-22S	22.45	Manual T
679222.6340	3082840.1720	J-16S	9.8	Manual T
679279.6830	3083075.4290	J-14S	55.8	Manual T
679149.4920	3082933.0980	J-13S	2.6	Manual T
679272.0040	3082652.6750	J-28S	6.1	Manual T
679224.5850	3082683.1400	J-26S	2.021	Manual T
679146.6460	3082549.7640	J-25S	2.45	Manual T
679169.0760	3082537.3510	J-27S	3.7	Manual T
679342.7410	3082605.3190	J-35S	5.1	Manual T
679304.6530	3082548.6880	J-34S	10.4	Manual T
679382.8900	3082667.5270	J-36S	18.8	Manual T
679329.4380	3082711.0960	J-29S	12.7	Manual T
679374.4420	3082791.3300	J-30S	23.8	Manual T
679453.4760	3082914.1150	J-32S	11.6	Manual T
679410.1490	3082845.8460	J-31S	14.75	Manual T
679560.6070	3082897.2580	J-41S	9.2	Manual T
679495.8840	3082940.9730	J-33S	5.4	Manual T
679524.3310	3082886.8990	J-40S	20.9	Manual T
679497.3310	3082840.3960	J-39S	6.9	Manual T
679470.3570	3082776.7350	J-38S	8	Manual T
679433.9450	3082731.6820	J-37S	6.7	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability (1-β) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

S

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region.

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}^{\alpha}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:


Amolysta	_		Para	amete	er		
Analyte		S	Δ	α	β	Z _{1-α} a	Z_{1-β} b
Lead	2	17.88 mg/kg	200 mg/kg	0.05	0.1	1.64485	1.28155

 a This value is automatically calculated by VSP based upon the user defined value of α . This value is automatically calculated by VSP based upon the user defined value of β .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples									
AL=400		α=	=5	α=	10	α=15			
		s=35.76	s=17.88	s=35.76 s=17.88		s=35.76	s=17.88		
	β=5	11	4	8	3	7	2		
LBGR=90	β=10	9	4	7	3	5	2		
	β=15	8	3	6	2	4	2		
	β=5	4	2	3	2	2	1		
LBGR=80	β=10	4	2	3	2	2	1		
	β=15	3	2	2	2	2	1		
LBGR=70	β=5	3	2	2	2	2	1		

β=10	3	2	2	1	2	1
β=15	2	2	2	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	2 Samples						
Field collection costs		\$100.00	\$200.00						
Analytical costs	\$400.00	\$400.00	\$800.00						
Sum of Field & Analytical costs		\$500.00	\$1,000.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$2,000.00						

Data Analysis for Lead

The following data points were entered by the user for analysis.

	Lead (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	2.021	2.15	2.45	2.6	3.4	3.6	3.7	4.4	4.6	4.8
10	5.1	5.4	6	6.1	6.7	6.9	6.9	7	7.2	8
20	8.3	8.9	9.2	9.8	9.9	10.4	11.6	12.7	14.75	16.1
30	17.1	17.7	18.8	18.9	19.75	20.9	22.45	23.8	55.8	80.6
40	80.7									

SUMMARY STATISTICS for Lead			
n	41		
Min	2.021		
Max	80.7		
Range	78.679		
Mean	n 14.321		
Median	8.3		
Variance	319.78		
StdDev	17.882		
Std Error	2.7928		
Skewness	2.9321		

Interquartile Range			12.45					
Perce			centil	les				
1%	5%	10%	25%	50% 75% 90% 95% 99%				99%
2.021	2.18	2.76	4.95	8.3	17.4	23.53	78.12	80.7

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Lead					
k Test Statistic R _k 5% Critical Value C _k Significant?					
1	3.712	3.05	Yes		

The test statistic 3.712 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OU	TLIERS for Lead
1	80.7

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)			
Shapiro-Wilk Test Statistic	0.6201		
Shapiro-Wilk 5% Critical Value	0.94		

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Lead


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Lead

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.5986			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	19.02			
95% Non-Parametric (Chebyshev) UCL	26.49			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (26.49) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SR}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (400),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-138.1	1.6839	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+) 95% Critical Value Null Hypothesis				
41	26	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	2
Number of samples on map ^a	41
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$2,000.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679268.7700	3083200.3260	J-11S	6	Manual	Т	
679301.1600	3083254.0340	J-12S	3.4	Manual	Т	
679171.2970	3083289.7960	J-04S	3.6	Manual	Т	
679155.0740	3083294.6960	J-03S	4.4	Manual	Т	
679133.4290	3083306.3130	J-01S	7	Manual	Т	
679104.2450	3083223.2620	J-02S	4.6	Manual	Т	
679164.8060	3083214.7100	J-06S	2.15	Manual	Т	
679181.2750	3083178.2880	J-08S	8.3	Manual	Т	
679213.7730	3083224.9730	J-09S	8.9	Manual	Т	
679280.5440	3083305.6810	J-10S	6.9	Manual	Т	
679242.7260	3083326.5280	J-07S	80.6	Manual	Т	
679225.8560	3083359.9740	J-05S	4.8	Manual	Т	

Area: Area 3					
X Coord	Y Coord	Label	Value	Туре	Historical
679261.0980	3083016.3510	J-15S	18.9	Manual	Т
679335.0020	3082941.1720	J-21S	17.7	Manual	Т
679343.5810	3082969.5980	J-19S	19.75	Manual	Т
679394.8070	3082971.8300	J-24S	7.2	Manual	Т
679382.8640	3083009.1130	J-20S	17.1	Manual	Т
679293.5600	3082950.4980	J-17S	16.1	Manual	Т
679360.5700	3083026.4980	J-18S	80.7	Manual	Т

679297.0010	3082840.6970	J-23S	9.9	Manual T
679252.7130	3082781.0290	J-22S	22.45	Manual T
679222.6340	3082840.1720	J-16S	9.8	Manual T
679279.6830	3083075.4290	J-14S	55.8	Manual T
679149.4920	3082933.0980	J-13S	2.6	Manual T
679272.0040	3082652.6750	J-28S	6.1	Manual T
679224.5850	3082683.1400	J-26S	2.021	Manual T
679146.6460	3082549.7640	J-25S	2.45	Manual T
679169.0760	3082537.3510	J-27S	3.7	Manual T
679342.7410	3082605.3190	J-35S	5.1	Manual T
679304.6530	3082548.6880	J-34S	10.4	Manual T
679382.8900	3082667.5270	J-36S	18.8	Manual T
679329.4380	3082711.0960	J-29S	12.7	Manual T
679374.4420	3082791.3300	J-30S	23.8	Manual T
679453.4760	3082914.1150	J-32S	11.6	Manual T
679410.1490	3082845.8460	J-31S	14.75	Manual T
679560.6070	3082897.2580	J-41S	9.2	Manual T
679495.8840	3082940.9730	J-33S	5.4	Manual T
679524.3310	3082886.8990	J-40S	20.9	Manual T
679497.3310	3082840.3960	J-39S	6.9	Manual T
679470.3570	3082776.7350	J-38S	8	Manual T
679433.9450	3082731.6820	J-37S	6.7	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyta	_	Parameter					
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
Lead	2	17.88 mg/kg	385.68 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

^b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples							
AL=400		α=5		α=	10	α=15	
		s=35.76	s=17.88	s=35.76	s=17.88	s=35.76	s=17.88
	β=5	11	4	8	3	7	2
LBGR=90	β=10	9	4	7	3	5	2
	β=15	8	3	6	2	4	2
	β=5	4	2	3	2	2	1
LBGR=80	β=10	4	2	3	2	2	1
	β=15	3	2	2	2	2	1
LBGR=70	β=5	3	2	2	2	2	1

β=10	3	2	2	1	2	1
β=15	2	2	2	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	2 Samples			
Field collection costs		\$100.00	\$200.00			
Analytical costs	\$400.00	\$400.00	\$800.00			
Sum of Field & Analytical costs		\$500.00	\$1,000.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$2,000.00			

Data Analysis for Lead

The following data points were entered by the user for analysis.

	Lead (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	2.021	2.15	2.45	2.6	3.4	3.6	3.7	4.4	4.6	4.8
10	5.1	5.4	6	6.1	6.7	6.9	6.9	7	7.2	8
20	8.3	8.9	9.2	9.8	9.9	10.4	11.6	12.7	14.75	16.1
30	17.1	17.7	18.8	18.9	19.75	20.9	22.45	23.8	55.8	80.6
40	80.7									

SUMMARY ST	SUMMARY STATISTICS for Lead				
n	41				
Min	2.021				
Max	80.7				
Range	78.679				
Mean	14.321				
Median	8.3				
Variance	319.78				
StdDev	17.882				
Std Error	2.7928				
Skewness	2.9321				

Inte	nge	12.45						
		Per	centil	les				
1%	5%	10%	25%	50%	75%	90%	95%	99%
2.021	2.18	2.76	4.95	8.3	17.4	23.53	78.12	80.7

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Lead					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	3.712	3.05	Yes		

The test statistic 3.712 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OU	TLIERS for Lead
1	80.7

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.6201				
Shapiro-Wilk 5% Critical Value	0.94				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Lead


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Lead

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.5986			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN							
95% Parametric UCL	19.02						
95% Non-Parametric (Chebyshev) UCL	26.49						

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (26.49) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SR}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (400),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic	Critical Value t _{0.95}	Null Hypothesis					
-138.1	1.6839	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+)	95% Critical Value	Null Hypothesis					
41	26	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN								
Primary Objective of Design	Compare a site mean to a fixed threshold							
Type of Sampling Design	Parametric							
Sample Placement (Location) in the Field	Simple random sampling							
Working (Null) Hypothesis	The mean value at the site exceeds the threshold							
Formula for calculating number of sampling locations	Student's t-test							
Calculated total number of samples	2							
Number of samples on map ^a	41							
Number of selected sample areas b	2							
Specified sampling area ^c	188054.34 m ²							
Total cost of sampling d	\$2,000.00							

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1										
X Coord	Y Coord	Label	Value	Туре	Historical						
679268.7700	3083200.3260	J-11S	22.3	Manual	Т						
679301.1600	3083254.0340	J-12S	5.1	Manual	Т						
679171.2970	3083289.7960	J-04S	1.3	Manual	Т						
679155.0740	3083294.6960	J-03S	1.15	Manual	Т						
679133.4290	3083306.3130	J-01S	4.7	Manual	Т						
679104.2450	3083223.2620	J-02S	1.1	Manual	Т						
679164.8060	3083214.7100	J-06S	0.985	Manual	Т						
679181.2750	3083178.2880	J-08S	6.1	Manual	Т						
679213.7730	3083224.9730	J-09S	7.7	Manual	Т						
679280.5440	3083305.6810	J-10S	2.4	Manual	Т						
679242.7260	3083326.5280	J-07S	5.1	Manual	Т						
679225.8560	3083359.9740	J-05S	1.7	Manual	Т						

Area: Area 3										
X Coord	Y Coord	Label	Value	Туре	Historical					
679261.0980	3083016.3510	J-15S	2.1	Manual	Т					
679335.0020	3082941.1720	J-21S	4.9	Manual	Т					
679343.5810	3082969.5980	J-19S	5.25	Manual	Т					
679394.8070	3082971.8300	J-24S	2.3	Manual	Т					
679382.8640	3083009.1130	J-20S	5.8	Manual	Т					
679293.5600	3082950.4980	J-17S	10.6	Manual	Т					
679360.5700	3083026.4980	J-18S	4.1	Manual	Т					

3082840.6970	J-23S	9.6	Manual T
3082781.0290	J-22S	6.85	Manual T
3082840.1720	J-16S	4.5	Manual T
3083075.4290	J-14S	4.1	Manual T
3082933.0980	J-13S	2.4	Manual T
3082652.6750	J-28S	6.6	Manual T
3082683.1400	J-26S	2.925	Manual T
3082549.7640	J-25S	1.6	Manual T
3082537.3510	J-27S	3.5	Manual T
3082605.3190	J-35S	9.1	Manual T
3082548.6880	J-34S	29.3	Manual T
3082667.5270	J-36S	10.5	Manual T
3082711.0960	J-29S	12.8	Manual T
3082791.3300	J-30S	16.6	Manual T
3082914.1150	J-32S	16.2	Manual T
3082845.8460	J-31S	17.25	Manual T
3082897.2580	J-41S	7	Manual T
3082940.9730	J-33S	4.8	Manual T
3082886.8990	J-40S	15.8	Manual T
3082840.3960	J-39S	7.8	Manual T
3082776.7350	J-38S	16	Manual T
3082731.6820	J-37S	13.2	Manual T
	3082781.0290 3082840.1720 3083075.4290 3082933.0980 3082652.6750 3082652.6750 3082549.7640 3082537.3510 3082605.3190 3082548.6880 3082667.5270 3082711.0960 3082791.3300 3082914.1150 3082845.8460 3082897.2580 3082940.9730 3082840.3960 3082776.7350	3082781.0290 J-22S 3082840.1720 J-16S 3083075.4290 J-14S 3082933.0980 J-13S 3082652.6750 J-28S 3082652.6750 J-26S 3082549.7640 J-25S 3082537.3510 J-27S 3082605.3190 J-35S 3082548.6880 J-34S 3082667.5270 J-36S 3082711.0960 J-29S 3082791.3300 J-30S 3082914.1150 J-32S 3082845.8460 J-31S 3082845.8460 J-31S 3082840.9730 J-33S 3082840.9730 J-33S 3082840.3960 J-39S 3082776.7350 J-38S	3082781.0290 J-22S 6.85 3082840.1720 J-16S 4.5 3083075.4290 J-14S 4.1 3082933.0980 J-13S 2.4 3082652.6750 J-28S 6.6 3082683.1400 J-26S 2.925 3082549.7640 J-25S 1.6 3082537.3510 J-27S 3.5 3082605.3190 J-37S 9.1 3082548.6880 J-34S 29.3 3082667.5270 J-36S 10.5 3082711.0960 J-29S 12.8 3082791.3300 J-30S 16.6 3082914.1150 J-32S 16.2 3082845.8460 J-31S 17.25 3082845.8460 J-31S 17.25 3082940.9730 J-33S 4.8 3082840.3960 J-39S 7.8 3082776.7350 J-38S 16

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

	Amolysta	_		Parar	neter			
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b	
	Vanadium	2	6.38 mg/kg	145.507 mg/kg	0.05	0.1	1.64485	1.28155


 $^{^{\}rm a}$ This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples									
AL=291.014		α=	:5	α=	10	α=15			
		s=12.76	12.76 s=6.38 s=12.76 s=6.38		s=12.76	s=6.38			
	β=5	4	2	3	2	2	1		
LBGR=90	β=10	3	2	3	2	2	1		
	β=15	3	2	2	2	2	1		
	β=5	2	2	2	1	1	1		
LBGR=80	β=10	2	2	2	1	1	1		
	β=15	2	2	2	1	1	1		
LBGR=70	β=5	2	2	2	1	1	1		

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	2 Samples						
Field collection costs		\$100.00	\$200.00						
Analytical costs	\$400.00	\$400.00	\$800.00						
Sum of Field & Analytical costs		\$500.00	\$1,000.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$2,000.00						

Data Analysis for Vanadium

The following data points were entered by the user for analysis.

	Vanadium (mg/kg)										
Rank 1 2 3 4 5 6 7 8 9									10		
0	0.985	1.1	1.15	1.3	1.6	1.7	2.1	2.3	2.4	2.4	
10	2.925	3.5	4.1	4.1	4.5	4.7	4.8	4.9	5.1	5.1	
20	5.25	5.8	6.1	6.6	6.85	7	7.7	7.8	9.1	9.6	
30	10.5	10.6	12.8	13.2	15.8	16	16.2	16.6	17.25	22.3	
40	29.3										

SUMMARY STATISTICS for Vanadium			
n	41		
Min	0.985		
Max	29.3		
Range	28.315		
Mean	7.6368		
Median	5.25		
Variance	40.68		
StdDev	6.3781		
Std Error	0.99609		
Skewness	1.4681		

Interquartile Range			7.8875					
Percentiles								
1%	5%	10%	25%	50% 75% 90% 95% 99%				99%
0.985	1.105	1.36	2.662	5.25	10.55	16.52	21.79	29.3

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Vanadium					
k Test Statistic R _k 5% Critical Value C _k Significant?					
1	3.397	3.05	Yes		

The test statistic 3.397 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS for Vanadium			
1	29.3		

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Shapiro-Wilk Test Statistic	0.8816			
Shapiro-Wilk 5% Critical Value	0.94			

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Vanadium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Vanadium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST			
Shapiro-Wilk Test Statistic 0.8546			
Shapiro-Wilk 5% Critical Value	0.941		

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	9.314
95% Non-Parametric (Chebyshev) UCL	11.98

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (11.98) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (291.014),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-284.49	1.6839	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+) 95% Critical Value Null Hypothesis				
41	26	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN				
Primary Objective of Design	Compare a site mean to a fixed threshold				
Type of Sampling Design	Parametric				
Sample Placement (Location) in the Field	Simple random sampling				
Working (Null) Hypothesis	The mean value at the site exceeds the threshold				
Formula for calculating number of sampling locations	Student's t-test				
Calculated total number of samples	2				
Number of samples on map ^a	41				
Number of selected sample areas b	2				
Specified sampling area ^c	188054.34 m ²				
Total cost of sampling d	\$2,000.00				

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679268.7700	3083200.3260	J-11S	22.3	Manual	Т	
679301.1600	3083254.0340	J-12S	5.1	Manual	Т	
679171.2970	3083289.7960	J-04S	1.3	Manual	Т	
679155.0740	3083294.6960	J-03S	1.15	Manual	Т	
679133.4290	3083306.3130	J-01S	4.7	Manual	Т	
679104.2450	3083223.2620	J-02S	1.1	Manual	Т	
679164.8060	3083214.7100	J-06S	0.985	Manual	Т	
679181.2750	3083178.2880	J-08S	6.1	Manual	Т	
679213.7730	3083224.9730	J-09S	7.7	Manual	Т	
679280.5440	3083305.6810	J-10S	2.4	Manual	Т	
679242.7260	3083326.5280	J-07S	5.1	Manual	Т	
679225.8560	3083359.9740	J-05S	1.7	Manual	Т	

Area: Area 3						
X Coord	Y Coord	Label	Value	Туре	Historical	
679261.0980	3083016.3510	J-15S	2.1	Manual	Т	
679335.0020	3082941.1720	J-21S	4.9	Manual	Т	
679343.5810	3082969.5980	J-19S	5.25	Manual	Т	
679394.8070	3082971.8300	J-24S	2.3	Manual	Т	
679382.8640	3083009.1130	J-20S	5.8	Manual	Т	
679293.5600	3082950.4980	J-17S	10.6	Manual	Т	
679360.5700	3083026.4980	J-18S	4.1	Manual	Т	

679297.0010 3082840.6970 J-23S 9.6 Manual T 679252.7130 3082781.0290 J-22S 6.85 Manual T 679222.6340 3082840.1720 J-16S 4.5 Manual T 679279.6830 3083075.4290 J-14S 4.1 Manual T 679149.4920 3082933.0980 J-13S 2.4 Manual T 679272.0040 3082652.6750 J-28S 6.6 Manual T 679224.5850 3082683.1400 J-26S 2.925 Manual T 679146.6460 3082549.7640 J-25S 1.6 Manual T 679169.0760 3082537.3510 J-27S 3.5 Manual T 679342.7410 3082605.3190 J-35S 9.1 Manual T 679382.8900 3082548.6880 J-34S 29.3 Manual T 679374.4420 3082791.3300 J-30S 16.6 Manual T 679453.4760 3082845.8460 J-31S 17.25 Manual T 679495.8840					
679222.6340 3082840.1720 J-16S 4.5 Manual T 679279.6830 3083075.4290 J-14S 4.1 Manual T 679149.4920 3082933.0980 J-13S 2.4 Manual T 679272.0040 3082652.6750 J-28S 6.6 Manual T 679224.5850 3082683.1400 J-26S 2.925 Manual T 679146.6460 3082549.7640 J-25S 1.6 Manual T 679169.0760 3082537.3510 J-27S 3.5 Manual T 679342.7410 3082605.3190 J-35S 9.1 Manual T 679382.8900 3082667.5270 J-36S 10.5 Manual T 679329.4380 3082711.0960 J-29S 12.8 Manual T 679374.4420 3082791.3300 J-30S 16.6 Manual T 679453.4760 3082845.8460 J-31S 17.25 Manual T 679450.6070 3082897.2580 J-41S 7 Manual T 679560.6070 3082897.2580 J-41S 7 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679497.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082886.8990 J-40S 15.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679297.0010	3082840.6970	J-23S	9.6	Manual T
679279.6830 3083075.4290 J-14S	679252.7130	3082781.0290	J-22S	6.85	Manual T
679149.4920 3082933.0980 J-13S 2.4 Manual T 679272.0040 3082652.6750 J-28S 6.6 Manual T 679245.5850 3082683.1400 J-26S 2.925 Manual T 679146.6460 3082549.7640 J-25S 1.6 Manual T 679169.0760 3082537.3510 J-27S 3.5 Manual T 679342.7410 3082605.3190 J-35S 9.1 Manual T 679304.6530 3082548.6880 J-34S 29.3 Manual T 679382.8900 3082667.5270 J-36S 10.5 Manual T 679374.4420 3082791.3300 J-30S 16.6 Manual T 679453.4760 3082845.8460 J-31S 17.25 Manual T 679460.670 3082897.2580 J-41S 7 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679222.6340	3082840.1720	J-16S	4.5	Manual T
679272.0040 3082652.6750 J-28S 6.6 Manual T 679224.5850 3082683.1400 J-26S 2.925 Manual T 679146.6460 3082549.7640 J-25S 1.6 Manual T 679169.0760 3082537.3510 J-27S 3.5 Manual T 679342.7410 3082605.3190 J-35S 9.1 Manual T 679304.6530 3082548.6880 J-34S 29.3 Manual T 679382.8900 3082667.5270 J-36S 10.5 Manual T 679329.4380 3082711.0960 J-29S 12.8 Manual T 679374.4420 3082791.3300 J-30S 16.6 Manual T 679453.4760 3082914.1150 J-32S 16.2 Manual T 679410.1490 3082845.8460 J-31S 17.25 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082886.8990 J-40S 15.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679279.6830	3083075.4290	J-14S	4.1	Manual T
679224.5850 3082683.1400 J-26S 2.925 Manual T 679146.6460 3082549.7640 J-25S 1.6 Manual T 679169.0760 3082537.3510 J-27S 3.5 Manual T 679342.7410 3082605.3190 J-35S 9.1 Manual T 679304.6530 3082548.6880 J-34S 29.3 Manual T 679382.8900 3082667.5270 J-36S 10.5 Manual T 679329.4380 3082711.0960 J-29S 12.8 Manual T 679374.4420 3082791.3300 J-30S 16.6 Manual T 679453.4760 3082914.1150 J-32S 16.2 Manual T 679410.1490 3082845.8460 J-31S 17.25 Manual T 679560.6070 3082897.2580 J-41S 7 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082886.8990 J-40S 15.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679149.4920	3082933.0980	J-13S	2.4	Manual T
679146.6460 3082549.7640 J-25S 1.6 Manual T 679342.7410 3082605.3190 J-35S 9.1 Manual T 679382.8900 3082548.6880 J-34S 29.3 Manual T 679329.4380 3082711.0960 J-29S 12.8 Manual T 679453.4760 3082914.1150 J-32S 16.2 Manual T 679495.8840 3082940.9730 J-30S 15.8 Manual T 679524.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679272.0040	3082652.6750	J-28S	6.6	Manual T
679169.0760 3082537.3510 J-27S 3.5 Manual T 679342.7410 3082605.3190 J-35S 9.1 Manual T 679304.6530 3082548.6880 J-34S 29.3 Manual T 679382.8900 3082667.5270 J-36S 10.5 Manual T 679329.4380 3082711.0960 J-29S 12.8 Manual T 679374.4420 3082791.3300 J-30S 16.6 Manual T 679453.4760 3082914.1150 J-32S 16.2 Manual T 679410.1490 3082845.8460 J-31S 17.25 Manual T 679560.6070 3082897.2580 J-41S 7 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679224.5850	3082683.1400	J-26S	2.925	Manual T
679342.7410 3082605.3190 J-35S 9.1 Manual T 679304.6530 3082548.6880 J-34S 29.3 Manual T 679382.8900 3082667.5270 J-36S 10.5 Manual T 679374.4420 3082791.3300 J-30S 16.6 Manual T 679453.4760 3082914.1150 J-32S 16.2 Manual T 679410.1490 3082845.8460 J-31S 17.25 Manual T 679560.6070 3082897.2580 J-41S 7 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679146.6460	3082549.7640	J-25S	1.6	Manual T
679304.6530 3082548.6880 J-34S 29.3 Manual T 679382.8900 3082667.5270 J-36S 10.5 Manual T 679329.4380 3082711.0960 J-29S 12.8 Manual T 679374.4420 3082791.3300 J-30S 16.6 Manual T 679453.4760 3082914.1150 J-32S 16.2 Manual T 679410.1490 3082845.8460 J-31S 17.25 Manual T 679560.6070 3082897.2580 J-41S 7 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679169.0760	3082537.3510	J-27S	3.5	Manual T
679382.8900 3082667.5270 J-36S 10.5 Manual T 679329.4380 3082711.0960 J-29S 12.8 Manual T 679374.4420 3082791.3300 J-30S 16.6 Manual T 679453.4760 3082914.1150 J-32S 16.2 Manual T 679410.1490 3082845.8460 J-31S 17.25 Manual T 679560.6070 3082897.2580 J-41S 7 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679342.7410	3082605.3190	J-35S	9.1	Manual T
679329.4380 3082711.0960 J-29S 12.8 Manual T 679453.4760 3082914.1150 J-32S 16.2 Manual T 679410.1490 3082845.8460 J-31S 17.25 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082846.8990 J-40S 15.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679304.6530	3082548.6880	J-34S	29.3	Manual T
679374.4420 3082791.3300 J-30S 16.6 Manual T 679453.4760 3082914.1150 J-32S 16.2 Manual T 679410.1490 3082845.8460 J-31S 17.25 Manual T 679560.6070 3082897.2580 J-41S 7 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679382.8900	3082667.5270	J-36S	10.5	Manual T
679453.4760 3082914.1150 J-32S 16.2 Manual T 679410.1490 3082845.8460 J-31S 17.25 Manual T 679560.6070 3082897.2580 J-41S 7 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679329.4380	3082711.0960	J-29S	12.8	Manual T
679410.1490 3082845.8460 J-31S 17.25 Manual T 679560.6070 3082897.2580 J-41S 7 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679374.4420	3082791.3300	J-30S	16.6	Manual T
679560.6070 3082897.2580 J-41S 7 Manual T 679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679453.4760	3082914.1150	J-32S	16.2	Manual T
679495.8840 3082940.9730 J-33S 4.8 Manual T 679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679410.1490	3082845.8460	J-31S	17.25	Manual T
679524.3310 3082886.8990 J-40S 15.8 Manual T 679497.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679560.6070	3082897.2580	J-41S	7	Manual T
679497.3310 3082840.3960 J-39S 7.8 Manual T 679470.3570 3082776.7350 J-38S 16 Manual T	679495.8840	3082940.9730	J-33S	4.8	Manual T
679470.3570 3082776.7350 J-38S 16 Manual T	679524.3310	3082886.8990	J-40S	15.8	Manual T
	679497.3310	3082840.3960	J-39S	7.8	Manual T
679433.9450 3082731.6820 J-37S 13.2 Manual T	679470.3570	3082776.7350	J-38S	16	Manual T
	679433.9450	3082731.6820	J-37S	13.2	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyta	_	Parameter					
Analyte	11	S	Δ	α	β	$Z_{1-\alpha}$ a	Z_{1-β} b
Vanadium	2	6.38 mg/kg	283.38 mg/kg	0.05	0.1	1.64485	1.28155


 $^{\rm a}$ This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

	Number of Samples						
AL 201	014	α=	:5	α=	10	α=	15
AL=291	.014	s=12.76	s=6.38	s=12.76	s=6.38	s=12.76	s=6.38
	β=5	4	2	3	2	2	1
LBGR=90	β=10	3	2	3	2	2	1
	β=15	3	2	2	2	2	1
	β=5	2	2	2	1	1	1
LBGR=80	β=10	2	2	2	1	1	1
	β=15	2	2	2	1	1	1
LBGR=70	β=5	2	2	2	1	1	1

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION							
Cost Details	Per Analysis	Per Sample	2 Samples				
Field collection costs		\$100.00	\$200.00				
Analytical costs	\$400.00	\$400.00	\$800.00				
Sum of Field & Analytical costs		\$500.00	\$1,000.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$2,000.00				

Data Analysis for Vanadium

The following data points were entered by the user for analysis.

	Vanadium (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	0.985	1.1	1.15	1.3	1.6	1.7	2.1	2.3	2.4	2.4
10	2.925	3.5	4.1	4.1	4.5	4.7	4.8	4.9	5.1	5.1
20	5.25	5.8	6.1	6.6	6.85	7	7.7	7.8	9.1	9.6
30	10.5	10.6	12.8	13.2	15.8	16	16.2	16.6	17.25	22.3
40	29.3									

SUMMARY STATISTICS for Vanadium				
n	41			
Min	0.985			
Max	29.3			
Range	28.315			
Mean	7.6368			
Median	5.25			
Variance	40.68			
StdDev	6.3781			
Std Error	0.99609			
Skewness	1.4681			

Interquartile Range				7.8875				
Per				centi	les			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.985	1.105	1.36	2.662	5.25	10.55	16.52	21.79	29.3

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Vanadium					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	3.397	3.05	Yes		

The test statistic 3.397 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS for Vanadium			
1	29.3		

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.8816				
Shapiro-Wilk 5% Critical Value	0.94				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Vanadium


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests for Vanadium

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic	0.8546				
Shapiro-Wilk 5% Critical Value	0.941				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN							
95% Parametric UCL	9.314						
95% Non-Parametric (Chebyshev) UCL	11.98						

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (11.98) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (291.014),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic	Critical Value t _{0.95}	Null Hypothesis					
-284.49	1.6839	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+)	95% Critical Value	Null Hypothesis					
41	26	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN								
Primary Objective of Design	Compare a site mean to a fixed threshold							
Type of Sampling Design	Parametric							
Sample Placement (Location) in the Field	Simple random sampling							
Working (Null) Hypothesis	The mean value at the site exceeds the threshold							
Formula for calculating number of sampling locations	Student's t-test							
Calculated total number of samples	2							
Number of samples on map ^a	41							
Number of selected sample areas b	2							
Specified sampling area ^c	188054.34 m ²							
Total cost of sampling d	\$2,000.00							

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1										
X Coord	Y Coord	Label	Value	Туре	Historical					
679268.7700	3083200.3260	J-11S	25.2	Manual	Т					
679301.1600	3083254.0340	J-12S	6.1	Manual	Т					
679171.2970	3083289.7960	J-04S	8.7	Manual	Т					
679155.0740	3083294.6960	J-03S	11.8	Manual	Т					
679133.4290	3083306.3130	J-01S	40.7	Manual	Т					
679104.2450	3083223.2620	J-02S	23.6	Manual	Т					
679164.8060	3083214.7100	J-06S	3.1	Manual	Т					
679181.2750	3083178.2880	J-08S	80.3	Manual	Т					
679213.7730	3083224.9730	J-09S	16.6	Manual	Т					
679280.5440	3083305.6810	J-10S	22.8	Manual	Т					
679242.7260	3083326.5280	J-07S	232	Manual	Т					
679225.8560	3083359.9740	J-05S	10.4	Manual	Т					

Area: Area 3									
X Coord	Y Coord	Label	Value	Туре	Historical				
679261.0980	3083016.3510	J-15S	31.1	Manual	Т				
679335.0020	3082941.1720	J-21S	39.5	Manual	Т				
679343.5810	3082969.5980	J-19S	26.15	Manual	Т				
679394.8070	3082971.8300	J-24S	22.2	Manual	Т				
679382.8640	3083009.1130	J-20S	30.2	Manual	Т				
679293.5600	3082950.4980	J-17S	143	Manual	Т				
679360.5700	3083026.4980	J-18S	35	Manual	Т				

679297.0010 3082840.6970 J-23S 44.1 Manual T 679252.7130 3082781.0290 J-22S 40.65 Manual T 679222.6340 3082840.1720 J-16S 129 Manual T 679279.6830 3083075.4290 J-14S 92.6 Manual T 679149.4920 3082933.0980 J-13S 17.2 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679224.5850 3082683.1400 J-26S 24.33 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 6794753.4760 3082914.1150 J-32S 59 Manual T 679460.6070					
679222.6340 3082840.1720 J-16S 129 Manual T 679279.6830 3083075.4290 J-14S 92.6 Manual T 679149.4920 3082933.0980 J-13S 17.2 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082845.8460 J-31S 26.05 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082886.8990 J-39S 29.8 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679297.0010	3082840.6970	J-23S	44.1	Manual T
679279.6830 3083075.4290 J-14S 92.6 Manual T 679149.4920 3082933.0980 J-13S 17.2 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679374.4420 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082845.8460 J-31S 26.05 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679495.8840 3082840.3960 J-39S 25.9 Manual T 679497.3310 3082886.8990 J-40S 31.8 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679252.7130	3082781.0290	J-22S	40.65	Manual T
679149.4920 3082933.0980 J-13S 17.2 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679146.6460 3082549.7640 J-26S 24.33 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082845.8460 J-31S 26.05 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679222.6340	3082840.1720	J-16S	129	Manual T
679272.0040 3082652.6750 J-28S 48 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082548.6880 J-34S 156 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082845.8460 J-31S 26.05 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679470.3570 3082876.7350 J-38S 29.8 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679279.6830	3083075.4290	J-14S	92.6	Manual T
679224.5850 3082683.1400 J-26S 24.33 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082845.8460 J-31S 26.05 Manual T 679460.6070 3082897.2580 J-41S 85.3 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679149.4920	3082933.0980	J-13S	17.2	Manual T
679146.6460 3082549.7640 J-25S 59 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082548.6880 J-34S 156 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082845.8460 J-31S 26.05 Manual T 679495.8840 3082940.9730 J-30S 79 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679272.0040	3082652.6750	J-28S	48	Manual T
679169.0760 3082537.3510 J-27S 29.4 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 6795260.6070 3082897.2580 J-41S 85.3 Manual T 679524.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679224.5850	3082683.1400	J-26S	24.33	Manual T
679342.7410 3082605.3190 J-35S 20.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679460.6070 3082845.8460 J-31S 26.05 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679146.6460	3082549.7640	J-25S	59	Manual T
679304.6530 3082548.6880 J-34S 156 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679169.0760	3082537.3510	J-27S	29.4	Manual T
679382.8900 3082667.5270 J-36S 40.2 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679342.7410	3082605.3190	J-35S	20.1	Manual T
679329.4380 3082711.0960 J-29S 19.7 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679304.6530	3082548.6880	J-34S	156	Manual T
679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679382.8900	3082667.5270	J-36S	40.2	Manual T
679453.4760 3082914.1150 J-32S 59 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679329.4380	3082711.0960	J-29S	19.7	Manual T
679410.1490 3082845.8460 J-31S 26.05 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679374.4420	3082791.3300	J-30S	79	Manual T
679560.6070 3082897.2580 J-41S 85.3 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679453.4760	3082914.1150	J-32S	59	Manual T
679495.8840 3082940.9730 J-33S 11.1 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679410.1490	3082845.8460	J-31S	26.05	Manual T
679524.3310 3082886.8990 J-40S 31.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679560.6070	3082897.2580	J-41S	85.3	Manual T
679497.3310 3082840.3960 J-39S 25.9 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T	679495.8840	3082940.9730	J-33S	11.1	Manual T
679470.3570 3082776.7350 J-38S 29.8 Manual T	679524.3310	3082886.8990	J-40S	31.8	Manual T
	679497.3310	3082840.3960	J-39S	25.9	Manual T
679433.9450 3082731.6820 J-37S 48.5 Manual T	679470.3570	3082776.7350	J-38S	29.8	Manual T
	679433.9450	3082731.6820	J-37S	48.5	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

S

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_		Paran	neter			
Analyte	n	S	Δ	α	β	Ζ _{1-α} ^a	Z _{1-β} b
Zinc	2	46.95 mg/kg	4960.74 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples									
AL=9921.47		α	;= 5	α=	=10	α:	α=15		
		s=93.9	s=46.95	s=93.9	s=46.95	s=93.9	s=46.95		
	β=5	2	2	1	1	1	1		
LBGR=90	β=10	2	2	1	1	1	1		
	β=15	2	2	1	1	1	1		
	β=5	2	2	1	1	1	1		
LBGR=80	β=10	2	2	1	1	1	1		
	β=15	2	2	1	1	1	1		
LBGR=70	β=5	2	2	1	1	1	1		

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	2 Samples						
Field collection costs		\$100.00	\$200.00						
Analytical costs	\$400.00	\$400.00	\$800.00						
Sum of Field & Analytical costs		\$500.00	\$1,000.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$2,000.00						

Data Analysis for Zinc

The following data points were entered by the user for analysis.

	Zinc (mg/kg)										
Rank	1	2	3	4	5	6	7	8	9	10	
0	3.1	6.1	8.7	10.4	11.1	11.8	16.6	17.2	19.7	20.1	
10	22.2	22.8	23.6	24.33	25.2	25.9	26.05	26.15	29.4	29.8	
20	30.2	31.1	31.8	35	39.5	40.2	40.65	40.7	44.1	48	
30	48.5	59	59	79	80.3	85.3	92.6	129	143	156	
40	232										

SUMMARY STATISTICS for Zinc			
n	41		
Min	3.1		
Max	232		
Range	228.9		
Mean	46.956		
Median	30.2		
Variance	2149.9		
StdDev	46.367		
Std Error	7.2413		
Skewness	2.3039		

Interquartile Range			32.6					
Pe			rcenti	les				
1%	5%	10%	25%	50% 75% 90% 95% 99%				99%
3.1	6.36	10.54	21.15	30.2	53.75	121.7	154.7	232

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Zinc					
k Test Statistic R _k 5% Critical Value C _k Significant?					
1	3.991	3.05	Yes		

The test statistic 3.991 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OL	JTLIERS for Zinc
1	232

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Shapiro-Wilk Test Statistic	0.7959			
Shapiro-Wilk 5% Critical Value	0.94			

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Zinc


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Zinc

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic 0.7426				
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	59.15
95% Non-Parametric (Chebyshev) UCI	78.52

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (78.52) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (9921.47).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-1363.6	1.6839	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+) 95% Critical Value Null Hypothesis				
41	26	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN				
Primary Objective of Design	Compare a site mean to a fixed threshold			
Type of Sampling Design	Parametric			
Sample Placement (Location) in the Field	Simple random sampling			
Working (Null) Hypothesis	The mean value at the site exceeds the threshold			
Formula for calculating number of sampling locations	Student's t-test			
Calculated total number of samples	2			
Number of samples on map ^a	41			
Number of selected sample areas b	2			
Specified sampling area ^c	188054.34 m ²			
Total cost of sampling d	\$2,000.00			

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679268.7700	3083200.3260	J-11S	25.2	Manual	Т	
679301.1600	3083254.0340	J-12S	6.1	Manual	Т	
679171.2970	3083289.7960	J-04S	8.7	Manual	Т	
679155.0740	3083294.6960	J-03S	11.8	Manual	Т	
679133.4290	3083306.3130	J-01S	40.7	Manual	Т	
679104.2450	3083223.2620	J-02S	23.6	Manual	Т	
679164.8060	3083214.7100	J-06S	3.1	Manual	Т	
679181.2750	3083178.2880	J-08S	80.3	Manual	Т	
679213.7730	3083224.9730	J-09S	16.6	Manual	Т	
679280.5440	3083305.6810	J-10S	22.8	Manual	Т	
679242.7260	3083326.5280	J-07S	232	Manual	Т	
679225.8560	3083359.9740	J-05S	10.4	Manual	Т	

Area: Area 3						
X Coord	Y Coord	Label	Value	Туре	Historical	
679261.0980	3083016.3510	J-15S	31.1	Manual	Т	
679335.0020	3082941.1720	J-21S	39.5	Manual	Т	
679343.5810	3082969.5980	J-19S	26.15	Manual	Т	
679394.8070	3082971.8300	J-24S	22.2	Manual	Т	
679382.8640	3083009.1130	J-20S	30.2	Manual	Т	
679293.5600	3082950.4980	J-17S	143	Manual	Т	
679360.5700	3083026.4980	J-18S	35	Manual	Т	

3082840.6970	J-23S	44.1	Manual T
3082781.0290	J-22S	40.65	Manual T
3082840.1720	J-16S	129	Manual T
3083075.4290	J-14S	92.6	Manual T
3082933.0980	J-13S	17.2	Manual T
3082652.6750	J-28S	48	Manual T
3082683.1400	J-26S	24.33	Manual T
3082549.7640	J-25S	59	Manual T
3082537.3510	J-27S	29.4	Manual T
3082605.3190	J-35S	20.1	Manual T
3082548.6880	J-34S	156	Manual T
3082667.5270	J-36S	40.2	Manual T
3082711.0960	J-29S	19.7	Manual T
3082791.3300	J-30S	79	Manual T
3082914.1150	J-32S	59	Manual T
3082845.8460	J-31S	26.05	Manual T
3082897.2580	J-41S	85.3	Manual T
3082940.9730	J-33S	11.1	Manual T
3082886.8990	J-40S	31.8	Manual T
3082840.3960	J-39S	25.9	Manual T
3082776.7350	J-38S	29.8	Manual T
3082731.6820	J-37S	48.5	Manual T
	3082781.0290 3082840.1720 3083075.4290 3082933.0980 3082652.6750 3082652.6750 3082549.7640 3082537.3510 3082548.6880 3082548.6880 3082667.5270 3082711.0960 3082791.3300 3082914.1150 3082845.8460 3082897.2580 3082940.9730 3082846.8990 3082840.3960 3082776.7350	3082781.0290 J-22S 3082840.1720 J-16S 3083075.4290 J-14S 3082933.0980 J-13S 3082652.6750 J-28S 3082652.6750 J-26S 3082549.7640 J-25S 3082537.3510 J-27S 3082605.3190 J-35S 3082548.6880 J-34S 3082667.5270 J-36S 3082711.0960 J-29S 3082791.3300 J-30S 3082914.1150 J-32S 3082845.8460 J-31S 3082845.8460 J-31S 3082840.9730 J-33S 3082840.9730 J-33S 3082840.3960 J-39S 3082776.7350 J-38S	3082781.0290 J-22S 40.65 3082840.1720 J-16S 129 3083075.4290 J-14S 92.6 3082933.0980 J-13S 17.2 3082652.6750 J-28S 48 3082683.1400 J-26S 24.33 3082549.7640 J-25S 59 3082537.3510 J-27S 29.4 3082605.3190 J-35S 20.1 3082548.6880 J-34S 156 3082667.5270 J-36S 40.2 3082711.0960 J-29S 19.7 3082791.3300 J-30S 79 3082914.1150 J-32S 59 3082845.8460 J-31S 26.05 3082849.9730 J-33S 11.1 3082840.3960 J-39S 25.9 3082776.7350 J-38S 29.8

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value of a site with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

S

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$,

 $Z_{1-\beta}^{1-\alpha}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}^{1-\alpha}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analyta	_	Parameter					
Analyte	n	S	Δ	α	β	Ζ _{1-α} ^a	Z _{1-β} b
Zinc	2	46.95 mg/kg	9872.91 mg/kg	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric or the sample size is more than 30; for extremely skewed data sets, additional samples may be required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level. The following table shows the results of this analysis.

Number of Samples								
AL 0004 47		α=5		α	=10	α=15		
AL=992	1.47	s=93.9	s=46.95	s=93.9	s=46.95	s=93.9	s=46.95	
	β=5	2	2	1	1	1	1	
LBGR=90	β=10	2	2	1	1	1	1	
	β=15	2	2	1	1	1	1	
	β=5	2	2	1	1	1	1	
LBGR=80	β=10	2	2	1	1	1	1	
	β=15	2	2	1	1	1	1	
LBGR=70	β=5	2	2	1	1	1	1	

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	2 Samples			
Field collection costs		\$100.00	\$200.00			
Analytical costs	\$400.00	\$400.00	\$800.00			
Sum of Field & Analytical costs		\$500.00	\$1,000.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$2,000.00			

Data Analysis for Zinc

The following data points were entered by the user for analysis.

	Zinc (mg/kg)									
Rank	1	2	3	4	5	6	7	8	9	10
0	3.1	6.1	8.7	10.4	11.1	11.8	16.6	17.2	19.7	20.1
10	22.2	22.8	23.6	24.33	25.2	25.9	26.05	26.15	29.4	29.8
20	30.2	31.1	31.8	35	39.5	40.2	40.65	40.7	44.1	48
30	48.5	59	59	79	80.3	85.3	92.6	129	143	156
40	232									

SUMMARY STATISTICS for Zinc				
n	41			
Min	3.1			
Max	232			
Range	228.9			
Mean	46.956			
Median	30.2			
Variance	2149.9			
StdDev	46.367			
Std Error	7.2413			
Skewness	2.3039			

Int	erquar	tile Ra	nge	32.6				
			Pei	rcenti	les			
1%	5%	10%	25%	50%	75%	90%	95%	99%
3.1	6.36	10.54	21.15	30.2	53.75	121.7	154.7	232

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST for Zinc					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	3.991	3.05	Yes		

The test statistic 3.991 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OL	JTLIERS for Zinc
1	232

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.7959				
Shapiro-Wilk 5% Critical Value	0.94				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots for Zinc


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends

to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests for Zinc

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.7426			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN		
95% Parametric UCL	59.15	
95% Non-Parametric (Chebyshev) UCL	78.52	

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (78.52) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=41 data,

AL is the action level or threshold (9921.47).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=40 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST			
t-statistic	Critical Value t _{0.95}	Null Hypothesis	
-1363.6	1.6839	Reject	

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test			
Test Statistic (S+)	95% Critical Value	Null Hypothesis	
41	26	Reject	

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.3.1.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2009 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.